



**FIGURE 4.58 A pipelined sequence of instructions.** Since the dependence between the load and the following instruction (and) goes backward in time, this hazard cannot be solved by forwarding. Hence, this combination must result in a stall by the hazard detection unit.

Copyright © 2021 Elsevier Inc. All rights reserved