
Task Activation
Min Dist
Task transition
Task saturation
EE cart error norm
EE reaching trsh
0
0.2
0.4
0.6
0.8
1
0.5
0
20
40
60
80
100
120
Time, (sec)