


Taxi to gate after landing!

During your final approach you would ask for your gate or parking area, or ATC could give it to you automatically. In most airports there will be hi speed exits from the runway this is to allow you to vacate the runway quick as possible due to constant traffic both arriving & departing the Runway.

This speed could be advised by ATC or ground control otherwise it is generally 20 – 25knotts, If you are heavy or in wet weather this speed would be reduced to 15knotts or if sharp turns are involved 10 – 12knotts.

Steps for Taxi back to Stand or Parking area.

- 1. Once landed vacate the runway as quickly and safely as possible.
- 2. When you have departed the runway, you come up to **Stop bars**, stop before the double solid Yellow lines and request clearance to continue over the lines.
- 3. While waiting for clearance Turn off your LANDING LIGHTS, set nose wheel to TAXI, Runway turnoff lights ON, Beacon MUST remain ON retract your flaps to zero, if over 30 degrees leave flaps at 1, disarm the spoilers Strobe OFF.



Taxi speed back to the Parking bay/ Gate is generally 15 - 20 Knotts but again if wet runway light (leave on if nighttime) this is for the safety of the sight for the ground crew. Leave BEACON ON till both engines have spooled down.