

# **HIMax**<sup>®</sup>

# Release Notes



All of the HIMA products mentioned in this manual are trademark protected. Unless noted otherwise, this also applies to other manufacturers and their respective products referred to herein.

HIQuad®, HIQuad®X, HIMax®, HIMatrix®, SILworX®, XMR®, HICore® and FlexSILon® are registered trademarks of HIMA Paul Hildebrandt GmbH.

All of the technical specifications and information in this manual were prepared with great care and effective control measures were employed for their compilation. For questions, please contact HIMA directly. HIMA appreciates any suggestion on which information should be included in the manual.

Equipment subject to change without notice. HIMA also reserves the right to modify the written material without prior notice.

All the current manuals can be obtained upon request by sending an e-mail to: documentation@hima.com.

© Copyright 2020, HIMA Paul Hildebrandt GmbH All rights reserved.

#### Contact

HIMA Paul Hildebrandt GmbH P.O. Box 1261 68777 Brühl, Germany

Fax: +49 6202 709-107 E-mail: info@hima.com

Phone: +49 6202 709-0

Document designation	Description
HI 801 529 D, Rev. 1.02 (2012)	German original document
HI 801 530 E, Rev. 1.02.00 (2012)	English translation of the German original document

Release Notes Table of Contents

# **Table of Contents**

1	HIMax Operating System V12	5
1.1	New Functions	5
1.2	Firmware Improvements	5
1.3	Firmware Restrictions	6
1.4	References	7
1.5	Zstandard License Conditions	7
	Appendix	8
	Index of Tables	8

HI 801 530 E Rev. 1.02.00 Page 3 of 9

Table of Contents Release Notes

Page 4 of 9 HI 801 530 E Rev. 1.02.00

## 1 HIMax Operating System V12

This main chapter describes the improvements and new functions of the following operating system versions:

OS version	File name	Description
V12.2	HIMAXCPU_HA1_OS_V12.2.ldb	Safety-related operating system for X-CPU 01 processor modules
V12.2	HIMAXCPU31_HA1_OS_V12.2.ldb	Safety-related operating system for X-CPU 31 processor modules
V12.4	HIMAXCOM_HA2_OS_V12.4.ldb	Operating system for X-COM 01 communication modules

Table 1: Current Operating System Versions

#### 1.1 New Functions

#### PROFIsafe V2.6MU1:

The operating system supports Basic Protocol Mode (BP), Loop Back Protocol Mode (LP) (F-Host only) and Expanded Protocol Mode (XP) (GSDML file as of V2.32 / SILworX code generation V11b).

Separate licenses are required for the PROFIsafe Host V2.6MU1 (LP, XP) and PROFIsafe Device V2.6MU1 (XP) functions. Additionally, a connection license is required for each configured protocol connection.

The Basic Protocol Mode additionally supports HIMA F-Devices with 10 and 12 bytes.

Restriction: The Basic Protocol Mode with more than 12 bytes and 4-byte CRC is no longer supported.

Due to the tight schedule of a customer project, PROFIsafe could not yet be certified by a PI-accredited testing institute.

The gateway IP address can be configured via DCP set. When establishing a PROFINET connection and the IP address of the PROFINET Device does not match the configured IP address (DCP set), the gateway IP address of the PROFINET Device is set in accordance with the configured IP address.

#### 1.2 Firmware Improvements

Improved behavior of Reset PROFIsafe connection state (for Host).
The connection states of up to 32 PROFIsafe connections can now be reset simultaneously.

HI 801 530 E Rev. 1.02.00 Page 5 of 9

#### 1.3 Firmware Restrictions

- In very seldom cases, if one or more communication protocols such as Modbus or ComUserTask are used under load control and the controller or COM module changes from RUN to STOP, the COM module may reboot.
- Restriction concerning the reload licenses

If only a demo license is available to load a feature required by a module, it may occur that the feature is not updated properly when a reload with a regular license is performed. The message displayed in the license management of the CPU module indicates that a regular license is available, but a demo license is being used.

This behavior occurs when the module itself is not subject to reload or cold reload. The new license is only used and properly reported after a new restart, reload or cold reload of the module.

[Restriktion

HE29163 ]

Restriction concerning the reload of I/O modules with an operating system version ≤ V5 Reload of I/O modules with operating system version ≤ V5 must not be performed in conjunction with a protocol change, a change to the X-COM or the deletion of modules. Workaround:

If I/O modules with operating system version ≤ V5 are to be changed or added to the configuration by performing a reload, the reload must not include any additional changes.

Restriction concerning the event transmission priority
In redundant systems, only select the value 1 for the Events priority, or problems may occur during synchronization.

Page 6 of 9 HI 801 530 E Rev. 1.02.00

#### 1.4 References

- HIMax system manual (HI 801 001 E).
- HIMax safety manual (HI 801 003 E).
- Communication manual (HI 801 101 E).
- HIPRO-S V2 manual (HI 800 723 E).
- PROFIBUS manual (HI 801 523 E).

#### 1.5 Zstandard License Conditions

The CPU operating systems contain a Zstandard decompression algorithm provided with the following license conditions:

**BSD License** 

For Zstandard software

Copyright (c) 2016-present, Facebook, Inc. All rights reserved.

Redistribution and use in source and binary forms, with or without modification, are permitted provided that the following conditions are met:

- Redistributions of source code must retain the above copyright notice, this list of conditions and the following disclaimer.
- Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the following disclaimer in the documentation and/or other materials provided with the distribution.
- Neither the name Facebook nor the names of its contributors may be used to endorse or promote products derived from this software without specific prior written permission.

THIS SOFTWARE IS PROVIDED BY THE COPYRIGHT HOLDERS AND CONTRIBUTORS "AS IS" AND ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL THE COPYRIGHT HOLDER OR CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

HI 801 530 E Rev. 1.02.00 Page 7 of 9

Appendix Release Notes

# **Appendix**

## **Index of Tables**

**Table 1: Current Operating System Versions** 

5

Page 8 of 9 HI 801 530 E Rev. 1.02.00

#### **Release Notes**

#### HI 801 530 E

For further information, please contact:

#### **HIMA Paul Hildebrandt GmbH**

Albert-Bassermann-Str. 28 68782 Brühl, Germany

Phone +49 6202 709-0 Fax +49 6202 709-107 E-mail info@hima.com

Learn more about HIMax online:



www.hima.com/en/products-services/himax/