TANZANIA WATERPOINT FUNCTIONALITY — EXECUTIVE TRIAGE DASHBOARD

Automated Field Maintenance Report | Evaluated Volume: 50 Waterpoints | Generated: 2026-10-13 15:18:06

Total Evaluated	Functional	Needs Repair	Non-Functional	Critical Attention
50 (100%)	34 (68.0%)	6 (12.0%)	10 (20.0%)	16 (32.0%)

1. Waterpoint Status Breakdown



2. Triage Priority Action



3. Top Critical Regions



4. Top 10 High-Risk Waterpoints Requiring Immediate Field Dispatch

Waterpoint ID	Region	Type	Quantity	Predicted Status	Risk Score	Recommended Field Acti
1032	Lindi	communal standpipe	enough	functional	93.7%	URGENT: Rehab
1019	Lindi	communal standpipe	dry	functional needs re	92.4%	Monitoring
1006	Tabora	communal standpipe	insufficient	functional needs re	87.6%	Monitoring
1025	Kigoma	other	dry	non functional	86.1%	URGENT: Rehab
1043	Kilimanjaro	communal standpipe	dry	functional needs re	86.0%	URGENT: Rehab
1050	Lindi	other	seasonal	functional	85.8%	Monitoring
1027	Lindi	communal standpipe	seasonal	functional	84.3%	Monitoring
1036	Kilimanjaro	communal standpipe	insufficient	functional	83.5%	Monitoring
1023	Kigoma	communal standpipe	enough	functional	82.7%	Monitoring
1029	Iringa	other	seasonal	functional	79.3%	URGENT: Rehab