NEVER EVER STAND STILL





32-NCY 4-Axis CNC Lathe with "C" & "Y" Axis 1-3/8" Bar Capacity



32-GTS 6-Axis Dual Spindle Twin-Gang CNC Mill-Turn 1-3/8" Bar Capacity



32-CS 7-Axis CNC "Swiss Style" Lathe 1.25" Bar Capacity



78-MSY Twin Spindle Single Turret CNC Mill-Turn 3" Bar Capacity



52/70-TTMY Twin Spindle Twin-Turret CNC Mill-Turn 2"/ 2-3/4" Bar Capacity



52/70-3TMY Twin Spindle Three-Turret CNC Mill-Turn 2"/ 2-3/4" Bar Capacity



52-BY2 "B" Axis Multi - Tasking

CNC Mill-Turn 2" Bar Capacity

Multi Axis 4 - 11 Axis **CNC Bar Machines**

Booth # 1959

Feb 24th - 26th, 2015



www.ganeshmachinery.com | 818-349-9166







Multi-Tasking Machines | CNC Turning & Turn/Mill Centers | High Speed Machining Centers | Heavy Duty Big Bore Lathes | 5-Axis VMC

CALL FOR MORE INFORMATION

4" Kuraki Horizontal Boring Mill with 4th Axis Table KURAKI Model KBM-11A New 1998 \$279,500

Okumua Heavy Duty 25" Pallet 2-Pallet HMC OKUMA HOWA Model Millac 630H New 2005 \$210,000

37" Timesaver 137-1HDMW Wet Belt Grinder Model 137-1HDMW New 2001 \$29,500

Chevalier FM-3VKH 2-Axis **CNC Knee Mill** New 1993 \$11,500

4" Nomura Horizontal Boring Mill with 4th Axis Table

USED EQUIPMENT FOR SA

NOMURA Model HBA-100T-R3 New 1998 \$269,000

AWEA SP-3016 CNC Bridge VMC AWEA Model SP-3016 New 2000

\$189,500

Mazak Integrex E-1060V/8ii 5-Axis Mill Turn Machine MAZAK Model Integrex E-1060V/8ii

New 2009 \$810,000

25"x120" Toolmex Engine Lathe Model TUR630A New 1996 \$33,000

Yang MV-3A Box Way Geared Head CNC VMC

YANG Model MV-3A New 1995 \$23,500

5"x12" Myford Precision Cylindrical Grinder Model MG-12 HAR

New 1981 \$22,500

Front / Rear Chucks, Threading and **Taper Attachments** New 1976 \$89.500

#2 OMV Cincinnati Milacron Centerless Grinder New 1990 **Call For Price**

WWW.STYSINC.COM

Phone: (216) 641-7897 | Fax: (216) 641-7868 | Office Email: sales@stysinc.com | Shop Email: stysinc521@gmail.com

The first thing to wear out on a CNC machine is often the drawbar!

Belleville springs hold the arbor in the spindle during cutting AND they are often the first thing to wear out on a CNC Machining Center. Just one broken spring has a huge effect on clamping force. Chatter, low tool life, poor finishes, less repeatability, and scrap parts are the result.

Eventually a tool may pull out during a cut, causing major damage to the machine and spindle.

Machines are never the same after a crash A typical drawbar assembly

Test CAT, BT, ISO, HSK, CAPTO and others

CLAMPRITE Spindle Drawbar Force Gage



Works with all types of pull studs

Drawbars seldom get the attention they deserve. Checking it requires a specially designed tool. The Clamprite Gage simulates a tool in the spindle, reads directly in pounds of force, and checks your drawbar in less than a minute.

Thousands of shops in the U.S. and around the world use the Clamprite Gage.

Customers say "it paid for itself the first time we used it"

The Clamprite Gage is the most economical tool for checking the drawbar force of your machine. Kits are furnished in a metal tool box with tray, and a foam fitted liner to protect the gage head.

Select your kit by spindle type and maximum drawbar force you will be testing. Go to www.clamprite.com for more information.

Find out if your drawbars still Clamprite. Call today!

www.clamprite.com Ph: 775-246-5100 Toll Free: 1-866-THE GAGE