Home Entry Prints Edit Data Entry Reports Logout

Indent Report

Indent No :KPY01077

Vehicle Reg No :LABOURWORK Make : Model :

Driver/Operator/Vehicle KP02645 Inspector Report No:

Indent 05-04-2022

Date: | Approxmate | A

Inspector Report No 1					
S.No.	Vehicle.No.	Description of Item	Unit(LS).	Approxmate Value	Amount
1	AP 11 X 6585	FRONT BROKEN CHASSIS SIDE NEW PATCH FITTING AND FULL WELDING BOLTS FITTING WORK CHASSIS CROSS MEMBER WELDING WORK MS ANGULAR AND FLATE PATTI TO MAKING BATTERY CASE AND WELDING WORK	1	9000	9000
				Total	9000

certified that the above spares truly required for the repair of the vehicles

A.E/A.E.E

Dy.E.E

EXECUTIVE ENGINEER S.W.M and Transport Chief Transport Officer GHMC.

Obtain Quotation and Prepare comparative Statement of rates for placing above Purchase order /work order

Site Best viewed in 1024*768 / IE7 (Designed, Developed & Maintained by IT Department.)