

FIRST NOTIFICATION OF LOSS

Submitted by Front Range Commercial Insurance Group, Inc. · Broker reference FRC/GL/2025/8804

NOTIFICATION

Reported by:	Hollis Baumgartner-Reyes
Reporting organisation:	Front Range Commercial Insurance Group, Inc.
Role:	Account Executive
Email:	h.baumgartner-reyes@frcig.example
Telephone:	+1 303 555 0198
Date reported:	9 February 2026

POLICY

Policy number:	
Insured name:	Beacon Mechanical Services, Inc.
Insured organisation:	Beacon Mechanical Services, Inc.
Policy type:	Not stated — client holds both a liability and an installation floater
Period of cover:	Not stated on the notice

CLAIMANT

Claimant name:	Cherry Creek Medical Campus Owner, LLC
Claimant contact:	Terrance Achebe-Lindgren, Project Manager (insured)
Claimant email:	t.achebe-lindgren@beaconmech.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy · Beacon Mechanical Services, Inc.

THE LOSS

Date of loss: **7 February 2026**
Time of loss: **from about 19:30, discovered 07:10 on 8 February**
Loss location: **3400 South Cherry Creek Drive North, Denver, CO 80209**
Country: **United States**
Cause of loss: **Escape of water — grooved coupling separation on a newly installed riser**

Description of loss:

The insured's crew filled and pressurised a new chilled water riser on Saturday afternoon and left site at about 17:00. A 6-inch grooved coupling on the riser separated at Level 4 during the evening and water discharged for approximately eleven and a half hours before it was found on Sunday morning. Water spread from the Level 4 riser closet into the corridor and three tenant suites, down through slab penetrations to Level 3, and into the Level 1 mechanical room.

Property affected:

Third-party: Level 4 corridor and Suites 410 and 415; Suite 315 including a wall-mounted panoramic X-ray unit and two operatory cabinets; Level 1 and 2 common areas. The insured's own: installation materials in the mechanical room, a pipe threading machine and hand tools, and the new riser itself

Injuries: **0**
Fatalities: **0**
Business interruption: **Yes — three tenant practices closed**
Structural damage: **No**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **590,000**
Repair estimate: **425,000**

ADDITIONAL

Incident reference: **BMS-2026-0207**
Authorities involved: **None**
Potential litigation: **Yes — the general contractor has served an indemnity demand**