

FIRST NOTIFICATION OF LOSS

Submitted by Sonoran Ridge Risk Advisors, LLC · Broker reference SRR/BR/2025/1147

NOTIFICATION

Reported by:	Desmond Achterberg
Reporting organisation:	Sonoran Ridge Risk Advisors, LLC
Role:	Producer
Email:	d.achterberg@sonoranridgerisk.example
Telephone:	+1 602 555 0510
Date reported:	13 April 2026

POLICY

Policy number:	IM-2298-66401
Insured name:	Meridian Grid Holdings, LLC
Insured organisation:	Meridian Grid Holdings, LLC
Policy type:	Stated as contractors equipment — see the risk manager's report
Period of cover:	Not stated on the notice

CLAIMANT

Claimant name:	Ironbark Constructors, Inc.
Claimant contact:	Alina Petrosyan-Ward, Corporate Risk Manager
Claimant email:	a.petrosyan-ward@ironbarkconstructors.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy IM-2298-66401 · Meridian Grid Holdings, LLC

THE LOSS

Date of loss: **11 April 2026**
Time of loss: **between 01:20 and 03:05, discovered 06:15**
Loss location: **14900 South Cypress Landing Way, Mesa, AZ 85212**
Country: **United States**
Cause of loss: **Theft — copper stripped from the works**

Description of loss:

Perimeter fence fabric was cut on the north-east boundary after two site cameras covering that approach were disabled. Roughly 4,800 linear feet of 500 and 750 kcmil copper feeder cable was cut from reels and from partially pulled runs in duct bank sections DB-4 and DB-5, 1,100 feet of 4/0 bare copper was stripped from the substation pad ground ring, and sixteen copper busway sections were removed. Two owner-supplied UPS module cabinets were damaged in an attempt to strip their bus stabs.

Property affected:

4,800 lin ft of copper feeder cable; 1,100 lin ft of ground ring conductor; 16 copper busway sections; two 500 kVA UPS module cabinets; duct bank DB-4 and DB-5 conduit and six handhole lids; one engine drive welder and hand tools from a job trailer; 220 lin ft of perimeter fence; two site cameras

Injuries: **0**
Fatalities: **0**
Business interruption: **No — delay in start-up not purchased on this programme**
Structural damage: **No**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **1,318,100**
Repair estimate: **1,264,000**

ADDITIONAL

Incident reference: **IBC-SEC-2026-0071**
Police reference: **MPD-2026-0338114**
Authorities involved: **Mesa Police Department**
Potential litigation: **None indicated**