

FIRST NOTIFICATION OF LOSS

Submitted by Coastline Brantley Insurance Advisors · Broker reference CB/ROOF/2024/3376

NOTIFICATION

Reported by:	Sylvia Okonjo-Pratt
Reporting organisation:	Coastline Brantley Insurance Advisors
Role:	Producer
Email:	s.okonjo-pratt@coastlinebrantley.example
Telephone:	+1 757 555 0271
Date reported:	19 June 2025

POLICY

Policy number:	GL-3376-90284
Insured name:	Tidewater Roofing & Exteriors, LLC
Insured organisation:	Tidewater Roofing & Exteriors, LLC
Policy type:	Commercial General Liability - Occurrence
Period of cover:	1 November 2024 to 1 November 2025

CLAIMANT

Claimant name:	Suffolk City Public Schools
Claimant contact:	Marguerite Delacroix-Iwu, Facilities Director
Claimant email:	m.delacroix-iwu@suffolkcps.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy GL-3376-90284 · Tidewater Roofing & Exteriors, LLC

THE LOSS

Date of loss: **18 June 2025**
Time of loss: **16:40 EDT**
Loss location: **4652 Driver Lane, Suffolk, VA 23435**
Country: **United States**
Cause of loss: **Water damage — rain into a roof left open during tear-off**

Description of loss:

The insured tore off approximately 9,400 sq ft of existing built-up roofing across Sections C and D under a summer-recess re-roof contract. Tear-off finished at 15:30 and the crew began temporary dry-in. A fast-developing thunderstorm arrived at about 16:40, roughly ninety minutes before planned dry-in completion. Approximately 6,200 sq ft had been dried in; approximately 3,200 sq ft had not. Water entered over eight classrooms and part of the media centre.

Property affected:

Eight classrooms C-104 to C-111 with ceiling collapse in six; the media centre including approximately 1,850 library volumes and two computer carts; Corridor C ceiling and four troffers; two 277/480V lighting panels; eight smoke detectors

Injuries: **0**
Fatalities: **0**
Business interruption: **No — the school was on summer recess**
Structural damage: **No — deck and insulation saturated but sound**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **510,000**
Repair estimate: **422,000**

ADDITIONAL

Incident reference: **SCPS-2025-RF-011**
Authorities involved: **None**
Potential litigation: **None indicated**