

FIRST NOTIFICATION OF LOSS

Submitted by Ridgeway Kessler Brokerage Services · Broker reference RK/MFG/2024/2210

NOTIFICATION

Reported by:	Priya Raghunathan-Lowe
Reporting organisation:	Ridgeway Kessler Brokerage Services
Role:	Wholesale Broker
Email:	p.raghunathan-lowes@ridgewaykessler.example
Telephone:	+1 864 555 0913
Date reported:	15 August 2025

POLICY

Policy number:	CP-2210-55870
Insured name:	Fairmount Textile Mills Holdings, Inc.
Insured organisation:	Fairmount Textile Mills Holdings, Inc.
Policy type:	Manufacturing All Risk Property
Period of cover:	1 September 2024 to 1 September 2025

CLAIMANT

Claimant name:	Piedmont Dye & Finish, LLC
Claimant contact:	Auberon Mkhize-Calloway, Director of Manufacturing Operations
Claimant email:	a.mkhize-calloway@fairmounttextile.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy CP-2210-55870 · Fairmount Textile Mills Holdings, Inc.

THE LOSS

Date of loss: **13 August 2025**
Time of loss: **21:04 EDT**
Loss location: **1180 Woodruff Industrial Road, Greenville, SC 29607**
Country: **United States**
Cause of loss: **Fire — hydraulic fluid release onto a hot thermal oil line**

Description of loss:

Second-shift operators reported flame at a hydraulic hose on Jet Dye Machine No. 4 in Building 1B. Pressurised fluid from a hose replaced two days earlier released onto a hot thermal oil line and auto-ignited. Fire spread into the overhead cable tray and into lint accumulation in the dust collection ductwork serving the finishing line. Two sprinkler zones operated and the plant fire brigade deployed hose lines; the fire was out at 22:47.

Property affected:

Jet Dye Machine No. 4 (total loss) and Machines 3 and 5; approximately 18,000 sq ft of Building 1B; motor control centre MCC-1B-2 and the finishing line PLC cabinets; the baghouse and dust collection ductwork; 214,000 linear yards of technical fabric

Injuries: **2**
Fatalities: **0**
Business interruption: **Yes — the dye house is the plant bottleneck with no redundancy**
Structural damage: **Yes — roof deck distortion over 3,200 sq ft, membrane burn-through**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **30,500,000**
Repair estimate: **17,900,000**

ADDITIONAL

Incident reference: **GCFD-25-0081144**
Authorities involved: **Greenville City Fire Department**
Potential litigation: **None indicated**