

FIRST NOTIFICATION OF LOSS

Submitted by Ridgeway Kessler Brokerage Services · Broker reference RK/MFG/2024/2210

NOTIFICATION

Reported by:	Priya Raghunathan-Lowe
Reporting organisation:	Ridgeway Kessler Brokerage Services
Role:	Wholesale Broker
Email:	p.raghunathan-low@ridgewaykessler.example
Telephone:	+1 864 555 0913
Date reported:	15 May 2025

POLICY

Policy number:	CP-2210-55870
Insured name:	Fairmount Textile Mills Holdings, Inc.
Insured organisation:	Fairmount Textile Mills Holdings, Inc.
Policy type:	Manufacturing All Risk Property
Period of cover:	1 September 2024 to 1 September 2025

CLAIMANT

Claimant name:	Fairmount Technical Fabrics, Inc.
Claimant contact:	Auberon Mkhize-Calloway, Director of Manufacturing Operations
Claimant email:	a.mkhize-calloway@fairmounttextile.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy CP-2210-55870 · Fairmount Textile Mills Holdings, Inc.

THE LOSS

Date of loss: **14 May 2025**
Time of loss: **15:40 EDT**
Loss location: **1180 Woodruff Industrial Road, Greenville, SC 29607 — Building 1D**
Country: **United States**
Cause of loss: **Collapse — bolted connection failure on a storage mezzanine**

Description of loss:

A steel storage mezzanine installed in 2018 over the north bay of Building 1D gave way during a routine fork truck let-down of fabric rolls. The collapse ran about 62 feet along the north wall over the full 28-foot depth of the mezzanine, bringing approximately 1,740 sq ft of deck down onto the racking and floor below. Nobody was on the mezzanine. The fork truck operator was at floor level about 30 feet away and was not struck.

Property affected:

1,740 sq ft of collapsed mezzanine and a further 3,900 sq ft unloaded and shored; 14 bays of pallet racking destroyed and 6 more to inspect; two ESFR branch lines and 11 heads; approximately 2,900 rolls of technical and coated fabric; north wall girts over 40 feet; two leased fork trucks

Injuries: **0**
Fatalities: **0**
Business interruption: **Yes — the north bay is out of service, shipping run from the south bay and LOC 3**
Structural damage: **Yes — girts deformed, slab spalled, column baseplates to inspect**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **8,700,000**
Repair estimate: **2,833,000**

ADDITIONAL

Incident reference: **FTM-2025-0514**
Authorities involved: **City of Greenville notified of the sprinkler impairment**
Potential litigation: **None indicated**