

FIRST NOTIFICATION OF LOSS

Submitted by Kettleridge Risk Partners, LLC · Broker reference KRP/CAR/2025/6612

NOTIFICATION

Reported by: **Marcus Adeyemi-Croft**
Reporting organisation: **Kettleridge Risk Partners, LLC**
Role: **Producer**
Email: **m.adeyemi-croft@kettleridgerisk.example**
Telephone: **+1 918 555 0347**
Date reported: **22 October 2025**

POLICY

Policy number:
Insured name: **Sundale Property Group, LLC**
Insured organisation: **Sundale Property Group, LLC**
Policy type: **Builder's Risk - Completed Value**
Period of cover: **1 February 2025 to 1 February 2027**

CLAIMANT

Claimant name: **Halcyon Builders, LLC**
Claimant contact: **Owen Kastellec-Brandt, Project Executive**
Claimant email: **o.kastellec-brandt@halcyonbuilders.example**

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy · Sundale Property Group, LLC

THE LOSS

Date of loss: **18 October 2025**
Time of loss: **overnight, discovered 20 October 06:40**
Loss location: **1725 Northfield Commons Drive, Madison, WI 53704**
Country: **United States**
Cause of loss: **Water intrusion — wind-driven rain into an incomplete structure**

Description of loss:
A frontal system crossed Dane County over the weekend. NWS Madison recorded 2.81 inches of rain over about thirty hours with gusts to 44 mph. Water entered Building A at two unflashed mechanical curbs and at the elevator overrun, and tracked down the shaft to the pit. Wind tore roughly 60% of the temporary poly on the north elevation at Levels 3 and 4, admitting wind-driven rain across two floors. Nobody was on site over the weekend.

Property affected:
11,400 sq ft of hung gypsum board and batt insulation on Levels 3 and 4; 4,200 sq ft of Level 2 ceiling assemblies; 190 sheets of stored board and 84 rolls of insulation; the elevator pit, rails and buffers; 14 panelboards and 320 device boxes; 700 linear feet of installed ductwork

Injuries: **0**
Fatalities: **0**
Business interruption: **No — schedule float absorbs two to three weeks**
Structural damage: **No — floor sheathing edge swell under assessment**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **915,000**
Repair estimate: **805,000**

ADDITIONAL

Incident reference: **HAL-NSL-2025-0088**
Authorities involved: **None**
Potential litigation: **None indicated**