

SITE SECURITY AND LOSS REPORT

Queen City Site Security · Our reference QCSS-2026-0118

INSTRUCTIONS

Instructed by:	Ashcombe Vail Commercial Insurance Services
On behalf of:	Rivergate Development Partners, LLC
Policy number:	
Author:	Delphine Amankwah-Ritter, Operations Supervisor
Prepared for:	Vanterra Construction Group, LLC
Prepared on:	19 January 2026
Discovery:	18 January 2026, 07:40, weekend patrol
Scope:	Discovery, site protection arrangements and preserved evidence

PROJECT AND WORKS AFFECTED

Project:	Rivergate Commons Phase II, 214 units over a two-level podium
Project status:	Level 5 framing, MEP rough-in on Levels 2 and 3, no CO issued
Stolen — permanent works:	Copper wire, tube, trim, eight panelboards
Damaged — permanent works:	Conduit, 140 boxes, drywall, three doors
Temporary works:	Perimeter fence and two site cameras

SITE SECURITY AND LOSS REPORT

Circumstances and findings

CIRCUMSTANCES

Circumstances:

The site was secured and vacated on Friday 16 January at 16:00. Two gates, six foot chain link, locked outside working hours. Eleven cameras with a recording DVR, not centrally monitored. A nightly drive-through patrol is contracted to this company under a written agreement.

FINDINGS

Findings:

Fence fabric was cut on the Rivergate Parkway frontage rather than at either gate. Two cameras covering the north-west corner were disabled by cutting their cables; the remaining nine recorded throughout and the footage has been exported and provided to Charlotte-Mecklenburg Police. The patrol log for 16 to 18 January is attached to this report. High-value material was partly secured: the panelboards and the plumbing trim were in a lockable Level 2 storage room and a Level 3 closet, but the wire reels were in the open on Level 2 and the copper tube was banded on the Level 3 deck. Nothing has been repaired or cleared; cut wire ends, damaged boxes, crushed conduit and the cut fence fabric are all in place.

Date of loss:	17 January 2026
Cause of loss:	Theft — copper stripped from the partially completed works
Incident reference:	RGC2-IR-2026-004
Injuries reported:	0

SITE SECURITY AND LOSS REPORT

Preliminary quantum and reserve advice

PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Copper branch circuit wire, 3,100 ft:	USD 74,000
Unpulled THHN reels, 22 off:	USD 58,000
Copper water tube, 900 ft:	USD 41,000
Plumbing fixtures and trim, 46 sets:	USD 33,000
Panelboards, eight off:	USD 47,000
Conduit, boxes, drywall, doors and rework:	USD 133,400
Estimated loss:	394,400
Currency:	USD

ON THE SITE PROTECTION REQUIREMENTS

Comment:

The project's builder's risk policy requires fencing with lockable gates, site lighting, and either monitored cameras or a logged nightly patrol. Both a recording camera system and a contracted logged patrol were in place, so the requirement appears satisfied on its face. The patrol log and the camera retention certificate are provided so that can be verified rather than assumed.

RECOMMENDATION

Recommendation:

Move all remaining copper and panelboards into a locked container inside the fence line, add a second overnight patrol and post a static guard until the MEP rough-in is closed up.