

FIRST NOTIFICATION OF LOSS

Submitted by Ashcombe Vail Commercial Insurance Services · Broker reference AV/BR/2025/3358

NOTIFICATION

Reported by:	Gerald Nwosu-Fitzgerald
Reporting organisation:	Ashcombe Vail Commercial Insurance Services
Role:	Construction Claims Handler
Email:	g.nwosu-fitzgerald@ashcombevail.example
Telephone:	+1 704 555 0731
Date reported:	26 February 2026

POLICY

Policy number:	BR-3358-20471
Insured name:	Rivergate Development Partners, LLC
Insured organisation:	Rivergate Development Partners, LLC
Policy type:	Builder's Risk - Completed Value
Period of cover:	15 April 2025 to 15 October 2026

CLAIMANT

Claimant name:	Vanterra Construction Group, LLC
Claimant contact:	Callum Baptiste-Ngo, Project Superintendent
Claimant email:	c.baptiste-ngo@vanterracg.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy BR-3358-20471 · Rivergate Development Partners, LLC

THE LOSS

Date of loss: **26 February 2026**
Time of loss: **14:52 EST**
Loss location: **2650 Rivergate Parkway, Charlotte, NC 28273**
Country: **United States**
Cause of loss: **Dropped load — wind gust during a crane pick**

Description of loss:

A bundled load of engineered floor joists and LVL beams being hoisted to Level 4 met a recorded 41 mph gust at about 42 feet. The load swung, the signal person called for a set-down, and during the set-down the load struck the north-east corner of the Level 3 framed wall. The choker then slipped and roughly two-thirds of the bundle fell to the podium deck below. The exclusion zone held and nobody was struck.

Property affected:

26 linear feet of Level 3 framed and sheathed exterior wall; two impact craters in the precast podium topping, one with exposed strand; 38 engineered joists and 6 LVL beams; 60 feet of edge protection; 46 sheets of subfloor sheathing; a construction hoist mast tie

Injuries: **0**
Fatalities: **0**
Business interruption: **No — schedule impact assessed at three to five weeks**
Structural damage: **Yes — podium deck strand exposed, wall section racked out of plumb**
Environmental exposure: **No**

FINANCIAL

Currency: **USD**
Estimated loss: **407,200**
Repair estimate: **407,200**

ADDITIONAL

Incident reference: **RGC2-IR-2026-014**
Authorities involved: **None — not OSHA reportable**
Potential litigation: **None indicated**