

FIRST NOTIFICATION OF LOSS

Submitted by Coastline Brantley Insurance Advisors · Broker reference CB/ROOF/2024/3376

NOTIFICATION

Reported by: Sylvia Okonjo-Pratt
Reporting organisation: Coastline Brantley Insurance Advisors
Role: Producer
Email: s.okonjo-pratt@coastlinebrantley.example
Telephone: +1 757 555 0271
Date reported: 27 August 2025

POLICY

Policy number:
Insured name: Tidewater Roofing & Exteriors, LLC
Insured organisation: Tidewater Roofing & Exteriors, LLC
Policy type: Commercial General Liability - Occurrence
Period of cover: Renewed November 2024 — certificates with the insured

CLAIMANT

Claimant name: Chandler Vale Cold Chain Solutions
Claimant contact: Ignatius Bellweather-Cho, Project Manager (insured)
Claimant email: i.bellweather-cho@tidewaterroofing.example

FIRST NOTIFICATION OF LOSS (CONTINUED)

Policy · Tidewater Roofing & Exteriors, LLC

THE LOSS

Date of loss: 26 August 2025
Time of loss: 11:15 EDT
Loss location: 1900 Bainbridge Logistics Way, Chesapeake, VA 23320
Country: United States
Cause of loss: Impact — crane load swung into a tenant's rooftop condensing units

Description of loss:

A bundle of insulation board and TPO membrane rolls was being flown to Roof Section 7 by a 90-ton hydraulic crane set up in the truck court. On the way over the load contacted the guy wires and then the housing of a tenant's rooftop condensing unit bank. Nothing fell; the load swung into the equipment and dragged across it. The tenant's process refrigeration serving a 22,000 sq ft temperature-controlled fulfilment area was taken out.

Property affected:

Four rooftop condensing units belonging to the tenant — two with crushed coils and bent fan shrouds, one with a fractured refrigerant line and full charge lost, one displaced off its curb; approximately 140 lb of R-448A vented; 30 ft of rooftop refrigerant piping and insulation; two condenser disconnects and whips; 20 ft of aluminium rooftop walkway

Injuries: 0
Fatalities: 0
Business interruption: Yes — tenant's temperature-controlled area on temporary cooling, product at risk
Structural damage: No
Environmental exposure: Yes — approximately 140 lb of R-448A refrigerant vented

FINANCIAL

Currency: USD
Estimated loss: 182,000
Repair estimate: 142,000

ADDITIONAL

Incident reference: TWR-HRLC-2025-0826
Authorities involved: None
Potential litigation: Yes — the property manager has served notice on the insured