

GEK-91457-7

INSTRUCTIONS

ELECTRIC DRIVE DRILLING EQUIPMENT

5GTA30

DRILLING ALTERNATOR

TRANSPORTATION SYSTEMS BUSINESS OPERATIONS

ERIE PENNSYLVANIA 16531

GENERAL ELECTRIC

PRINTED IN U.S.A.

CONTENTS

GENERAL MAINTENANCE OF ELECTRICAL ROTATING APPARATUS . . . GEI-85166

COMMUTATOR MAINTENANCE GEI-85167A

5GTA30 DRILLING ALTERNATOR GEK-87916A

INSPECTION AND MAINTENANCE SCHEDULE GEK-47175A

LUBRICATION SPECIFICATIONS GEI-73029C

SHIPPING INSTRUCTIONS GEI-69852C

RECOMMENDED STORAGE INSTRUCTIONS GEK-61777

REMOVING MOTORS AND GENERATORS FROM STORAGE GEK-2818

These instructions do not purport to cover all details or variations in equipment nor to provide for every possible contingency to be met in connection with installation, operation or maintenance. Should further information be desired or should particular problems arise which are not covered sufficiently for the purchaser's purposes, the matter should be referred to the General Electric Company. Any applicable Federal, State or local regulations or company safety or operating rules must take precedence over any instructions given in this material. GE has no obligation to keep the material up to date after the original publication.

THERE ARE NO WARRANTIES OF ACCURACY, MERCHANTABILITY OR FITNESS FOR PARTICULAR PURPOSE.

Verify numbers for parts, tools, or material by using the Renewal Parts or Tool Catalogs, or contact your General Electric representative for assistance. Do not order from this publication.

GENERAL ELECTRIC