Figure 1: Access Portal – Account Registration




Figure 2: Create Account Form




Figure 3: Forgot Password





Figure 4: Mining Monitoring Dashboard



Figure 5: Dashboard – Active Alerts



Active Alerts

Category	ID	Level	Message	Recommended Action
Safety Incident	INC002	HIGH	HIGH severity safety incident	Investigate the incident and implement
Safety Incident	INC004	CRITICAL	CRITICAL severity safety incident	Investigate the incident and implement
Equipment	TRK-012	CRITICAL	Temperature = 104 °C, Vibration = 9.2 mm/s	Inspect equipment and initiate appropr
Equipment	LHD-003	WARNING	Temperature = 88 °C, Vibration = 6.4 mm/s	Inspect equipment and initiate appropr
Equipment	DRL-004	CRITICAL	Temperature = 97 °C, Vibration = 8.6 mm/s	Inspect equipment and initiate appropr
Maintenance	TRK-012	WARNING	Repeated equipment alerts (3)	Perform a detailed inspection to identif
Maintenance	DRL-004	CRITICAL	Maintenance overdue	Schedule the equipment for maintenan
Maintenance	DRL-004	WARNING	Excessive downtime (42 hours)	Investigate the cause of excessive down
Maintenance	DRL-004	WARNING	Repeated equipment alerts (4)	Perform a detailed inspection to identif
Maintenance	CONV-01	WARNING	Excessive downtime (55 hours)	Investigate the cause of excessive down

Figure 6: Safety Incidents by Department




Figure 7: Dashboard – Equipment Availability




Figure 8: Worker Health and Safety Monitoring



Worker ID	Department	Job Role	Shift	PPE Compliance	Safety Training Status	Fatigue Level	Safety Observations	Ne
W001	Mining	Drill Operator	Day	Yes	Complete	Low	2	
W002	Mining	LHD Operator	Night	No	Complete	High	5	
W003	Maintenance	Fitter	Day	Yes	Incomplete	Medium	3	
W004	Processing	Plant Operator	Night	Yes	Complete	High	4	
W005	Safety	Safety Representative	Day	Yes	Complete	Low	1	

Figure 9: Incidents by Type




Figure 10: Safety Incident Database




Figure 11: Add New Incident Form



Figure 12: Equipment Database and Condition Monitoring




Figure 13: Equipment Temperature Chart




Figure 14: Equipment Vibration Chart




Figure 15: Equipment Maintenance Monitoring





Figure 16: Maintenance – Equipment Availability



Availability = Operating Time / (Operating Time + Downtime) × 100.

Figure 17: Mining Risk Assessment




Figure 18: User Management

