

Centurion UK Rentals & Services

Unit 12 Denmore Road, Bridge Aberdeen, AB23 8JW Tel: 01224 826662

REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE)

This document is in accordance with; The Lifting Operations and Lifting Equipment Regulations SI 2307:1998

The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment) Regulations SI 2184:2006

The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment) (Amendment) Regulations SI 2166:2008

Report Number: 462091

Date of Examination: 29/12/2023

Date of Report: 29/12/2023

Cust. Ref/PO No: 15146980

Qty, Description of Equipment, Serial Numbers			Manufacturer & Date of Manufacturer (if known)	Working Load Lim	it Proof Load Applied	First Examination Yes / No	Date of Last Thorough Examination	Date Of Next Thorough Examination	Date Next Test Due	Test Certificate Number or Manufacturer Tracking Ref
4 M30 4T HW COLLAR EYEBOLT			GEORGE TAYLOR	4.00TE	N/A	NO	14/07/2023	28/07/2024	N/A	370041.G
Serial No(s): 14JA1-4										
Particulars of defects which are a danger to persons or 'None' NONE	Particulars of any other defects or 'none' NONE		repaired		Particulars of any repair, alteration to remedy defect or 'none' NONE			Particulars of any Observations		
NONE										
was made: carried out. ITHACA ENERGY UK LTD HILL OF RUBISLAW ABERDEEN Centurion Unit 16 Det Aberdeen			1		Name, Address & qualifications of the person who carried out the examination:			Name & address of person signing the report on behalf of its author:		
			UK Rentals &Services Ltd nmore Road, Bridge of Don AB23 8JW		STUART COOK COMPANY APPOINTED EXAMINER					
		Aberdeen, Al						Reference No:15146980 Customer Order.879202		
Signature of the person who carried out the		Stor	,		Signature on behalf of ATR Lifting	f author for	Ľ	Dustoffier Order.8792	.02	

I hereby certify that on the above stated date the item(s) described above were thoroughly examined, and as far as is resonably practicable by this type of examination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'