Report of Visual Thorough Examination

The undersigned certifies on behalf of this company, that below particulars are correct and that the described lifting equipment is installed correctly & safe to operate.
The described lifting equipment is thoroughly examined according to LOLER S.I. 1998/2307 or LOLER S.I. 2006/2184 Regulations.
The inspection is carried out according to the LEEA and/or EKH Code of Practice.

CU Job No: 124-2-0042	Customer PO:	Customer Contact: Mcsorley, m

Report Number	: CU/2024/2001658875/V	Last Thorough Examination	: 20-Mar-2023
Date of Examination	: **26-Feb-2024**	Prev. Examination Type	: Visual
Test Location	: On Client Site	Prev. Report Number	: CU/2023/2001566797/V
Re-examination Before	: 25-Feb-2025	Inspection Interval Visual	: 12 Months

Identification No.	: **R040100**	Connected to	: N/A
Serial / Mfg cert. No.	: N/A	Related Items	: N/A
Item	: Pipe hook		
Working Load Limit (WLL)	: 4.064 tonne		

Owner	: Shell U.K. Limited 1 Altens Farm Road AB12 3FY Aberdeen Great Britain	Description : PH3 Pipe Hook Superclamp to BSEN-13155 40mm Max Pipe Wall Thickness Location - Rigging Loft	
Location	: Shearwater platform		
Material	: Alloy / Grade-T		

Manufacturer	: Riley (Lifting Equipment) Ltd., Lancashire, Great Britain
Mfg. Standard(s)	: EN-1677 / NEN 1713

Remarks	:	Noted Defects	: None
		Required Repairs	: None
		Limited Validation	: N/A
		Newly Installed/Assembled	: N/A

Date Printed	: 15-Mar-2024	Authorised and competent person:	
Name Inspector	: Bain, J.	Bain, J.	
Qualification	: Company Appointed Examiner		