

Centurion UK Rentals & Services

Unit 12 Denmore Road, Bridge Aberdeen, AB23 8JW Tel: 01224 826662

REPORT OF THOROUGH EXAMINATION (AND CERTIFICATE OF TEST IF APPLICABLE)

This document is in accordance with; The Lifting Operations and Lifting Equipment Regulations SI 2307:1998 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment), Regulations SI 2184:2006 The Merchant Shipping and Fishing Vessels (Lifting Operations and Lifting Equipment) (Amendment) Regulations SI 2166:2008 Report Number: 462160

Date of Examination: 28/12/2023

Date of Report: 28/12/2023

Cust. Ref/PO No: 15146980

Qty, Description of Equipment, Serial Numbers			Manufacturer & Date of Manufacturer (if known)	Working Load Lim	it Proof Load Applied	First Examination Yes / No	Date of Last Thorough Examination	Date Of Next Thorough Examination	Date Next Test Due	Test Certificate Number or Manufacturer Tracking Ref
6 3TE 6M EWL ROUNDSLING			SAFE HOLD	3.00T	N/A	NO	01/12/2023	27/07/2024	N/A	1971
Serial No(s) : T44345-071, T44	1345-072, T44345-07	3, T44345-07	74, T44345-075, T4434	45-076						
Particulars of defects which are a danger to persons or 'None'			repaired		Particulars of any repair, alteration to remedy defect or 'none' NONE			Particulars of any Observations		
NONE										
		Address of pre carried out.			Name, Address & qualifications of the person who carried out the examination:			Name & address of person signing the report on behalf of its author:		
HILL OF RUBISLAW Centurion			JK Rentals &Services Ltd		STUART COOK COMPANY APPOINTED EXAMINER					
Aberdeen,		Aberdeen, AE			COMPANT AFFORMED EXAMINER			Reference No:15146980		
AB15 6XL Tel: 01224 2 Signature of the person who carried out the		Tel: 01224 22	2777		Cimpature on heli-14 -4	l author for	L	Customer Order.8792	02	
examination:		SCOR	5K		Signature on behalf of ATR Lifting	autnor tof				

I hereby certify that on the above stated date the item(s) described above were thoroughly examined, and as far as is resonably practicable by this type of examination, considered to be safe to operate unless stipulated otherwise in 'Particulars of Defects'