# ;PROGRAM TO CREATE OR DELETE FILES

.MODEL SMALL
DISP MACRO MSG
LEA DX,MSG
MOV AH,09H
INT 21H
ENDM

### .DATA

MSG1 DB 0DH,0AH,"ENTER THE FILE NAME FOR CREATION: \$"
MSG2 DB 0DH,0AH,"FILE CREATED SUCCESSFULLY\$"
MSG3 DB 0DH,0AH,"CREATION FAILED\$"
MSG4 DB 0DH,0AH,"ENTER THE FILE NAME FOR DELETION: \$"
MSG5 DB 0DH,0AH,"FILE DELETED SUCCESSFULLY\$"
MSG6 DB 0DH,0AH,"DELETION FAILED\$"
FNAME1 DB 10 DUP(0)

.CODE

FNAME2 DB 10 DUP(0)

MOV AX,@DATA MOV DS,AX DISP MSG1 MOV SI,00

#### BACK1:

MOV AH,01H
INT 21H
CMP AL,0DH
JE NEXT1
MOV FNAME1[SI],AL
INC SI
JMP BACK1

### NEXT1:

MOV FNAME1[SI],'\$'
LEA DX,FNAME1
MOV CX,00
MOV AH,3CH ;FILE CREATION INTERRUPT

INT 21H JC CFAIL DISP MSG2 JMP DEL CFAIL: DISP MSG3 DEL: DISP MSG4 MOV SI,00 BACK2: MOV AH,01H INT 21H CMP AL, 0DH JE NEXT2 MOV FNAME2[SI],AL INC SI JMP BACK2 NEXT2: MOV FNAME2[SI], '\$' LEA DX, FNAME2 MOV CX,00 MOV AH,41H ;FILE DELETION INTERRUPT INT 21H JC DFAIL DISP MSG5 JMP LAST DFAIL: DISP MSG6 LAST: MOV AH,4CH INT 21H

**END** 

### **OUTPUT:**

MOV DS, AX

DOSBox 0.74-3, Cpu speed: 3000 cycles, Frameskip 0, Program: DOSBOX Х C:\>LINK FILE.OBJ;; Microsoft (R) Overlay Linker Version 3.60 Copyright (C) Microsoft Corp 1983-1987. All rights reserved. LINK : warning L4021: no stack segment C:\>FILE.EXE ENTER THE FILE NAME FOR CREATION : BMSCE FILE CREATED SUCCESSFULLY ENTER THE FILE NAME FOR DELETION : BMSCE FILE DELETED SUCCESSFULLY C:\>FILE.EXE ENTER THE FILE NAME FOR CREATION : QWE FILE CREATED SUCCESSFULLY ENTER THE FILE NAME FOR DELETION : ASD DELETION FAILED C:\>s

; TO DISPLAY SYSTEM TIME IN STANDARD FORMAT
.MODEL SMALL
DISPLAY MACRO MSG
LEA DX,MSG
MOV AH,09H
INT 21H
ENDM

.DATA
TIMESTR DB 020H DUP(?)
MSG1 DB "CURRENT TIME :: \$"

.CODE
START:
MOV AX,@DATA

```
;CLEAR SCREEN
MOV AH,00H
MOV AL, 03H
INT 10H
AG:
;SET PARTICULAR LOCATION FOR THE CLOCK
MOV BH,00H
MOV DH,01H
MOV DL,01H
MOV AH, 02H
INT 10H
MOV SI, OFFSET TIMESTR
MOV AH, 2CH ; INTERRUPT FOR GETTING SYSTEM TIME
INT 21H
MOV AL, CH; CH-HOUR CL-MIN DH-SEC
AAM
ADD AX,3030H
MOV [SI], AH
INC SI
MOV [SI], AL
INC SI
MOV [SI], BYTE PTR':'
INC SI
MOV AL, CL ; CH-HOUR CL-MIN DH-SEC
AAM
ADD AX,3030H
MOV [SI], AH
INC SI
MOV [SI],AL
INC SI
MOV [SI], BYTE PTR':'
INC SI
MOV AL, DH; CH-HOUR CL-MIN DH-SEC
AAM
```

```
ADD AX,3030H
MOV [SI], AH
INC SI
MOV [SI],AL
INC SI
MOV [SI], BYTE PTR'$'
DISPLAY MSG1
DISPLAY TIMESTR
;CHECK FOR KEYBOARD STATUS
; IF KEY IS PRESSED, TERMINATE THE PROGRAM
MOV AH, 0BH
INT 21H
CMP AL,00H
JE AG
FINAL:
MOV AH, 4CH
INT 21H
END START
```

## **OUTPUT:**

```
DOSBox 0.74-3, Cpu speed: 3000 cycles, Frameskip 0, Program: DOSBOX
                                                                      _ _
                                                                                  ×
CURRENT TIME :: 10:54:33
C:\>
C:\>s_
```