TOF sensor grove cable connect to 4P connector Not to Atom S3

Power cable clack to middle connector "Power in"

4p molex cable to left Connector "Power out"

4P molex cable connect to clack power connector from "power out" clack reader pcb



Clack Reader v4 connections for LESS softener (WS PI)

1x i2c grove cable 50 cm 1x 3P molex 1x 4P molex

> Chlorinator connector to "chlorinator" on clack reader pcb (not yet delivered / to be determined)