
Clack Reader v4 connections for WS1 CI

1x i2c cable -TOF sensr 1x 3P molex -flowmeter 1x 4P molex -power



Groove cable to TOF sensor I2c cable

Do <u>not</u> use the free port on the ESP