

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2021-02-03	OM-EAS	Sikorsky 269/300 (Lycoming)	5	TBSH	Performed exchange longitudinal trim servo	SHOP	B1.4	4.00	01.02.21/0283	
2021-02-03	OM-EAS	Sikorsky 269/300 (Lycoming)	5	CRS	CRS after repair	SHOP	B1.4	1.00	01.02.21/0283	
2021-02-17	OM-STA	Sikorsky 269/300 (Lycoming)	5	CRS	50H Inspection	SHOP	B1.4	6.00	01.02.21/S1815	
2021-03-09	OM-ARM	Sikorsky 269/300 (Lycoming)	5	MOD	Performed exchange transponder. CS-STAN, CS-SC002c, Form 123 No. 01.03.21/S1268	SHOP	B2	8.00	01.03.21/S1268	
2021-03-09	OM-ARM	Sikorsky 269/300 (Lycoming)	5	SPC	Performed XPDR, ELT check.	SHOP	B2	4.00	01.03.21/S1268	
2021-03-09	OM-ARM	Sikorsky 269/300 (Lycoming)	5	SPC	Magnetic compass compesation	SHOP	B2	3.00	01.03.21/S1268	
2021-03-09	OM-ARM	Sikorsky 269/300 (Lycoming)	5	CRS	CRS	SHOP	B2	1.00	01.03.21/S1268	
2021-03-10	OM-EAS	Sikorsky 269/300 (Lycoming)	5	TBSH	Performed exchange of longitude trim servo	SHOP	B1.4	4.00	01.03.21/0283	
2021-03-10	OM-EAS	Sikorsky 269/300 (Lycoming)	5	CRS	CRS after repair.	SHOP	B1.4	1.00	01.03.21/0283	
2021-03-11	OM-STA	Sikorsky 269/300 (Lycoming)	5	TBSH	Performed torque check of droop stop retaining nut.	SHOP	B1.4	2.00	01.03.21/S1815	
2021-03-11	OM-STA	Sikorsky 269/300 (Lycoming)	5	SER	Performed main rotor hub retention nut torque check	SHOP	B1.4	2.00	01.03.21/S1815	SK.145.033
2021-03-11	OM-STA	Sikorsky 269/300 (Lycoming)	5	CRS	CRS after performed work	SHOP	B1.4	2.00	01.03.21/S1815	SK.145.033
2021-03-11	OM-STA	Sikorsky 269/300 (Lycoming)	5	REP	Performed exchange of fork assembly P/N 269A5664-3	SHOP	B1.4	3.00	01.03.21/S1815	SK.145.033

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2021-03-11	OM-STA	Sikorsky 269/300 (Lycoming)	5	OPC	Performed tail rotor Track and Balance	SHOP	B1.4	2.00	01.03.21/S1812	SK.145.033
2021-03-15	OM-ARM	Sikorsky 269/300 (Lycoming)	5	SUP	Performed 25 inspection of Airframe.	SHOP	B1.4	4.00	02.03.21/S1268	SK.145.033
2021-03-15	OM-ARM	Sikorsky 269/300 (Lycoming)	5	SUP	Performed exchange if oil filter snd oil on engine	SHOP	B1.4	2.00	02.03.21/S1268	SK.145.033
2021-03-15	OM-ARM	Sikorsky 269/300 (Lycoming)	2	CRS	Performed realising to service sfter Inspection.	SHOP	B1.4	2.00	02.02.21/S1268	SK.145.033
2021-03-15	OM-STA	Sikorsky 269/300 (Lycoming)	5	SUP	Performed 25 H Inspection.	SHOP	B1.4	2.00	02.03.21/S1815	SK.145.033
2021-03-15	OM-STA	Sikorsky 269/300 (Lycoming)	5	CRS	Performed realising to service.	SHOP	B1.4	2.00	02.03.21/S1815	SK.145.033
2021-03-15	OM-EAS	Sikorsky 269/300 (Lycoming)	5	SUP	Performed 25H Inspection of Airframe	SHOP	B1.4	3.00	02.03.21/S0283	SK.145.033
2021-03-15	OM-EAS	Sikorsky 269/300 (Lycoming)	5	REM	Releasing to service	SHOP	B1.4	2.00	02.03.21/0283	SK.145.033
2021-03-18	OM-EAS	Sikorsky 269/300 (Lycoming)	5	REM	Performed 100 H; Performed Lycoming SB 480F, AD US 2015-19-07, AD US 2015-23-01	SHOP	B1.4	8.00	03.03.21/0283	SK.145.033
2021-03-18	OM-EAS	Sikorsky 269/300 (Lycoming)	5	INS	Releasing to service.	SHOP	B1.4	2.00	03.03.21/0283	SK.145.033
2021-03-18	OM-STA	Sikorsky 269/300 (Lycoming)	5	SUP	Performed 50 H inspection. Performed Lycoming SB 480F.	SHOP	B1.4	6.00	03.03.21/S1815	SK.145.033
2021-03-18	OM-STA	Sikorsky 269/300 (Lycoming)	5	CRS	Releasing to service after inspection.	SHOP	B1.4	2.00	03.03.21/S1815	SK.145.033

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2021-03-24	OM-HCY	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 200 H inspection airframe. Performed 100 H inspection engine. Performed exchange magneto P/N 4270. Performed AD US 2015-19-07, AD US 2015-23-01, Lycoming SB-480 F.	SHOP	B1.4	9.99	03.03.21/0288	SK.145.033
2021-03-24	OM-HCY	Sikorsky 269/300 (Lycoming)	5	CRS	Performed releasing to service	SHOP	B1.4	2.00	03.03.0288	SK.145.033
2021-04-12	OM-ARM	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 100 Hr inspection Airframe	SHOP	B1.4	9.00	02.04.21/S1268	SK.145.033
2021-04-13	OM-ARM	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 100 H Inspection Engine, SB 480F, AD 2015-23-01, AD US 2015-19-07	SHOP	B1.4	8.00	02.04.21/S1268	SK.145.033
2021-04-13	OM-ARM	Sikorsky 269/300 (Lycoming)	5	CRS	Releasing to service	SHOP	B1.4	2.00	02.04.21/S1268	SK.145.033
2021-04-14	OM-HCY	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 25 H inspection of Airframe	SHOP	B1.4	3.00	03.04.21/0288	SK.145.033
2021-04-14	OM-HCY	Sikorsky 269/300 (Lycoming)	5	CRS	Releasing to service after maintenance	SHOP	B1.4	2.00	03.04.21/0288	SK.145.033
2021-09-30	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed of 100 Hrs Engine Inspection	SHOP	B1.2	3.00	08/2021/ZMI	SK.CAO.009
2021-09-30	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed of 100 Hrs Airframe Inspection	SHOP	B1.2	5.00	08/2021/ZMI	SK.CAO.009
2021-09-30	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed of 100 Hrs Propeller Inspection	SHOP	B1.2	2.00	08/2021/ZMI	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	GVI	Performed 50/100/200 Hrs Airframe Inspection	SHOP	B1.2	8.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	GVI	Performed 50/100/200 Engine Inspection	SHOP	B1.2	6.00	1/2021/KIT	SK.CAO.009

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	REP	Performed replacement of Engine Oil Filter	SHOP	B1.2	1.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	SER	Performed servicing of Engine with Oil	SHOP	B1.2	1.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	FUC	Performed functional check of Fuel Quantity Indicating System	SHOP	B1.2	2.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	GVI	Performed of Annual Inspection	SHOP	B1.2	8.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	OPC	Performed operational check of NAV/COM and XPDR	SHOP	B2	3.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	OPC	Performed operational check of ELT	SHOP	B2	1.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	OPC	Performed Pitot-static and Altimeter Test	SHOP	B2	5.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	DVI	Performed of SID No.1 Inspection	SHOP	B1.2	2.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	DVI	Performed of SID No. 2 Inspection	SHOP	B1.2	2.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	DVI	Performed of SID No. 22 Inspection	SHOP	B1.2	2.00	1/2021/KIT	SK.CAO.009
2021-10-08	OM-KIT	Cessna 150/F150 (Continental)	5	DVI	Performed of SID No. 24 Inspection	SHOP	B1.2	3.00	1/2021/KIT	SK.CAO.009
2021-10-14	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100/200 Hrs Airframe inspection	SHOP	B1.2	6.00	06/2021/FFL	SK.CAO.009
2021-10-14	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100/200 Hrs Engine Inspection	SHOP	B1.2	3.00	06/2021/FFL	SK.CAO.009

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2021-10-14	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100 Hrs Propeller Inspection	SHOP	B1.2	1.72	06/2021/FFL	SK.CAO.009
2021-10-21	OM-LKJ	Viper SD-4 (Rotax) RTC	5	GVI	Performed 100/200 Hrs Airframe inspection	SHOP	B1.2	6.00	03/2021/LKJ	SK.CAO.009
2021-10-21	OM-LKJ	Viper SD-4 (Rotax) RTC	5	GVI	Performed 100/200 Hrs Engine Inspection	SHOP	B1.2	6.00	03/2021/LKJ	SK.CAO.009
2021-10-21	OM-LKJ	Viper SD-4 (Rotax) RTC	5	GVI	Performed 100 Hrs Propeller Inspection	SHOP	B1.2	2.00	03/2021/LKJ	SK.CAO.009
2021-10-21	OM-LKJ	Viper SD-4 (Rotax) RTC	5	REP	Performed replacement of Engine Oil Filter	SHOP	B1.2	1.00	03/2021/LKJ	SK.CAO.009
2021-10-21	OM-LKJ	Viper SD-4 (Rotax) RTC	5	SER	Performed servicing of Engine Oil Shell Ultra 4T 10W/40gine With Oil	SHOP	B1.2	3.00	03/2021/LKJ	SK.CAO.009
2021-10-27	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed replacement of MLG Legs	SHOP	B1.2	8.00	CAMO-2100285	SK.CAO.009
2021-11-11	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed 100/200 Hrs Airframe inspection	SHOP	B1.2	6.00	10/2021/ZMI	SK.CAO.009
2021-11-11	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed 100 Hrs Propeller Inspection	SHOP	B1.2	2.00	10/2021/ZMI	SK.CAO.009
2021-11-11	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed 100/200/400 Inspection of Engine	SHOP	B1.2	6.00	10/2021/ZMI_	SK.CAO.009
2021-11-11	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	REP	Performed replacement of Sparks Plugs P/N 297656	SHOP	B1.2	2.00	10/2021/ZMI	SK.CAO.009
2021-11-11	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	REP	Performed replacement of Engine Oil Filter	SHOP	B1.2	1.00	10/2021/ZMI	SK.CAO.009
2021-11-11	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	SER	Performed servicing of Engine Oil Shell Ultra 4T 10W/40WWith Oil	SHOP	B1.2	1.00	10/2021/ZMI	SK.CAO.009

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2021-12-09	OM-KAB	Cessna 172/F172 (Continental)	5	GVI	Performed 50 Hrs Inspection of Airframe	SHOP	B1.2	6.00	04/2021/KAB	SK.CAO.009
2021-12-09	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 50 Hrs Inspection of Engine	SHOP	B1.2	6.00	04/2021/KAB	SK.CAO.009
2021-12-09	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 50 Hrs Inspection of Propeller	SHOP	B1.2	2.00	04/2021/KAB	SK.CAO.009
2021-12-09	OM-KAB	Cessna 172/F172 (Lycoming)	5	REM	Performed replacement of Engine Oil Filter	SHOP	B1.2	1.00	04/2021/KAB	SK.CAO.009
2021-12-09	OM-KAB	Cessna 172/F172 (Lycoming)	5	SER	Performed servicing of Engine With Oil	SHOP	B1.2	2.00	04/2021/KAB	SK.CAO.009
2021-12-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	IND	Performed 100/200 Hrs Airframe inspection	SHOP	B1.2	8.00	07/2021/FFL	SK.CAO.009
2021-12-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100/200 Hrs Engine Inspection	SHOP	B1.2	6.00	07/2021/FFL	SK.CAO.009
2021-12-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100 Hrs Propeller Inspection	SHOP	B1.2	4.00	07/2021/FFL	SK.CAO.009
2021-12-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	REM	Performed replacement of Oil Filter P/N 825012	SHOP	B1.2	0.50	07/2021/FFL	SK.CAO.009
2021-12-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	SER	Performed servicing of Engine With Oil Shell Ultra 4T 10W/40	SHOP	B1.2	1.00	07/2021/FFL	SK.CAO.009
2022-02-14	OK-HSO	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	3.00	01.02.22/02	
2022-02-16	OM-BHK	UH-60A (GE-T700)	5	SPC	Performed Engine History recorder Reading	Base	B1.3	1.00	01.02.22/81-235 52	
2022-02-16	OM-BHK	UH-60A (GE-T700)	5	SUP	Supervised performed work - IGB, TGB Oil Sample.	Base	B1.3	5.00	01.02.22/81-235 52	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-02-16	OM-BHK	UH-60A (GE-T700)	5	GVI	Performed Inspect And Test Ground Receptacle	Base	B1.3	2.00	01.02.22/81-23552	
2022-02-17	OM-BHK	UH-60A (GE-T700)	34	SPC	Performed Avionics/Altimeter/Transponder/NAV/ELT 12 M Inspection	Base	B2	9.00	01.02.22/81-23552	
2022-02-18	OM-BHK	UH-60A (GE-T700)	5	FUC	Performed Pitot-Static system test, Altimeter test	Base	B2	8.00	01.02.22/81-23552	
2022-02-21	OE-XMF	Sikorsky 269/300 (Lycoming)	5	SPC	Performed XPDR Test.	Base	B2	4.00	01.03.22/1140372	
2022-02-22	OM-BHK	UH-60A (GE-T700)	5	REP	Performed replacement of Digital Clock Battery.	Base	B2	2.00	01.02.22/81-23552	
2022-03-15	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed CRS after maintenance	SHOP	B1.2	1.00	01/2022/ZMI	Sk.CAO.009
2022-03-15	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed inspection of Engine	SHOP	B1.2	6.00	01/2022/ZMI	Si.CAO.009
2022-03-15	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed inspection of Propeller	SHOP	B1.2	2.00	01/2022/ZMI	SK.CAO.009
2022-03-15	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	REP	Performed replacement of Oil Filter	SHOP	B1.2	1.00	01/2022/ZMI	SK.CAO.009
2022-03-15	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	SER	Performed servicing of engine oil	SHOP	B1.2	0.50	01/2022/ZMI	SK.CAO.009
2022-03-15	OE-XMF	Sikorsky 269/300 (Lycoming)	5	FUC	Performed Magneto Timing according to Lyc. SB183A	Base	B1.4	4.00	01.03.22/1140372	
2022-03-16	OE-XMF	Sikorsky 269/300 (Lycoming)	5	SPC	Performed Capacity Test GILL Battery acc. GILL CMM Q01-1120	Base	B2	8.00	01.03.22/1140372	
2022-03-17	OM-BHK	UH-60A (GE-T700)	64	REP	Performed replacement T/R Spring capsule Assy.	Base	B1.3	9.99	01.02.22/81-23552	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-03-18	OM-BHK	UH-60A (GE-T700)	5	SPC	Performed Ultrasonic test inspection of the M/R hub spindle.	Base	B1.3	9.99	01.02.22/81-23552	
2022-03-20	OE-XMF	Sikorsky 269/300 (Lycoming)	5	SPC	Performed Pitot-Static system test, Altimeter test	Base	B2	8.00	01.03.22/1140372	
2022-03-21	OM-BHK	UH-60A (GE-T700)	49	REP	Performed exchange fuel control unit.	Base	B1.3	4.00	01.02.22/81-23552	
2022-03-22	OE-XMF	Sikorsky 269/300 (Lycoming)	5	SPC	Performed Compass Swing	Base	B2	6.00	01.03.22/1140372	
2022-03-23	OM-CBS	Viper SD-4 (Rotax)	5	GVI	Performed inspection of the engine.	SHOP	B1.2	4.00	01/2022/CBS	SK.CAO.009
2022-03-23	OM-CBS	Viper SD-4 (Rotax)	5	GVI	Performed inspection of the propeller.	SHOP	B1.2	2.00	01/2022/CBS	SK.CAO.009
2022-03-23	OM-CBS	Viper SD-4 (Rotax)	5	SER	Performed servicing of engine with oil.	SHOP	B1.2	1.00	01/2022/CBS	SK.CAO.009
2022-03-23	OM-CBS	Viper SD-4 (Rotax)	5	REP	Performed replacement of engine oil filter.	SHOP	B1.2	1.00	01/2022/CBS	SK.CAO.009
2022-03-23	OM-CBS	Viper SD-4 (Rotax)	5	FUC	Performed carburetors synchronization	SHOP	B1.2	1.00	01/2022/CBS	SK.CAO.009
2022-03-23	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	REM	Performed Removal of engine ROTAX 912 ULS2	Base	B3	9.99	01/2022/FFL	
2022-03-23	OE-XMF	Sikorsky 269/300 (Lycoming)	5	DUP	Performed Double Inspection After Maintenance.	Base	B1.4	8.00	01.03.22/1140372	
2022-03-24	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	INS	Performed Installation of engine ROTAX 912 ULS2	Base	B3	9.99	01/2022/FFL	
2022-03-25	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	DVI	Performed 400 H Engine inspection	Base	B3	6.00	01/2022/FFL	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-03-25	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	SER	Performed servicing of engine with oil.	Base	B3	1.00	01/2022/FFL	
2022-03-27	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	REM	Performed inspection of the propeller.	Base	B3	3.00	01/2022/FFL	
2022-03-29	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 25H inspection of Airframe	Base	B1.4	3.00	WO 01.03.22/S1928	
2022-03-29	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 50H inspection of Airframe	Base	B1.4	4.00	WO 01.03.22/S1928	
2022-03-29	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 50H inspection of Engine	Base	B1.4	3.00	WO 01.03.22/S1928	
2022-03-30	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed SB SD4-02-2020	Base	B3	3.00	01/2022/FFL	
2022-03-30	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 100H inspection of Airframe	Base	B1.4	6.00	WO 01.03.22/S1928	
2022-03-30	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 200H inspection of Airframe	Base	B1.4	4.00	WO 01.03.22/S1928	
2022-03-31	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 12M / Annual inspection of Airframe	Base	B1.4	8.00	WO 01.03.22/S1928	
2022-03-31	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 100H inspection of Engine	Base	B1.4	6.00	WO 01.03.22/S1928	
2022-03-31	OM-GGB	Sikorsky 269/300 (Lycoming)	4	OPC	Performed Fire Extinguisher Wighting	Base	B1.4	2.00	WO 01.03.22/S1928	
2022-04-01	OM-KAB	Cessna 172/F172 (Lycoming)	5	DVI	Performed SID operation 1, 2	Base	B3	8.00	01/2022/KAB	
2022-04-01	OM-GGB	Sikorsky 269/300 (Lycoming)	4	IND	Performed 12M avionics inspection of Altimeter, Pitot-Static System, XPDR, ELT, Battery	Base	B2	8.00	WO 01.03.22/S1928	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-04-02	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 200 H Inspection of the airframe	Base	B3	8.00	01/2022/KAB	
2022-04-04	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 200 H inspection of the Engine	Base	B3	8.00	01/2022/KAB	
2022-04-04	OM-GGB	Sikorsky 269/300 (Lycoming)	5	MOD	Performed Service Bulletin AD US 2015-23-01, US 2015-19-07, SB 480F	Base	B1.4	6.00	WO 01.03.22/S1928	
2022-04-04	OM-GGB	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	4.00	WO 01.03.22/S1928	
2022-04-05	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed Annual inspection of the Aircraft	Base	B3	8.00	01/2022/KAB	
2022-04-06	OM-EAS	Sikorsky 269/300 (Lycoming)	5	SPC	Performed special check of TQ of main rotor retention nut and droop stop retainer nut at first 10 Hrs of operation.	Base	B1.4	4.00	WO 01.04.22/0283	
2022-04-06	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed SID No. 25,26,27	Base	B3	8.00	01/2022/KAB	
2022-04-07	OM-KAB	Cessna 172/F172 (Lycoming)	5	ADJ	Performed Magnetic Compass Kalibration	Base	B3	3.00	01/2024/KAB	
2022-04-07	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed Release to Service after Inspection	Base	B3	3.00	01/2024/KAB	
2022-04-28	OK-HSO	MD Heli 369 (RR250)	5	REP	Performed exchange of Indicator el. tachometer P/N 369D24518	Base	B2	6.00	03.04.22/0200 E	
2022-05-04	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	FUC	Performed carburetors synchronization	Base	B3	3.00	01/2022/FFL	
2022-05-05	OM-HCY	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 25 Hr Inspection of Airframe	Base	B1.4	3.00	01.05.22/0288	
2022-05-05	OM-HCY	Sikorsky 269/300 (Lycoming)	5	SER	Performed 25 Hr Lubrication.	Base	B1.4	2.00	01.05.22/0288	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-05-05	OM-HCY	Sikorsky 269/300 (Lycoming)	5	SER	Performed 25 Hr Lubrication.	Base	B1.4	2.00	01.05.22/0288	
2022-05-06	OM-HCY	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 50/100 Hrs Inspection of Airframe	Base	B1.4	8.00	01.05.22/0288	
2022-05-08	OM-HCY	Sikorsky 269/300 (Lycoming)	5	REP	Performed replacement of Engine Oil Filter.	Base	B1.4	2.00	01.05.22/0288	
2022-05-09	OM-HCY	Sikorsky 269/300 (Lycoming)	5	GVI	Performed SB 480F, AD 2015-23-01, AD US 2015-19-07	Base	B1.4	5.00	01.05.22/0288	
2022-05-09	OM-HCY	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	3.00	01.05.22/0288	
2022-05-12	OK-EAI	MD Heli 369 (RR250)	5	GVI	Performed 35 Hrs / 200 TE M/R Blade Root Fittings Inspection.	Base	B1.3	3.00	03.05.22/0392 E	
2022-05-12	OK-EAI	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	03.05.22/0392 E	
2022-05-16	OE-XRN	Sikorsky 269/300 (Lycoming)	5	GVI	Performed Daily/25/50/100/150 Hrs Inspection of Airframe.	Base	B1.4	8.00	01.05.22/S1544	
2022-05-16	OE-XRN	Sikorsky 269/300 (Lycoming)	5	SER	Performed 25/50/100 Hrs Lubrication	Base	B1.4	4.00	01.05.22/S1544	
2022-05-17	OE-XRN	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 600 Hrs/24 M Thrust Bearing Lubrication, 1200 Hrs/24 M T/R Swashplate Lubrication, 1200 Hrs/24 M Shwashplate Bearing Lubrication.	Base	B1.4	6.00	01.05.22/S1544	
2022-05-17	OK-HSO	MD Heli 369 (RR250)	5	INS	Performed installation M/R Blades P/N 500P2100-105	Base	B1.3	3.00	03.04.22/0200 E	
2022-05-17	OK-HSO	MD Heli 369 (RR250)	5	DVI	Performed 35 Hrs / 200 TE M/R Blade Root Fittings Inspection.	Base	B1.3	3.00	03.04.22/0200 E	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-05-17	OE-XRN	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 50/100 Hrs Inspection of Engine	Base	B1.4	6.00	01.05.22/S1544	
2022-05-18	OE-XRN	Sikorsky 269/300 (Lycoming)	5	GVI	Performed SB 480F, AD 2015-23-01, AD US 2015-19-07	Base	B1.4	5.00	01.05.22/S1544	
2022-05-18	OE-XRN	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 12 M exchange of T/R GBX, M/R GBX Oil.	Base	B1.4	4.00	01.05.22/S1544	
2022-05-18	OK-PKS	MD Heli 369 (RR250)	5	GVI	Performed 35 Hrs / 200 TE M/R Blade Root Fittings Inspection.	Base	B1.3	3.00	02.05.22/0191E	
2022-05-18	OK-PKS	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	02.05.22/0191E	
2022-05-18	OK-HSO	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	3.00	03.04.22/0200 E	
2022-05-19	OM-GGB	Sikorsky 269/300 (Lycoming)	5	TBSH	Performed troubleshooting of Longitude Trimmer	Base	B2	8.00	WO 02.05.22/S1928	
2022-05-19	OM-GGB	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	3.00	WO 02.05.22/S1928	
2022-05-20	OE-XRN	Sikorsky 269/300 (Lycoming)	5	GVI	Performed Fire Extinguisher Inspection and weighting. Performed SB NI83.3 - T/R Blades Leading Edge Insp.	Base	B1.4	4.00	01.05.22/S1544	
2022-05-23	OE-XRN	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	4.00	01.05.22/S1544	
2022-05-24	OM-EAS	Sikorsky 269/300 (Lycoming)	5	SER	Performed 6M/400 Hrs Battery Gill Capacity Check.	Base	B2	8.00	WO 01.05.22/0283	
2022-05-24	OE-XMF	Sikorsky 269/300 (Lycoming)	5	GVI	Performed Daily/25/50/100/150 Hrs Inspection of Airframe.	Base	B1.4	8.00	01.05.22/114037 2	
2022-05-24	OE-XMF	Sikorsky 269/300 (Lycoming)	5	GVI	Performed AD 2017-14-06, AD-78-02-02, AD 89-20-03R1, AD 95-03-12	Base	B1.4	5.00	01.05.22/114037 2	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-05-25	OM-EAS	Sikorsky 269/300 (Lycoming)	5	FUC	Performed 12M avionics inspection - Altimeter, Pitot Static, XPDR, NAV-COM, Compass Swing, ELT	Base	B2	8.00	WO 01.05.22/0283	
2022-05-25	OE-XMF	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 50/100 Hrs Inspection of Engine	Base	B1.4	6.00	01.05.22/114037 2	
2022-05-25	OE-XMF	Sikorsky 269/300 (Lycoming)	5	REM	Performed SB480 - Oil and Filter Change.	Base	B1.4	2.00	01.05.22/114037 2	
2022-05-25	OE-XMF	Sikorsky 269/300 (Lycoming)	5	FUC	Performed Magneto Timing according to Lyc. SB183A	Base	B1.4	2.00	01.05.22/114037 2	
2022-05-25	OE-XMF	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	2.00	01.05.22/114037 2	
2022-05-26	OM-EAS	Sikorsky 269/300 (Lycoming)	5	SPC	Performed 12M Fire Extinguisher weighting	Base	B1.4	2.00	WO 01.05.22/0283	
2022-05-30	OM-EAS	Sikorsky 269/300 (Lycoming)	5	INS	Performed installation of M/R Blades.	Base	B1.4	4.00	WO 01.05.22/0283	
2022-05-30	OM-EAS	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service after maintenance.	Base	B1.4	4.00	WO 01.05.22/0283	
2022-05-30	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100 H Inspection of the Airframe, Engine and Propeller	Base	B3	8.00	02/2022/FFL	
2022-05-30	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	REP	Performed Replacement of MLG tyre	Base	B3	2.00	02/2022/FFL	
2022-06-01	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	REP	Performed Replacement of left Shock Cord ring.	Base	B3	3.00	02/2022/FFL	
2022-06-01	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed Release to service.	Base	B3	3.00	02/2022/FFL	
2022-06-09	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed 50 H Inspection of the engine, airframe and propeller.	Base	B3	6.00	02/2022/PAC	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-06-09	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SID No.2	Base	B3	2.00	02/2022/PAC	
2022-06-09	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SID No.2	Base	B3	2.00	02/2022/PAC	
2022-06-09	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SID No.2	Base	B3	2.00	02/2022/PAC	
2022-06-09	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Release to service after Inspection	Base	B3	3.00	02/2022/PAC	
2022-06-13	OM-BHK	UH-60A (GE-T700)	5	CRS	Released the aircraft for service	Base	B1.3	9.99	01.02.22/81-23552	
2022-06-14	OE-XMF	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 25 Hr Inspection of Airframe	Base	B1.4	3.00	02.06.22/1140372	
2022-06-14	OE-XMF	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	2.00	02.06.22/1140372	
2022-06-30	OK-HSO	MD Heli 369 (RR250)	25	REP	Performed replacement of ELT Battery Kit 200.	Base	B2	2.00	02.06.22/0200E	
2022-06-30	OK-HSO	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	02.06.22/0200E	
2022-07-08	OM-EAS	Sikorsky 269/300 (Lycoming)	4	GVI	Performed 25H inspection of Airframe	Base	B1.4	3.00	WO 01.07.22/0288	
2022-07-08	OM-EAS	Sikorsky 269/300 (Lycoming)	4	CRS	Released the aircraft for service	Base	B1.4	2.00	WO 01.07.22/0288	
2022-07-08	OM-HCY	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 25 Hr Inspection of Airframe	Base	B1.4	2.00	01.07.22/0288	
2022-07-08	OM-HCY	Sikorsky 269/300 (Lycoming)	5	SER	Performed 25 Hr Lubrication.	Base	B1.4	2.00	01.07.22/0288	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-07-08	OM-HCY	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	2.00	01.07.22/0288	
2022-07-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100/200 Hrs Engine Inspection	Base	B3	6.00	03/2022/FFL	
2022-07-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100 Hrs Propeller Inspection	Base	B3	3.00	03/2022/FFL	
2022-07-21	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	SER	Performed servicing of Engine With Oil.	Base	B3	2.00	03/2022/FFL	
2022-07-22	OK-HSO	MD Heli 369 (RR250)	5	DUP	Performed Double Inspection	Base	B1.3	9.99	01.07.22/0200 E	
2022-07-25	OM-CBS	Viper SD-4 (Rotax)	5	GVI	Performed servicing of Engine With Oil.	Base	B3	2.00	02/2022/CBS	
2022-07-25	OM-CBS	Viper SD-4 (Rotax)	5	GVI	Performed 100 Hrs Engine Inspection.	Base	B3	6.00	02/2022/CBS	
2022-07-26	OM-CBS	Viper SD-4 (Rotax)	5	OPC	Performed Magnetic Compass Calibration	Base	B3	4.00	02/2022/CBS	
2022-07-26	OM-CBS	Viper SD-4 (Rotax)	5	SPC	Performed Pitot-Static and Altimeter check.	Base	B3	3.00	02/2022/CBS	
2022-07-26	OM-CBS	Viper SD-4 (Rotax)	5	FUC	Performed Functional Check of ELT	Base	B2	2.00	02/2022/CBS	
2022-08-03	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 25H/50H inspection of Airframe	Base	B1.4	6.00	WO 02.08.22/S1928	
2022-08-03	OM-GGB	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 50H inspection of Engine	Base	B1.4	3.00	WO 02.08.22/S1928	
2022-08-03	OM-GGB	Sikorsky 269/300 (Lycoming)	5	MOD	Performed Service Bulletin 480F	Base	B1.4	1.00	WO 02.08.22/S1928	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-08-04	OM-GGB	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	3.00	WO 02.08.22/S1928	
2022-08-05	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed 100/200/400 H Engine Inspection	Base	B3	8.00	04/2022/ZMI	
2022-08-05	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	REP	Performed Replacement of spark plugs	Base	B3	2.00	04/2022/ZMI	
2022-08-06	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed 100/200 H Airframe and propeller inspection	Base	B3	7.00	04/2022/ZMI	
2022-08-06	OM-ZMI	Tomark Viper SD-4 RTC (Rotax)	5	GVI	Performed release to service after inspection	Base	B3	3.00	04/2022/ZMI	
2022-08-07	OM-HCY	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 50/100 Hrs Inspection of Engine	Base	B1.4	8.00	01.05.22/0288	
2022-08-18	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed 100 H Inspection of the Airframe, Engine and Propeller	Base	B3	8.00	05/2022/PAC	
2022-08-19	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed AD US-2011-10-09	Base	B3	1.00	05/2022/PAC	
2022-08-19	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed TCM MSB94-DB	Base	B3	2.00	05/2022/PAC	
2022-08-19	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SEB95-3 R1	Base	B3	2.00	05/2022/PAC	
2022-08-19	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Release to service after inspection	Base	B3	3.00	05/2022/PAC	
2022-08-23	OM-LKJ	Viper SD-4 (Rotax) RTC	5	GVI	Performed 100/200/400 H Engine Inspection	Base	B3	8.00	02/2022/LKJ	
2022-08-24	OM-LKJ	Viper SD-4 (Rotax) RTC	5	GVI	Performed 100/200 H Airframe and propeller inspection	Base	B3	6.00	02/2022/LKJ	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-08-24	OM-LKJ	Viper SD-4 (Rotax) RTC	5	SER	Performed Servicing of	Base	B3	1.00	02/2022/LKJ	
2022-08-24	OM-LKJ	Viper SD-4 (Rotax) RTC	5	REP	Performed Replacement of MLG tyres	Base	B3	3.00	02/2022/LKJ	
2022-08-24	OK-HSO	MD Heli 369 (RR250)	12	REP	Performed exchange Main Transmission Oil and Oil Filter.	Base	B1.3	6.00	01.08.22/0200 E	
2022-08-24	OK-HSO	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	01.08.22/0200 E	
2022-08-25	OM-LKJ	Viper SD-4 (Rotax) RTC	5	GVI	Performed carburetors synchronization	Base	B3	2.00	02/2022/LKJ	
2022-08-25	OM-LKJ	Viper SD-4 (Rotax) RTC	5	GVI	Performed Release to Service after Inspection	Base	B3	3.00	02/2022/LKJ	
2022-09-05	OK-HSO	MD Heli 369 (RR250)	63	TBSH	Performed T/S M/R XMSN Chip Detector acc. 63-25-10 CSP-HMI-2, Rev. 54 and CSP-HMI-3 acc. 95-00-00 Rev. 54 - found shortcut on wire to chip detector ground. Made repair of the broken wire.	Base	B2	2.00	01.09.22/0200 E	
2022-09-05	OK-HSO	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	1.00	01.09.22/0200 E	
2022-09-06	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed 50 H Inspection of the engine, airframe and propeller.	Base	B3	6.00	06/2022/PAC	
2022-09-07	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SID No.23	Base	B3	4.00	06/2022/PAC	
2022-09-07	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SEL-79-03	Base	B3	2.00	06/2022/PAC	
2022-09-07	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SEL-79-03	Base	B3	2.00	06/2022/PAC	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-09-07	OK-HSO	MD Heli 369 (RR250)	5	DVI	Performed 35 Hrs / 200 TE M/R Blade Root Fittings Inspection.	Base	B1.3	3.00	02.09.22/0200 E	
2022-09-08	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Release to Service after Inspection	Base	B3	3.00	06/2022/PAC	
2022-09-08	OK-HSO	MD Heli 369 (RR250)	5	RPR	Performed repair of Pitot-Static System.	Base	B2	8.00	02.09.22/0200 E	
2022-09-12	OK-HSO	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	02.09.22/0200 E	
2022-09-13	OK-PKS	MD Heli 369 (RR250)	5	REP	Performed replacement of ELT Battery Kit 200.	Base	B2	4.00	01.09.22/0191E	
2022-09-13	OK-PKS	MD Heli 369 (RR250)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	01.09.22/0191E	
2022-11-15	OM-BHK	UH-60A (GE-T700)	5	GVI	Performed 30 Day SLAB Battery inspection.	Base	B2	2.00	01.11.22/81-2335 2	
2022-11-15	OM-BHK	UH-60A (GE-T700)	5	GVI	Performed 30D/40 Hrs Lube.	Base	B1.3	4.00	01.11.22/81-2335 2	
2022-11-15	OM-BHK	UH-60A (GE-T700)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	01.11.22/81-2335 2	
2022-11-20	OM-BRE	Tecnam P92 (Rotax)	5	GVI	Performed Annual inspection of the Aircraft	Base	B3	8.00	CAMO-220025 4	
2022-11-21	OM-BRE	Tecnam P92 (Rotax)	5	GVI	Performed 100 Hrs Propeller Inspection	Base	B3	3.00	CAMO-220025 4	
2022-11-25	OM-BRE	Tecnam P92 (Rotax)	5	SPC	Performed Magnetic Compass Calibration	Base	B3	5.00	CAMO-220025 4	
2022-11-26	OM-BRE	Tecnam P92 (Rotax)	5	OPC	Performed Pitot-Static and Altimeter check.	Base	B3	5.00	CAMO-220025 4	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-12-01	OM-BRE	Tecnam P92 (Rotax)	5	FUC	Performed Fire extinguisher inspection	Base	B3	2.00	CAMO-2200254	
2022-12-02	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of Carburator Flange Assy	Base	B3	5.00	CAMO-2200254	
2022-12-03	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of Diapharm Carburator	Base	B3	3.00	CAMO-2200254	
2022-12-05	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of fuel hoses	Base	B3	9.00	CAMO-2200254	
2022-12-06	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of Fuel pump	Base	B3	3.00	CAMO-2200254	
2022-12-07	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of Gyro Air Filter	Base	B3	3.00	CAMO-2200254	
2022-12-08	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of Venting hose of carburators	Base	B3	3.00	CAMO-2200254	
2022-12-09	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of Rubber Hoses on compensating tubes	Base	B3	5.00	CAMO-2200254	
2022-12-10	OM-BRE	Tecnam P92 (Rotax)	5	GVI	Performed AD 2011-0092	Base	B3	4.00	CAMO-2200254	
2022-12-11	OM-BRE	Tecnam P92 (Rotax)	5	GVI	Performed SB 006-CS	Base	B3	4.00	CAMO-2200254	
2022-12-11	OM-BRE	Tecnam P92 (Rotax)	5	GVI	Performed SB 108-CS	Base	B3	3.00	CAMO-2200254	
2022-12-12	OM-BRE	Tecnam P92 (Rotax)	5	GVI	Performed 100/200 Hrs Engine Inspection	Base	B3	8.00	CAMO-2200254	
2022-12-13	OM-BRE	Tecnam P92 (Rotax)	5	REP	Performed Replacement of Shock Absorbers	Base	B3	8.00	CAMO-2200254	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2022-12-15	OE-XMF	Sikorsky 269/300 (Lycoming)	5	REP	Performed replacement Strobe Light P/N 06-190125	Base	B2	2.00	01.12.22/114037 2	
2023-01-23	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100/500 H Airframe inspection	Base	B3	8.00	01/2023/FFL	
2023-01-24	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100 Hrs Engine Inspection.	Base	B3	6.00	01/2023/FFL	
2023-01-24	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	REP	Performed Replacement of Main Battery Fuse	Base	B3	1.00	01/2023/FFL	
2023-01-25	OM-FFL	Tomark Viper SD4 RTC (Rotax)	5	GVI	Performed 100 Hrs Propeller Inspection	Base	B3	2.00	01/2023/FFL	
2023-01-26	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 50 H Inspection of the engine.	Base	B3	6.00	01/2023/KAB	
2023-01-27	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 50 Hrs Propeller Inspection	Base	B3	2.00	01/2023/KAB	
2023-01-27	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 50 H Airframe inspection	Base	B3	8.00	01/2023/KAB	
2023-01-28	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed servicing of engine with oil.	Base	B3	2.00	01/2023/KAB	
2023-01-30	OK-HSO	MD Heli 369 (RR250)	5	GVI	Performed SH401GL	Base	B1.3	3.00	23.01.05/0200E	
2023-01-31	OM-STA	Sikorsky 269/300 (Lycoming)	5	REM	Performed removal of main rotor blades.	Base	B1.4	2.00	23.01.01/S1815	
2023-04-13	OM-BHK	UH-60A (GE-T700)	22	TBSH	Performed T/S and replacing stabilator amplifier.	Base	B2	5.00	23.04.06/81-23 552	
2023-04-13	OM-BHK	UH-60A (GE-T700)	5	GVI	Performed 30 Day SLAB Battery inspection.	Base	B2	2.00	23.04.06/81-23 552	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2023-04-14	OM-BHK	UH-60A (GE-T700)	5	SER	Performed 30D/40 Hrs Lube.	Base	B1.3	3.00	23.04.06/81-23552	
2023-04-16	OM-BHK	UH-60A (GE-T700)	5	GVI	Performed Engine History recorder Reading	Base	B1.3	1.00	23.04.06/81-23552	
2023-04-17	OM-BHK	UH-60A (GE-T700)	5	CRS	Released the aircraft for service	Base	B1.3	3.00	23.04.06/81-23552	
2023-04-18	OM-BHB	UH-60A (GE-T700)	5	GVI	Performed 30 Day SLAB Battery inspection.	Base	B2	2.00	23.04.06/80-23495	
2023-04-18	OM-BHB	UH-60A (GE-T700)	5	SER	Performed 30D/40 Hrs Lube.	Base	B1.3	3.00	23.04.06/80-23495	
2023-04-18	OM-BHB	UH-60A (GE-T700)	5	DVI	Performed 90 Day Corrosion Inspection.	Base	B1.3	5.00	23.04.06/80-23495	
2023-04-18	OM-BHB	UH-60A (GE-T700)	5	CRS	Released the aircraft for service	Base	B1.3	2.00	23.04.06/80-23495	
2023-04-28	OE-XPS	Sikorsky 269/300 (Lycoming)	25	ADJ	Performed exchange and programming ELT.	Base	B2	3.00	23.04.01/S1640	
2023-05-04	OE-XMF	Sikorsky 269/300 (Lycoming)	24	TBSH	Performed T/S on faulty alternator.	Base	B2	8.00	23.05.09/114-0372	
2023-05-06	OE-XMF	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	3.00	23.05.09/114-0372	
2023-05-10	OE-XPS	Sikorsky 269/300 (Lycoming)	25	SPC	Performed Battery test on Garmin GI275 acc. to maintenance manual.	Base	B2	4.00	23.04.01/S1640	
2023-05-12	OE-XPS	Sikorsky 269/300 (Lycoming)	27	TBSH	Performed T/S on right grip pf the longitude trim - Found faulty 4-way switch. Performed exchange of the switch.	Base	B2	4.00	23.04.01/S1640	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2023-05-24	OM-STA	Sikorsky 269/300 (Lycoming)	5	REP	Performed Rmvd old callsign and installed new. Performed install national flag. Performed dmvd and install new fireproof sticker.	Base	B1.4	4.00	23.05.03/S1815	
2023-05-24	OM-STA	Sikorsky 269/300 (Lycoming)	5	ADJ	Performed recoding XPDR and ELT.	Base	B2	2.00	23.05.04/S1815	
2023-05-24	OM-STA	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	2.00	23.05.03/S1815	
2023-05-31	OM-KAB	Cessna 172/F172 (Lycoming)	5	SPC	Performed Magneto to Engine timing	Base	B3	3.00	02/2023/KAB	
2023-06-01	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed 50/100/200/400 H inspection on the engine	Base	B3	8.00	02/2023/KAB	
2023-06-02	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed servicing of engine with oil.	Base	B3	2.00	02/2023/KAB	
2023-06-03	OM-KAB	Cessna 172/F172 (Lycoming)	5	FUC	Performed Magnetic Compass Calibration	Base	B3	4.00	02/2023/KAB	
2023-06-04	OM-KAB	Cessna 172/F172 (Lycoming)	5	REP	Performed Replacement of bracket air filter element.	Base	B3	2.00	02/2023/KAB	
2023-06-14	OM-XBB	Agusta AB206 (RR 250)	5	SPC	Performed 12M Altimeter encoding check.	Base	B2	4.00	23.06.01/8604	
2023-06-15	OM-XBB	Agusta AB206 (RR 250)	5	SPC	Performed AC Battery deep cycle.	Base	B2	2.00	23.06.01/8604	
2023-06-19	OM-XBB	Agusta AB206 (RR 250)	5	SPC	Performed 12 M Avionics inspection (Altimeter, Pitot-Static, XPDR, Compass Swing, NAV-COM, ELT)	Base	B2	8.00	23.06.01/8604	
2023-06-26	OM-ARM	Sikorsky 269/300 (Lycoming)	5	INS	Performed install M/R blades	Base	B1.4	3.00	23.06.04/S1268	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2023-06-26	OM-ARM	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	2.00	23.06.04/S1268	
2023-06-26	OM-HCY	Sikorsky 269/300 (Lycoming)	5	INS	Performed install M/R blades	Base	B1.4	3.00	23.06.06/0288	
2023-06-27	OM-PKV	MD Heli 369 (RR250)	5	DVI	Performed SB369F-125 - Inspection of the horizontal stabilizer attach lug fittings.	Base	B1.3	4.00	23.06.03/0317F	
2023-07-05	OM-BHB	UH-60A (GE-T700)	49	CLE	Performed Engine compressor cleaning.	Base	B1.3	5.00	23.07.10/80-23495	
2023-07-05	OM-BHB	UH-60A (GE-T700)	65	REP	Performed exchange of the spring of the droop stops.	Base	B1.3	2.00	23.07.10/80-23495	
2023-07-10	OM-HCA	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 25 Hr Inspection of Airframe. Performed 25 Hr lubrication.	Base	B1.4	3.00	23.07.06/0214	
2023-07-10	OM-HCA	Sikorsky 269/300 (Lycoming)	5	GVI	Performed 150 Hr Inspection. Performed exchange coupling drive shaft.	Base	B1.4	2.00	23.07.06/0214	
2023-07-10	OM-HCA	Sikorsky 269/300 (Lycoming)	5	SPC	Performed TQ check of T/R blade retaining nut after 25 Hr.	Base	B1.4	1.00	23.07.06/0214	
2023-07-10	OM-HCA	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	2.00	23.07.06/0214	
2023-07-12	OM-HCY	Sikorsky 269/300 (Lycoming)	24	TBSH	Performed T/S - Alternator. Performed exchange of the alternator.	Base	B1.4	4.00	23.07.08/0288	
2023-07-12	OM-HCY	Sikorsky 269/300 (Lycoming)	5	CRS	Released the aircraft for service	Base	B1.4	2.00	23.07.08/0288	
2023-07-19	OK-HSO	MD Heli 369 (RR250)	5	SPC	Performed 12 M Avionics inspection (Altimeter, Pitot-Static, XPDR, Compass Swing, NAV-COM, ELT)	Base	B2	8.00	23.07.05/0200E	
2023-07-19	OK-HSO	MD Heli 369 (RR250)	5	SUP	Supervised lead acid inspection	Base	B2	1.00	23.07.05/0200E	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2023-07-20	OK-HSO	MD Heli 369 (RR250)	5	DUP	Performed double inspection	Base	B1.3	4.00	23.07.05/0200 E	
2023-07-20	OM-XBB	Agusta AB206 (RR 250)	5	GVI	Performed 100/300 Hrs Engine Inspection	Base	B1.3	8.00	23.06.01/8604	
2023-07-20	OM-FFL	Tomark Viper SD4 RTC (Rotax)	53	SPC	Performed Special Check of Pitot-Static System and Altimeter.	Base	B2	3.00	04/2023/FFL	
2023-07-20	OM-FFL	Tomark Viper SD4 RTC (Rotax)	53	SPC	Performed Compass Compensation	Base	B2	4.00	04/2023/FFL	
2023-07-21	OM-XBB	Agusta AB206 (RR 250)	5	REP	Performed 600 Hr/12M Engine Oil change include facet filter change.	Base	B1.3	4.00	23.06.01/8604	
2023-07-21	OM-XBB	Agusta AB206 (RR 250)	5	REP	Performed replacement stickers and data plates.	Base	B1.3	4.00	23.06.01/8604	
2023-07-28	OM-XBB	Agusta AB206 (RR 250)	5	SER	Performed exchange hydraulic oil.	Base	B1.3	3.00	23.06.01/8604	
2023-08-15	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Fuel Tanks and Bladder	Base	B3	1.00	03/2023/PAC	
2023-08-15	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Governor Inspection	Base	B3	1.00	03/2023/PAC	
2023-08-15	OM-PAC	Cessna 182/F182 Series (Continental)	5	REP	Performed Replacement of air filter.	Base	B3	2.00	03/2023/PAC	
2023-08-15	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed hose fuel line inspection	Base	B3	2.00	03/2023/PAC	
2023-08-15	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Fuel vent inspection No. 28-20-02	Base	B3	2.00	03/2023/PAC	
2023-08-15	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Fuel Reservoir and fuel tank inspection No. 28-30-01	Base	B3	2.00	03/2023/PAC	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Fuel Gaging System Inspection	Base	B3	1.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	REP	Performed Replacement of hydraulic Hoses.	Base	B3	3.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Flap Inspection	Base	B3	1.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Cowl flap inspection	Base	B3	1.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Trim Tab inspection	Base	B3	1.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	SPC	Performed Magnetic Compass Calibration	Base	B3	2.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	SPC	Performed Pitot-Static and Altimeter check.	Base	B3	2.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed CPCP task 2 Wing Structure Insp	Base	B3	2.00	03/2023/PAC	
2023-08-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SEB95-3 R1	Base	B3	1.00	03/2023/PAC	
2023-10-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Engine control and linkage inspection	Base	B3	1.00	05/2023/PAC	
2023-10-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Induction filter cleaning.	Base	B3	1.00	05/2023/PAC	
2023-10-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Alternator inspection	Base	B3	1.00	05/2023/PAC	
2023-10-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed TCM MSB94-8D	Base	B3	2.00	05/2023/PAC	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2023-10-16	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SEB95-3 R1	Base	B3	1.00	05/2023/PAC	
2023-10-17	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed Marvel-Shraber SB-17	Base	B3	1.00	05/2023/PAC	
2023-10-17	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed EASA US-2011-10-09	Base	B3	1.00	05/2023/PAC	
2023-10-17	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed EASA US-2008-10-02	Base	B3	1.00	05/2023/PAC	
2023-10-17	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed SEL-79-03	Base	B3	1.00	05/2023/PAC	
2023-10-17	OM-PAC	Cessna 182/F182 Series (Continental)	5	GVI	Performed EASA 2008-0078R1	Base	B3	2.00	05/2023/PAC	
2023-10-19	OM-NVF	Viper SD-4 (Rotax)	5	GVI	Performed SB SD4-02-2020	Base	B3	3.00	06/2023/NVF	
2023-10-19	OM-NVF	Viper SD-4 (Rotax)	5	GVI	Performed 100 Hrs Engine Inspection.	Base	B3	3.00	06/2023/NVF	
2023-10-19	OM-NVF	Viper SD-4 (Rotax)	5	GVI	Performed 100 Hrs Propeller Inspection	Base	B3	2.00	06/2023/NVF	
2023-10-19	OM-NVF	Viper SD-4 (Rotax)	5	GVI	Performed 100 H Inspection of the Airframe.	Base	B3	5.00	06/2023/NVF	
2023-10-24	OM-VOS	Cessna 150/F150 (Continental)	5	DVI	Performed Detailed Visual Inspection of Rudder Horn For Corrosion. SEL-27-02	Base	B3	5.00	01/2023/VOS	
2023-10-25	OM-VOS	Cessna 150/F150 (Continental)	5	GVI	Performed General Visual Inspection of the spinner	Base	B3	1.00	01/2023/VOS	
2023-10-25	OM-VOS	Cessna 150/F150 (Continental)	5	GVI	Performed General Visual Inspection of Blades of the Propeller	Base	B3	2.00	01/2023/VOS	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2023-10-26	OM-VOS	Cessna 150/F150 (Continental)	5	GVI	Performed General Visual Inspection of Engine Baffles	Base	B3	1.00	01/2023/VOS	
2023-10-26	OM-VOS	Cessna 150/F150 (Continental)	5	GVI	Performed General Visual Inspection of Hose, Metal lines and fittings.	Base	B3	2.00	01/2023/VOS	
2023-10-30	OM-VOS	Cessna 150/F150 (Continental)	5	GVI	Performed General Visual Inspection of Spark plugs. Performed removing, cleaning and gapping spark plugs.	Base	B3	2.00	01/2023/VOS	
2023-10-30	OM-VOS	Cessna 150/F150 (Continental)	5	GVI	Performed General Visual Inspection of Vacuum relief filter (cabin)	Base	B3	1.00	01/2023/VOS	
2023-11-10	OM-NFR	Viper SD-4 (Rotax)	5	GVI	Performed SB SD4-02-2020	Base	B3	2.00	04/2023/NFR	
2023-11-10	OM-NFR	Viper SD-4 (Rotax)	5	GVI	Performed 100/200/600 H Engine Inspection	Base	B3	6.00	04/2023/NFR	
2023-11-10	OM-NFR	Viper SD-4 (Rotax)	5	GVI	Performed carburetors synchronization	Base	B3	2.00	04/2023/NFR	
2023-12-01	OM-VOS	Cessna 150/F150 (Continental)	5	GVI	Performed General Visual Inspection of Cabin heat valves, doors and controls.	Base	B3	4.00	01/2023/VOS	
2024-01-14	OM-TKM	Tecnam P92 (Rotax)	5	GVI	Performed check all SB, SI complied with engine	Base	B3	1.00	01/2024/TKM	
2024-01-14	OM-TKM	Tecnam P92 (Rotax)	5	SPC	Performed Special Check of compression by differential pressure method.	Base	B3	3.00	01/2024/TKM	
2024-01-15	OM-TKM	Tecnam P92 (Rotax)	5	CLE	Performed remove and check all spark plugs.	Base	B3	2.00	01/2024/TKM	
2024-01-15	OM-TKM	Tecnam P92 (Rotax)	5	DVI	Performed remove and check magnetic plug.	Base	B1.2	1.00	01/2024/TKM	
2024-01-15	OM-TKM	Tecnam P92 (Rotax)	5	SER	Performed Servicing of engine with oil. Performed exchange oil filter.	Base	B1.2	2.00	01/2024/TKM	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2024-01-16	OM-TKM	Tecnam P92 (Rotax)	5	GVI	Performed visual check general condition of wrap-around skin and rivets.	Base	B1.2	2.00	01/2024/TKM	
2024-01-16	OM-TKM	Tecnam P92 (Rotax)	5	GVI	Performed check seat rails and stops and safety belt attachments.	Base	B1.2	1.00	01/2024/TKM	
2024-01-17	OM-TKM	Tecnam P92 (Rotax)	5	GVI	Performed check integrity and general condition of transparent surfaces and doors.	Base	B1.2	3.00	01/2024/TKM	
2024-01-17	OM-TKM	Tecnam P92 (Rotax)	5	SER	Performed Servicing of brake system	Base	B1.2	2.00	01/2024/TKM	
2024-01-17	OM-TKM	Tecnam P92 (Rotax)	5	GVI	Performed inspect support truss for gear strut and attachment hinges, orioer movement of steering levers and pushrods.	Base	B1.2	3.00	01/2024/TKM	
2024-01-18	OM-TKM	Tecnam P92 (Rotax)	5	GVI	Performed General Visual Inspection of electric pump connections, mount and engine silent blocks.	Base	B1.2	1.00	01/2024/TKM	
2024-01-19	OM-TKM	Tecnam P92 (Rotax)	5	FUC	Performed Pitot-static system inspection and test altimeter.	Base	B2	6.00	01/2024/TKM	
2024-01-20	OM-TKM	Tecnam P92 (Rotax)	5	SPC	Performed Magnetic compass swing	Base	B2	5.00	01/2024/TKM	
2024-02-01	OM-KAB	Cessna 172/F172 (Lycoming)	0	GVI	Performed General Visual Inspection of blade propellers.	Base	B3	2.00	01/2024/KAB	
2024-02-01	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed Inspection of engine oil screen, filter cap, dip-stick, drain plug.	Base	B3	2.00	01/2024/KAB	
2024-02-01	OM-KAB	Cessna 172/F172 (Lycoming)	5	GVI	Performed General Visual Inspection of engine controls, engine cowlng.	Base	B3	1.00	01/2024/KAB	
2024-02-02	OM-KAB	Cessna 172/F172 (Lycoming)	0	GVI	Performed General Visual Inspection of fuel shutoff valve and placards, nose gear wheel, torque links, steering tubes, boots and fairing.	Base	B3	1.00	01/2024/KAB	

I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature _____

AIRCRAFT MAINTENANCE ENGINEER EXPERIENCE

Name: **Patrik Gonda**

Date	A/C REG or SER No	Aircraft Type (engine)	ATA	Task Type	Task Description	Work Type	Licence Category	Duration (hrs)	Workorder	Verified By
2024-02-02	OM-KAB	Cessna 172/F172 (Lycoming)	0	GVI	Performed General Visual Inspection of Instrument and markings, defrosting, heating and ventilating systems and controls.	Base	B3	2.00	01/2024/KAB	
2024-02-02	OM-KAB	Cessna 172/F172 (Lycoming)	0	GVI	Performed General Visual Inspection of seat stops, seat rails, upholstery, structure and mounting for cracks	Base	B3	2.00	01/2024/KAB	
2024-03-03	OM-AJA	Viper SD-4 (Rotax)	5	GVI	Performed check all fuel system connections.	Base	B3	2.00	01/2024/AJA	
2024-03-03	OM-AJA	Viper SD-4 (Rotax)	5	GVI	Performed check fuel pressure indication reads.	Base	B3	2.00	01/2024/AJA	
2024-03-03	OM-AJA	Viper SD-4 (Rotax)	5	GVI	Performed fuel selector valve function.	Base	B3	2.00	01/2024/AJA	
2024-03-04	OM-AJA	Viper SD-4 (Rotax)	5	GVI	Performed remove drain valve and inspect for sediments.	Base	B3	3.00	01/2024/AJA	
2024-03-04	OM-AJA	Viper SD-4 (Rotax)	5	GVI	Performed Pitot-Static system leaks.	Base	B3	3.00	01/2024/AJA	



I hereby declare, above work has been carried out correctly and IAW the appropriate technical documentation.

Owner's signature_____