Sensors and Actuators CM0506 – Small Embedded Systems

Dr Alun Moon

Department of Computer and Information Science

Lecture 8

What are They?

Actuators

- Change something in the environment
- Under computer control
- Provide feedback to a process to maintain the predetermined set-points
- Convert electrical signals into physical changes

What are They?

Sensors

- Allow sampling of an environment or process variable
- Convert changes in the process under control into electrical signals

Sensors

Physical quantities measurable:

- Temperature
- Pressure
- Distance/displacement
- Velocity
- Acceleration
- Fluid flow
- Light Intensity
- Voltage
- Current
- Resistance
- Force
- Liquid level
- Torque
- pH
- + many more...
 Dr Alun Moon (Department of Compute)

Switches

- Binary devices
- Normally closed/normally open
- Momentary closure
- Position closure of contacts confirm position of mechanical parts
- Human hands keyboards, etc.
- Conditions pressure, temperature (thermostats)
- Compressed air switches
- Hydraulics

Pressure measurement

- Pressure bends an elastic element such as a diaphragm, tube, bellows or piston
- The displacement in turn moves a needle, change an electrical impedance or resistance
- Piezoelectric pressure sensors
- Rapid changes in pressure are difficult to measure why?
- High pressure transducers are costly

Temperature

- Expansion of solids, liquids or gases
- Pressure or movement changes can be measured
- Thermocouples junction between dissimilar metals generate small voltages
- Other solid state devices are available such as thermistors

Actuators

Relays switch large electrical loads using a small electrical input Solenoids Motion of an iron core in a coil does mechanical work Motors perform mechanical work

- rotation or other through levers
- DC and Stepper

Relays

- Power switching devices
- Were used in large numbers by PO
- Small current and voltage inputs
- Allow switching of large currents/voltages
- Switch AC or DC
- Multiple contacts changeover
- Electrical isolation
- Reed relays are sealed in a glass tube
- Opto-isolators solid state devices electrical isolation of components

Motors

- DC motors are employed very widely in industry, appliances, automobiles, etc.
- Used to provide continuous rotation or no rotation position
- Inexpensive and efficient
- Can use PWM for speed control noisy
- Geared for more torque

Stepper Motors

- Digitally controlled
- Discrete positioning
- Useful where accurate control is required
- Lower torque than DC
- Pulses cause the motor to rotate in steps perhaps 1.8deg per pulse
- Positional feedback is not required (unless the motor slips)

Accuracy

- Accuracy the total of all deviations between a measured value and the actual value sum of non-linearity, repeatability and hysteresis.
- Non-linearity the maximum difference in measured value or output from a straight line between calibration points
- Repeatability the max difference in a measured value or output when a set point is approached multiple times from above or below
 - Hysteresis the max difference in measured value or output when a set value is approached from above, and then below the value.

Signal Conditioning

- Usually some manipulation of the signals is required between a computer interface and sensors/actuators
- Change in power power levels in computer interfaces are low
- Voltage levels e.g., 0-5 v to -2.5-2.5
- Current to voltage and voltage to current
- Requires use of operational amplifiers, etc.

Part 1

Ananlogue to Digital Conversion

ADC

Data acquisition equipment

- receives an analogue signal
- 2 it is converted to a voltage
- in order to transfer to the computer/processor that voltage needs to be digitised by an Analogue-to-Digital Converter (ADC)
- An Analogue-to-Digital Converter (ADC) is an electronic circuit which takes as input an analog signal (usually a voltage) and produces a corresponding digital number at the output
- ADCs (and DACs) are available as modules, integrated circuits or fully integrated inside other components such as microcontrollers