```
0001
                     0002
0003
                     * PDS V3N CASSETTE LCAD & SAVE
0004
0005
                     * V3N HAS BEEN MODIFIED TO
                     * INCLUDE CASSETTE LOAD & SAVE
0006
0007
                     * ROUTINES. OPERATIONS ON THE
                     * BUFFER POINTERS (CASSETTE <->
8000
                     * EDITOR) ARE ALSO PROVIDED.
0009
0010
0011
                     * REFER TO THE MANUAL FOR
                     * ADDITIONAL INFORMATION.
0012
0013
0014
                     0015
0016
      0200
                     EDITOR EQU
                                    $FC67
                                             PDS EDITOR
                     *EDITOR EQU $F400 PIE EDITOR
0017
0018
                     REEDIT EQU
      0200
                                    $FC6F
                                             PDS EDITOR
                     *REEDIT EQU $F402 PIE EDITOR
0019
0020
0021
                     * OVERLAY CURRENT EXEC
0022
      0200
                                    $FC14
                             ORG
0023
0024
                     EXEC
      FC14 8D 21
                              BSR
                                    HOME
                                             CLEAR SCREEN
0025
      FC16 8D 25
                              BSR
                                    CLEAR
0026
                     EXEC1
0027
      FC18 8D 73
                                    CR1
                                              CRLF
                              ESR
0028
      FC1A BD FE71
                              JSR
                                    INPCHR
                                             GET/DISPLAY CHAR
0029
      FC1D 81 01
                                              CTRL-A
                              CMPA
                                    =1
      FC1F 26 03
FC21 7E E800
0030
                              ENE
                                    EXEC2
0031
                             JMP
                                    $E800
                                             JMP FOR ADDT L CMNDS
0032
0033
      FC24 81 05
                     EXEC2
                              CMPA
                                    =5
                                              CTRL-E
0034
0035
0036
      FC26 26 03
                              BNE
                                    EXEC3
                     * JSR USED TO ALLOW JUMP TO PIE
0037
      FC28 BD FC67
                             JSR
                                    EDITOR
                                             EDIT NEW FILE
                     * NOTE: ON RETURN, BOTH FDITOR * CALLS FALL THRU TO DEBUGGER
0038
0039
0040
      FC2B 81 12
                     EXEC3
0041
                                    =$12
                                              CTRL-R
                              CMPA
0042
      FC2D 26 03
                              ENE
                                    FXEC4
      FC2F BD FC6F
0043
                              JSR
                                    REEDIT
                                             RE-EDIT OLD FILE
0044
0045
      FC32 81 54
                     EXEC4
                              CMPA = T
                                              SET UP FOR NEXT
      FC34 7E FDA1
0046
                                    $FDA1
                                              COMMAND TEST
                              \mathsf{JMP}
0047
      FC37
0048
                     HOME
                             EQU
                                    $FC37
      FC37
FC37
FC37
0049
0050
                                    $FC3D
                     CLEAR
                             EQU
                              EQU
                                    $FC8D
                     CR1
0051
                             EQU
                     INPCHR
                                    $FE71
```

```
0200
                                 EQU
                                        $C
0001
                        BUFADR
                                 EQU
                                        $E
0002
       0200
                        BUFEND
                                        $1D
0003
       0200
                                 EQU
                        CSRP+1
                                 EQU
                                        $20
0004
       0200
                       BUFFLO
                                        $22
0005
                        BUFFHI
       0200
                                 EQU
0006
      0200
                                         $24
                        SCNPTR
                                 EQU
                                        $33
$34
0007
       0200
                                 EQU
                        BLKNAM
3000
       0200
                                 EQU
                        BLKN+1
0009
      0200
                       ACIANO
                                 EQU
0010
       0200
                        ACIA+1
                                 EQU
                                        $39
                                        $3A
$3C
$3D
0011
       C200
                       NOPRNT
                                 EQU
0012
       0200
                        BFRPTR
                                 EQU
0013
      0200
                                 EQU
                        BFRP+1
0014
                                         $3E
       C200
                        BFRSZE
                                 EQU
0015
0016
                                         $3F
       0200
                        BFRS+1
                                 EQU
       0200
                       PCVAL
                                 EQU
                                        $40
0017
0018
0019
                        * DEFAULT CASSETTE DECK:
0020
                        *CASS EQU $F050 CASS1
0021
       0200
                        CASS
                                 EQU
                                        $F060
                                                   CASS2
0022
0023
                        * OVERLAY MINI-ASSEMBLER
0024
       0200
                                 ORG
                                         $FDA1
0025
0026
                        * GOT HERE FROM $FC34
0027
0028
       FDA1 26 OE
                                 BNE
                                        TSTL
0029
                        * T COMMAND - TRANSFER CASS BUF
0029
0030
0031
0032
0033
0034
0035
                        * PTRS -> EDIT BUF PTRS
                                 LDX
                                                   BEG OF CASS BUF
       FDA3 DE
                                         BFRPTR
       FDA5 DF OC
                                 STX
                                         EUFADR
       FDA7 DE 3E
FDA9 DF 20
                                 LDX
                                        BFRSZE
                                                   END OF CASS BUF
                                 STX
                                         BUFFLO
       FDAB DE OE
                                 LDX
                                         BUFEND
                                                   END OF EDIT BUF
       FDAD DF 22
                                 STX
                                         BUFFHI
0037
0038
0039
       FDAF 20 1D
FDB1 81 4C
                                        DSPBUF
='L'
                                 BRA
                                                   GO DISPLAY PTRS
                        TSTL
                                 CMPA
       FDB3 26 07
                                 BNE
                                        TSTS
0040
0041
                        * L COMMAND - CASSETTE LOAD
0042
       FDB5 8D 32
                                 BSR
                                        PARMS
                                                   GET PARMS
0043
                                 JSR
       FDB7 BD FB91
                                        RDBLK
                                                   READ CASS BLOCK
                                        DSPBUF
= S
SCOM
0044
       FDBA 20 12
                                 BRA
                                                   GO DISLAY PTRS
0045
0046
       FDBC 81 53
FDBE 27 03
                                 CMPA
                        TSTS
                                 BEQ
0047
0048
       FDCO 7E FE64
                                 JMP
                                        DEBUG
                                                   BAD COMMAND - EXIT
0049
                        * S COMMAND - CASSETTE SAVE
0050
       FDC3 DE OC FDC5 DF 3C
                                 LDX
                                                   DEFAULT IS TO
                        SCOM
                                         BUFADR
0051
0052
0053
                                  STX
                                         BFRPTR
                                                   USE EDIT BUFFER
       FDC7 DE 20
                                  LDX
                                         EUFFLO
                                                   POINTERS
       FDC9 8D 26
                                         PARM1
                                                   GET PARMS
                                 BSR
0054
       FDCB BD FB2D
                                 JSR
                                                   WRITE CASS BLOCK
                                        WRTBLK
0055
0056
0057
                        * DISPLAY EEG & END OF BUF PTRS
                                LDAA =$7C
       FDCE 36 7C
                        DSPBUF
                                                   MOVE CURSOR
0058
       FDDO 97 1D
                                  AATS
                                         CSRP+1
                                                   JUST BELOW STATUS
```

PAGE NO O1 PDS V3N CASSETTE LOAD & SAVE PART 3 8/25/78

0001 0002 0003 0004		* * OVERLAY CTRL—T COMMAND IN * DEBUGGER (NOW CLEARS SCREEN) *			
0005	0200	*	ORG	\$FED2	
0007	FED2 BD FC37 FED5 7F FC3D	CLRSCN	JSR JMP	HOME CLEAR	
0010	FED8 FED8	HOME CLEAR	EQU EQU	\$FC37 \$FC3D	

0059 0060 0061 0062 0063 0064 0065	FDD2 DE 3E FDD4 8D OE FDD6 86 77 FDD8 97 1D FDDA DE 3C		EGINNII	BFRSZE DSPHEX =\$77 CSRP+1 BFRPTR PCVAL WI	ECUTE
0066 0067 0068 0069	FDDC 8D 06 FDDE BD FC37 FDE1 7E FC18	RETHOM *	BSR JSR JMP	DSPHEX HOME EXEC1	DISPLAY BUF BEG RET TO BEG OF LINE
0070 0071 0072 0073 0074 0075 0076 0076 0077 0080 0081 0082 0083 0085 0086 0086 0086 0087 0088 0089 0091 0092 0093 0095 0095 0099 0099 0099 0099 0099	FDE4 DF 40 FDE6 7E FEFC			EX DIGITS ROYS PCVAL PNTDIG	
	FDE9 7F 0033 FDEC CE 0200 FDEF DF 3C	PARMS	CLR LDX STX	DR CASSET: BLKNAM =\$200 BFRPTR	TE L/S DEFAULT NAME DEFAULT BUF BEG
	FDF1 DF 3E FDF3 CE FO60 FDF6 DF 38 FDF8 97 3A FDFA BD FCA5	PARM1	STX LDX STX STAA JSR	BFRSZE =CASS ACIANO NOPRNT RTARRO	DEFAULT CASS ACIA DISPLAY STATUS MOVE OVER ONE SPACE
	FDFD DF 24 FDFF BD FC4A FE02 81 18 FE04 26 04	* PLOOP	STX JSR CMPA BNE	SCNPTR GETCHR =\$18 PEDIT	SAVE BEG OF PARMS CTRL-X (CANCEL)
	FE06 31 FE07 31 FE08 20 D4 FE0A BD FC8F FE0D 81 1B FE0F 26 EE	PEDIT	INS INS BRA JSR CMPA BNE	RETHOM INSERT =\$1B PLOOP	BACK TO BEG OF LINE CALL EDITOR ESCAPE (DONE)
	FE11 DE 24 FE13 A6 00 FE15 81 60 FE17 27 1E FE19 97 33	*	LDX LDAA CMPA BEQ STAA	SCNPTR O,X =\$60 PEXIT ELKNAM	GET BEG OF STRING GET 1ST CHAR OF NAME NO NAME?
0101 0102 0103 0104	FE1B 08 FE1C A6 00 FE1E 97 34 FE2O 08	u.	INX LDAA STAA INX	O,X ELKN+1	GET 2ND CHAR OF NAME
0105 0106 0107 0108 0109 0110	FE21 8D 17 FE23 27 04 FE25 D7 3C FE27 97 3D	*	BSR BEQ STAB STAA	GETONE GETEND BFRPTR EFRP+1	GET BEG ADDR NONE SPECIFIED
0111 0112 0113 0114 0115 0116	FE29 8D OF FE2B 27 04 FE2D D7 3E FE2F 97 3F	GETEND * *	BSR BEQ STAB STAA	GETONE GETDCK BFRSZE EFRS+1	GET END ADDR NONE SPECIFIED

PAGE NO 03 PDS V3N CASSETTE LOAD & SAVE PART 2 8/25/78

0117 0118 0119 0120 0121	FE31 8D 07 FE33 27 02 FE35 97 39 FE37 7E FB00	GETDCK PEXIT	BSR BEQ STAA JMP		GET DECK # NONE SPECIFIED STORE LOW BYTE INIT ACIA & RET
0122		* GET O	NE PAR	AMETER	
0123 0124	FE3A A6 00 FE3C 81 60	GETONE	LDAA CMPA	0,X =\$60	GET CHAR
0125 0126	FE3E 27 09 FE40 08			GEXIT	END OF STRING
0127 0128	FE41 DF 24 FE43 BD FF22		STX JSR	SCNPTR ASCBIN	SKIP PAST DELIMITER GET HEX #
0129	FE46 09		DEX		
0130 0131	FE47 9C 24 FE49 39	GEXIT	CPX RTS	SCNPTR	RET = IF NO PARM
0132 0133 0134 0135 0136 0137 0139 0140 0142 0143	FE4A FE4A FE4A FE4A FE4A FE4A FE4A FE4A	* INTLZ RDBLK WRTBLK RTARRO HOME EXEC1 DEBUG PNTDIG GETCHR INSERT ASCBIN	EQU EQU EQU EQU EQU EQU EQU EQU EQU	\$FB00 \$FB91 \$FB2D \$FCA5 \$FC37 \$FC18 \$FE64 \$FE64 \$FEFC \$FC4A \$FC4A \$FC8F \$FC8F	