

# Why windshield edges fade into black dots

The opaque band and dot matrix are fired ceramic enamel, but they solve different problems at the glass edge.

**The black marks are a functional ceramic coating, not a decorative print.**

## 1 Gradual transition

The dots shrink toward clear glass, making the visual and thermal change less abrupt.

## 2 Opaque band protects the bond

It blocks ultraviolet light before it reaches the polyurethane adhesive.

## 3 Hides the mounting zone

It conceals the adhesive bead and body flange from normal view.

