Fritzing Diagram Wednesday, July 5, 2023 4:42 PM From top to bottom: Backside pressure 34 Brown = Ball release (pin 12) Battery Display Pins: Bottle pressure 35 Purple = Pin release (pin 14) Blue = Bleed (pin 27) Pin 21 = 100% indicator Pin Status 32 Cyan = Charge (pin 26) Pin 19 = 80% indicator Ball Status 33 Pin 18 = 60% indicator Wiper Status 25 Wiper status = white (pin 25) Pin 17 = 40% indicator Pin status = pink (pin 32) Pin 16 = 20% indicator Charge Action 26 Ball status = green (pin 33) Bleed Action 27 Bottle pressure = ochre (puke brown) (pin 34) Ball Release 12 Backside pressure = orange (pin 35) Pin Release 14







