Installing the power and temperature logger

Stefan Schokker November 29, 2019

Contents

1 Setup 1

1 Setup

To continue where this project has left of, internet is definitely required. We use a hotspot to do everything that required an internet connection.

The cluster also needs to be setup correctly. Make sure all the power connectors from the black PCB's are connected to the correct Raspberry Pi's. We labelled the Pi's from bottom to top: 0 - 3, with the highest up one being the "g" pi, or Grafana pi. In our setup we conected them to the PCB as follows:

Address	Pi
0x40	0
0x41	1
0x42	2
0x43	3
0x44	G

With the addresses being on the following places:




Figure 1: PCB INA connector layout, following page 18 of http://www.ti.com/lit/ds/symlink/ina260.pdf

After that, make sure every Pi has it's own ethernet connection to the switch. If everything is setup correctly, it should work with the provided settings file "pis.xml" in the ina260 folder, the file will be required when starting the logger.

NOTE:

• In the current release of Debian Buster, the Pi picks only one of two interfaces (WiFi or Ethernet). Keep this in mind when trying to connect the Pi's to your hotspot.