PRODUCT MANUAL

# Installation & Operation Manual - ACT-TA-2875 Tubing Anchor Catcher

Document MAN-TA-2875 | Revision A | 2025-06-03

| | |
|---|---|
| **Product Family** | ACT-TA-2875 |
| **Prepared By** | A. Gutierrez |
| **Approved By** | J. Martinez, P.E. |
| **Document Control** | L. Hargrove |
| **Distribution** | Field operations, service centers, licensed distributors |

## Table of Contents



## Product Revision History (from engineering records)

| Rev | Date | Description of Change | By |
|---|---|---|---|
| A | 2025-05-12 | Initial release | A. Gutierrez |

## 1. GENERAL

The ACT-TA-2875 tubing anchor catcher anchors 2-7/8 in. tubing in 5-1/2 in. casing for rod pumping service. Slip rating 90,000 lbf. Set and release with right-hand rotation; emergency shear release at 60,000 lbf straight pull (6 brass pins x 10,000 lbf).

## 2. SETTING

| Step | Action |
|---|---|
| 1 | Run anchor to setting depth (recommend within 2 joints above pump seating nipple). |
| 2 | Rotate tubing 1/4 turn RIGHT at the tool (allow 1 full surface turn per 3,000 ft of depth for wind-up). |
| 3 | Slack off 3,000 - 5,000 lbf to engage slips; then pull tension per design. |
| 4 | Set tubing in tension: typical 6,000 - 10,000 lbf over neutral for rod pump service. |
| 5 | Land tubing; verify anchor holds by observing weight transfer. |

*NOTE: Tension setting calculation: required overpull = (fluid load + thermal contraction load) x 1.15 safety factor. See ACT Engineering Bulletin EB-24-03.*

## 3. RELEASING

Release by picking up to neutral weight and rotating 1/4 turn RIGHT at the tool; slips retract via the jay-slot. If rotation is impossible (parted rods, stuck string), pull straight tension to 60,000 lbf +/- 10% over string weight to shear the brass release pins.

**WARNING: After a shear release the anchor is spent: all six pins ACT-TA-2875-06 must be replaced and the jay-clutch inspected before reuse.**

## 4. MAINTENANCE

| Interval | Action |
|---|---|
| Each pull | Visual: slips, wickers, drag springs; replace bent springs |
| Each redress | Replace shear pins (6x) and o-rings from kit ACT-TA-2875-RK |
| Annually | MPI mandrel and cone; gauge wicker sharpness |

## Document Approval

| Role | Name | Signature | Date |
|---|---|---|---|
| **Prepared** | A. Gutierrez | */signed electronically/* | 2025-06-03 |
| **Quality Review** | S. Nguyen | */signed electronically/* | 2025-06-03 |
| **Approved** | J. Martinez, P.E. | */signed electronically/* | 2025-06-03 |