

Liner Running & Setting Procedure - ACT-LH-7625 Hydraulic Liner Hanger

Controlled Procedure LRP-LH-7625 Rev A | Product: ACT-LH-7625

Prepared By	R. Callahan
Checked By	S. Nguyen
Approved By	J. Martinez, P.E.
Effective Date	2024-07-18

1. Scope

Running, setting, cementing interface and release of the ACT-LH-7625 hydraulic liner hanger with hydraulic-release running tool ACT-LH-RT-45.

2. Reference Documents

- BOM-LH-7625 Rev A
- DS-LH-7625
- HTR-2024-0389
- TS-200

3. Equipment & Materials Required

Equipment / Material	Requirement
ACT-LH-RT-45 running tool	Serviced; release nut inspected
Liner-wiper plug & pump-down dart set	Sized 4-1/2 in.
Ball, setting, 1.50 in. phenolic	In cellar basket, clean
Torque-turn sub	Calibrated

4. Procedure

Steps marked 'QC HOLD' are mandatory hold points: work shall not proceed past a hold point without sign-off by the responsible party in the right-hand column. Record actual values on the job traveler.

4.1 Make-Up And Running

Step	Action	Responsible / Sign-off
1	Make up hanger to liner top; torque 4-1/2 LTC landing collar per API 5C1.	Operator
2	Engage RT-45 running tool; verify LH release nut fully made up + anti-rotation keys seated.	ACT Rep
3	RIH liner on drill pipe at max 2 ft/sec; break circulation every 2,000 ft.	Driller
4	Wash down last joint to setting depth; circulate bottoms-up minimum.	Driller

4.2 Setting And Release

Step	Action	Responsible / Sign-off
5	Drop 1.50 in. setting ball; pump at 2 bbl/min to seat (ball seat in landing collar).	ACT Rep
6	Pressure in stages to 2,200 psi +/- 150 - hanger slips set. Hold 5 min.	ACT Rep
7	Slack off 20,000 lbf to confirm hang-off; mark pipe.	Driller
8	Increase pressure to 3,000 psi to shear ball seat; establish circulation.	ACT Rep
9	Release running tool: 10 turns RH at hanger depth (surface turns = 10 + 1 per 3,000 ft).	ACT Rep
10	Pick up 3 ft - verify free (string weight loss = liner weight).	Driller
11	Cement per program through liner shoe; displace wiper plug/dart.	Cementer
12	Pull 2 stands, reverse out excess, POOH. PBR is ready for ACT-SA-4000 tieback seals.	Driller

5. Notes & Cautions

- Hydraulic release backup: if RH rotation fails, 12 turns generates no release - use emergency shear-release at 90,000 lbf overpull per RT-45 data sheet.
- Protect the PBR: do not rotate drill pipe inside the polished bore.
- PBR bore 4.000 in. honed - any tool run through it must be < 3.900 in. OD.

6. Sign-off Record

Role	Name	Signature	Date
Prepared	R. Callahan	/signed electronically/	2024-07-18
Checked (QA)	S. Nguyen	/signed electronically/	2024-07-18
Approved	J. Martinez, P.E.	/signed electronically/	2024-07-18