

Slickline Gas Lift Valve Change-Out Procedure - ACT-SPM-2875 Side Pocket Mandrel

Controlled Procedure KOP-SPM-2875 Rev A | Product: ACT-SPM-2875

Prepared By	A. Gutierrez
Checked By	S. Nguyen
Approved By	J. Martinez, P.E.
Effective Date	2025-08-06

1. Scope

Slickline retrieval and installation of ACT-GLV-1000 gas lift valves in the ACT-SPM-2875 side pocket mandrel using a kickover tool with RK latch running/pulling heads.

2. Reference Documents

- BOM-SPM-2875 Rev B
- DS datasheets
- API SPEC 11V1 (valve)
- TS-200

3. Equipment & Materials Required

Equipment / Material	Requirement
Kickover tool, 2-7/8, RK head	Serviced
ACT-GLV-1000 replacement valve	Dome charge verified on test bench +/- 2%
Slickline unit 0.108 in.	With jar assembly

4. Procedure

Steps marked 'QC HOLD' are mandatory hold points: work shall not proceed past a hold point without sign-off by the responsible party in the right-hand column. Record actual values on the job traveler.

4.1 Valve Retrieval

Step	Action	Responsible / Sign-off
1	Rig up slickline; drift tubing to top mandrel with 2.313 in. gauge cutter.	SL Op
2	RIH kickover tool with RK pulling head; locate mandrel by tubing stop/CCL depth.	SL Op
3	Pull up through orienting sleeve - tool kicks over into pocket.	SL Op
4	Jar down to engage latch; jar up to shear latch retention and pull valve.	SL Op
5	POOH; verify complete valve recovered (latch, bellows housing, check dart).	SL Op

4.2 Valve Installation

Step	Action	Responsible / Sign-off
6	Verify replacement GLV-1000 port size and dome pressure against gas lift design table.	GL Eng
7	RIH with running head; kick over; jar down to snap RK latch into pocket seat.	SL Op
8	Pull test 300 lbf to confirm latch; POOH.	SL Op
9	Function test: inject gas at design casing pressure; confirm valve opens/transfers.	GL Eng

5. Notes & Cautions

- Never jar up on a valve without first jarring down to release the latch keeper.
- Discriminator guide orients tool automatically; if kickover fails twice, check mandrel orientation record from installation.
- Recovered valves: tag with well, mandrel number and pull date; send to ACT for teardown report.

6. Sign-off Record

Role	Name	Signature	Date
Prepared	A. Gutierrez	/signed electronically/	2025-08-06
Checked (QA)	S. Nguyen	/signed electronically/	2025-08-06
Approved	J. Martinez, P.E.	/signed electronically/	2025-08-06