Change Order Report For Project   Course.PrjPcb And Course.PrjPcb

Action	Object	Change Document	Status
Add Components			
Add	C1	To PCB_all.PcbDoc	
Add	C2	To PCB_all.PcbDoc	
Add	C3	To PCB_all.PcbDoc	
Add	C4	To PCB_all.PcbDoc	
Add	C5	To PCB_all.PcbDoc	
Add	C7	To PCB_all.PcbDoc	
Add	C8	To PCB_all.PcbDoc	
Add	C9	To PCB_all.PcbDoc	
Add	C10	To PCB_all.PcbDoc	
Add	C11	To PCB_all.PcbDoc	
Add	C12	To PCB_all.PcbDoc	
Add	C13	To PCB_all.PcbDoc	
Add	C15	To PCB_all.PcbDoc	
Add	C16	To PCB_all.PcbDoc	
Add	C17	To PCB_all.PcbDoc	
Add	C18	To PCB_all.PcbDoc	
Add	C19	To PCB_all.PcbDoc	
Add	C20	To PCB_all.PcbDoc	
Add	C21	To PCB_all.PcbDoc	
Add	C22	To PCB_all.PcbDoc	
Add	C23	To PCB_all.PcbDoc	
Add	C24	To PCB_all.PcbDoc	
Add	C25	To PCB_all.PcbDoc	
Add	C26	To PCB_all.PcbDoc	
Add	C27	To PCB_all.PcbDoc	
Add	C28	To PCB_all.PcbDoc	
Add	C29	To PCB_all.PcbDoc	
Add	C30	To PCB_all.PcbDoc	
Add	C31	To PCB_all.PcbDoc	
Add	C32	To PCB_all.PcbDoc	
Add	C33	To PCB_all.PcbDoc	
Add	C34	To PCB_all.PcbDoc	
Add	C36	To PCB_all.PcbDoc	
Add	C37	To PCB_all.PcbDoc	
Add	C38	To PCB_all.PcbDoc	
Add	C39	To PCB_all.PcbDoc	
Add	C44	To PCB_all.PcbDoc	
Add	C45	To PCB_all.PcbDoc	
Add	C46	To PCB_all.PcbDoc	
Add	C47	To PCB_all.PcbDoc	
Add	C48	To PCB_all.PcbDoc	
Add	C49	To PCB_all.PcbDoc	
Add	C50	To PCB_all.PcbDoc	
Add	C51	To PCB_all.PcbDoc	
Add	C53	To PCB_all.PcbDoc	
Add	C54	To PCB_all.PcbDoc	
Add	C55	To PCB_all.PcbDoc	
Add	C56	To PCB_all.PcbDoc	
Add	C58	To PCB_all.PcbDoc	
Add	C59	To PCB_all.PcbDoc	
Add	C60	To PCB_all.PcbDoc	
Add	C61	To PCB_all.PcbDoc	
Add	C62	To PCB_all.PcbDoc	
Add	C63	To PCB_all.PcbDoc	
Add	C65	To PCB_all.PcbDoc	
Add	C66	To PCB_all.PcbDoc	
Add	C67	To PCB_all.PcbDoc	
Add	C68	To PCB_all.PcbDoc	
Add	C69	To PCB_all.PcbDoc	
Add	C70	To PCB_all.PcbDoc	
Add	C71	To PCB_all.PcbDoc	
Add	C72	To PCB_all.PcbDoc	
Add	C73	To PCB_all.PcbDoc	
Add	C74	To PCB_all.PcbDoc	
Add	C75	To PCB_all.PcbDoc	
Add	C76	To PCB_all.PcbDoc	
Add	C77	To PCB_all.PcbDoc	

Action	Object	Change Document	Status
Add Components			
Add	C78	To PCB_all.PcbDoc	
Add	C79	To PCB_all.PcbDoc	
Add	C80	To PCB_all.PcbDoc	
Add	C81	To PCB_all.PcbDoc	
Add	C82	To PCB_all.PcbDoc	
Add	C83	To PCB_all.PcbDoc	
Add	C84	To PCB_all.PcbDoc	
Add	C85	To PCB_all.PcbDoc	
Add	C86	To PCB_all.PcbDoc	
Add	C87	To PCB_all.PcbDoc	
Add	C88	To PCB_all.PcbDoc	
Add	C89	To PCB_all.PcbDoc	
Add	C90	To PCB_all.PcbDoc	
Add	C91	To PCB_all.PcbDoc	
Add	C92	To PCB_all.PcbDoc	
Add	C93	To PCB_all.PcbDoc	
Add	C94	To PCB_all.PcbDoc	
Add	C95	To PCB_all.PcbDoc	
Add	C96	To PCB_all.PcbDoc	
Add	C97	To PCB_all.PcbDoc	
Add	C98	To PCB_all.PcbDoc	
Add	C99	To PCB_all.PcbDoc	
Add	C100	To PCB_all.PcbDoc	
Add	C101	To PCB_all.PcbDoc	
Add	C102	To PCB_all.PcbDoc	
Add	C103	To PCB_all.PcbDoc	
Add	C104	To PCB_all.PcbDoc	
Add	C105	To PCB_all.PcbDoc	
Add	C106	To PCB_all.PcbDoc	
Add	C107	To PCB_all.PcbDoc	
Add	C108	To PCB_all.PcbDoc	
Add	C109	To PCB_all.PcbDoc	
Add	C110	To PCB_all.PcbDoc	
Add	C111	To PCB_all.PcbDoc	
Add	C112	To PCB_all.PcbDoc	
Add	C113	To PCB_all.PcbDoc	
Add	C114	To PCB_all.PcbDoc	
Add	C115	To PCB_all.PcbDoc	
Add	C116	To PCB_all.PcbDoc	
Add	C117	To PCB_all.PcbDoc	
Add	C118	To PCB_all.PcbDoc	
Add	C119	To PCB_all.PcbDoc	
Add	C120	To PCB_all.PcbDoc	
Add	C121	To PCB_all.PcbDoc	
Add	C122	To PCB_all.PcbDoc	
Add	C123	To PCB_all.PcbDoc	
Add	C124	To PCB_all.PcbDoc	
Add	C125	To PCB_all.PcbDoc	
Add	C126	To PCB_all.PcbDoc	
Add	C127	To PCB_all.PcbDoc	
Add	C128	To PCB_all.PcbDoc	
Add	C129	To PCB_all.PcbDoc	
Add	C130	To PCB_all.PcbDoc	
Add	C131	To PCB_all.PcbDoc	
Add	C132	To PCB_all.PcbDoc	
Add	C133	To PCB_all.PcbDoc	
Add	C138	To PCB_all.PcbDoc	
Add	C139	To PCB_all.PcbDoc	
Add	C140	To PCB_all.PcbDoc	
Add	C141	To PCB_all.PcbDoc	
Add	C142	To PCB_all.PcbDoc	
Add	C143	To PCB_all.PcbDoc	
Add	C144	To PCB_all.PcbDoc	
Add	C145	To PCB_all.PcbDoc	
Add	C146	To PCB_all.PcbDoc	
Add	C147	To PCB_all.PcbDoc	
Add	C148	To PCB_all.PcbDoc	
Add	C149	To PCB_all.PcbDoc	
Add	C150	To PCB_all.PcbDoc	

Action	Object	Change Document	Status
Add Components			
Add	C151	To PCB_all.PcbDoc	
Add	C152	To PCB_all.PcbDoc	
Add	C153	To PCB_all.PcbDoc	
Add	C154	To PCB_all.PcbDoc	
Add	C155	To PCB_all.PcbDoc	
Add	C156	To PCB_all.PcbDoc	
Add	C157	To PCB_all.PcbDoc	
Add	C158	To PCB_all.PcbDoc	
Add	C159	To PCB_all.PcbDoc	
Add	C160	To PCB_all.PcbDoc	
Add	C161	To PCB_all.PcbDoc	
Add	C162	To PCB_all.PcbDoc	
Add	C164	To PCB_all.PcbDoc	
Add	C165	To PCB_all.PcbDoc	
Add	C166	To PCB_all.PcbDoc	
Add	C167	To PCB_all.PcbDoc	
Add	C168	To PCB_all.PcbDoc	
Add	C169	To PCB_all.PcbDoc	
Add	C170	To PCB_all.PcbDoc	
Add	C171	To PCB_all.PcbDoc	
Add	C172	To PCB_all.PcbDoc	
Add	D4	To PCB_all.PcbDoc	
Add	D5	To PCB_all.PcbDoc	
Add	D6	To PCB_all.PcbDoc	
Add	D7	To PCB_all.PcbDoc	
Add	D8	To PCB_all.PcbDoc	
Add	R1	To PCB_all.PcbDoc	
Add	R2	To PCB_all.PcbDoc	
Add	R3	To PCB_all.PcbDoc	
Add	R4	To PCB_all.PcbDoc	
Add	R5	To PCB_all.PcbDoc	
Add	R6	To PCB_all.PcbDoc	
Add	R7	To PCB_all.PcbDoc	
Add	R8	To PCB_all.PcbDoc	
Add	R9	To PCB_all.PcbDoc	
Add	R10	To PCB_all.PcbDoc	
Add	R11	To PCB_all.PcbDoc	
Add	R12	To PCB_all.PcbDoc	
Add	R13	To PCB_all.PcbDoc	
Add	R14	To PCB_all.PcbDoc	
Add	R15	To PCB_all.PcbDoc	
Add	R16	To PCB_all.PcbDoc	
Add	R17	To PCB_all.PcbDoc	
Add	R18	To PCB_all.PcbDoc	
Add	R19	To PCB_all.PcbDoc	
Add	R20	To PCB_all.PcbDoc	
Add	R21	To PCB_all.PcbDoc	
Add	R22	To PCB_all.PcbDoc	
Add	R23	To PCB_all.PcbDoc	
Add	R24	To PCB_all.PcbDoc	
Add	R25	To PCB_all.PcbDoc	
Add	R26	To PCB_all.PcbDoc	
Add	R27	To PCB_all.PcbDoc	
Add	R28	To PCB_all.PcbDoc	
Add	R29	To PCB_all.PcbDoc	
Add	R30	To PCB_all.PcbDoc	
Add	R31	To PCB_all.PcbDoc	
Add	R32	To PCB_all.PcbDoc	
Add	R33	To PCB_all.PcbDoc	
Add	R34	To PCB_all.PcbDoc	
Add	R35	To PCB_all.PcbDoc	
Add	R36	To PCB_all.PcbDoc	
Add	R37	To PCB_all.PcbDoc	
Add	R38	To PCB_all.PcbDoc	
Add	R39	To PCB_all.PcbDoc	
Add	R40	To PCB_all.PcbDoc	
Add	R41	To PCB_all.PcbDoc	
Add	R42	To PCB_all.PcbDoc	
Add	R43	To PCB_all.PcbDoc	

Action	Object	Change Document	Status
Add Components			
Add	R44	To PCB_all.PcbDoc	
Add	R45	To PCB_all.PcbDoc	
Add	R46	To PCB_all.PcbDoc	
Add	R47	To PCB_all.PcbDoc	
Add	R48	To PCB_all.PcbDoc	
Add	R49	To PCB_all.PcbDoc	
Add	R50	To PCB_all.PcbDoc	
Add	R51	To PCB_all.PcbDoc	
Add	R52	To PCB_all.PcbDoc	
Add	R53	To PCB_all.PcbDoc	
Add	R54	To PCB_all.PcbDoc	
Add	R55	To PCB_all.PcbDoc	
Add	R56	To PCB_all.PcbDoc	
Add	R57	To PCB_all.PcbDoc	
Add	R58	To PCB_all.PcbDoc	
Add	R59	To PCB_all.PcbDoc	
Add	R60	To PCB_all.PcbDoc	
Add	R61	To PCB_all.PcbDoc	
Add	R62	To PCB_all.PcbDoc	
Add	R63	To PCB_all.PcbDoc	
Add	R64	To PCB_all.PcbDoc	
Add	R65	To PCB_all.PcbDoc	
Add	R66	To PCB_all.PcbDoc	
Add	R67	To PCB_all.PcbDoc	
Add	R68	To PCB_all.PcbDoc	
Add	R69	To PCB_all.PcbDoc	
Add	R70	To PCB_all.PcbDoc	
Add	R71	To PCB_all.PcbDoc	
Add	R72	To PCB_all.PcbDoc	
Add	R73	To PCB_all.PcbDoc	
Add	R74	To PCB_all.PcbDoc	
Add	R75	To PCB_all.PcbDoc	
Add	R76	To PCB_all.PcbDoc	
Add	R77	To PCB_all.PcbDoc	
Add	R78	To PCB_all.PcbDoc	
Add	R79	To PCB_all.PcbDoc	
Add	R80	To PCB_all.PcbDoc	
Add	R81	To PCB_all.PcbDoc	
Add	R82	To PCB_all.PcbDoc	
Add	R83	To PCB_all.PcbDoc	
Add	R84	To PCB_all.PcbDoc	
Add	R85	To PCB_all.PcbDoc	
Add	R86	To PCB_all.PcbDoc	
Add	R87	To PCB_all.PcbDoc	
Add	R88	To PCB_all.PcbDoc	
Add	R89	To PCB_all.PcbDoc	
Add	R90	To PCB_all.PcbDoc	
Add	R91	To PCB_all.PcbDoc	
Add	R92	To PCB_all.PcbDoc	
Add	R93	To PCB_all.PcbDoc	
Add	R94	To PCB_all.PcbDoc	
Add	R95	To PCB_all.PcbDoc	
Add	R96	To PCB_all.PcbDoc	
Add	R97	To PCB_all.PcbDoc	
Add	R98	To PCB_all.PcbDoc	
Add	R99	To PCB_all.PcbDoc	
Add	R100	To PCB_all.PcbDoc	
Add	R101	To PCB_all.PcbDoc	
Add	R102	To PCB_all.PcbDoc	
Add	R103	To PCB_all.PcbDoc	
Add	R104	To PCB_all.PcbDoc	
Add	R105	To PCB_all.PcbDoc	
Add	R106	To PCB_all.PcbDoc	
Add	R107	To PCB_all.PcbDoc	
Add	R108	To PCB_all.PcbDoc	
Add	R109	To PCB_all.PcbDoc	
Add	R110	To PCB_all.PcbDoc	
Add	R111	To PCB_all.PcbDoc	
Add	R112	To PCB_all.PcbDoc	

Add Components			
Add	R113	To PCB_all.PcbDoc	
Add	R114	To PCB_all.PcbDoc	
Add	R115	To PCB_all.PcbDoc	
Add	R116	To PCB_all.PcbDoc	
Add	R117	To PCB_all.PcbDoc	
Add	R118	To PCB_all.PcbDoc	
Add	R119	To PCB_all.PcbDoc	
Add	R120	To PCB_all.PcbDoc	
Add	R121	To PCB_all.PcbDoc	
Add	R122	To PCB_all.PcbDoc	
Add	R123	To PCB_all.PcbDoc	
Add	R124	To PCB_all.PcbDoc	
Add	R125	To PCB_all.PcbDoc	
Add	R126	To PCB_all.PcbDoc	
Add	R127	To PCB_all.PcbDoc	
Add	R128	To PCB_all.PcbDoc	
Add	R129	To PCB_all.PcbDoc	
Add	R130	To PCB_all.PcbDoc	
Add	R131	To PCB_all.PcbDoc	
Add	R132	To PCB_all.PcbDoc	
Add	R133	To PCB_all.PcbDoc	
Add	R134	To PCB_all.PcbDoc	
Add	R135	To PCB_all.PcbDoc	
Add	R136	To PCB_all.PcbDoc	
Add	R137	To PCB_all.PcbDoc	
Add	R138	To PCB_all.PcbDoc	
Add	R139	To PCB_all.PcbDoc	
Add	R140	To PCB_all.PcbDoc	
Add	R141	To PCB_all.PcbDoc	
Add	R142	To PCB_all.PcbDoc	
Add	R143	To PCB_all.PcbDoc	
Add	R144	To PCB_all.PcbDoc	
Add	R145	To PCB_all.PcbDoc	
Add	R146	To PCB_all.PcbDoc	
Add	R147	To PCB_all.PcbDoc	
Add	R148	To PCB_all.PcbDoc	
Add	R149	To PCB_all.PcbDoc	
Add	R150	To PCB_all.PcbDoc	
Add	R151	To PCB_all.PcbDoc	
Add	R152	To PCB_all.PcbDoc	
Add	R153	To PCB_all.PcbDoc	
Add	R154	To PCB_all.PcbDoc	
Add	R155	To PCB_all.PcbDoc	
Add	R156	To PCB_all.PcbDoc	
Add	R157	To PCB_all.PcbDoc	
Add	R158	To PCB_all.PcbDoc	
Add	R159	To PCB_all.PcbDoc	
Add	R160	To PCB_all.PcbDoc	
Add	R161	To PCB_all.PcbDoc	
Add	R162	To PCB_all.PcbDoc	
Add	R163	To PCB_all.PcbDoc	
Add	R164	To PCB_all.PcbDoc	
Add	R165	To PCB_all.PcbDoc	
Add	R166	To PCB_all.PcbDoc	
Add	R167	To PCB_all.PcbDoc	
Add	R168	To PCB_all.PcbDoc	
Add	R169	To PCB_all.PcbDoc	
Add	R170	To PCB_all.PcbDoc	
Add	R171	To PCB_all.PcbDoc	
Add	R172	To PCB_all.PcbDoc	
Add	R173	To PCB_all.PcbDoc	
Add	R174	To PCB_all.PcbDoc	
Add	R175	To PCB_all.PcbDoc	
Add	R176	To PCB_all.PcbDoc	
Add	R177	To PCB_all.PcbDoc	
Add	R178	To PCB_all.PcbDoc	
Add	R179	To PCB_all.PcbDoc	
Add	R180	To PCB_all.PcbDoc	
Add	R181	To PCB_all.PcbDoc	

Action	Object	Change Document	Status
Add Components			
Add	R182	To PCB_all.PcbDoc	
Add	R183	To PCB_all.PcbDoc	
Add	R184	To PCB_all.PcbDoc	
Add	R185	To PCB_all.PcbDoc	
Add	R186	To PCB_all.PcbDoc	
Add	R187	To PCB_all.PcbDoc	
Add	R188	To PCB_all.PcbDoc	
Add	R189	To PCB_all.PcbDoc	
Add	R190	To PCB_all.PcbDoc	
Add	R191	To PCB_all.PcbDoc	
Add	R192	To PCB_all.PcbDoc	
Add	R193	To PCB_all.PcbDoc	
Add	R194	To PCB_all.PcbDoc	
Add	R195	To PCB_all.PcbDoc	
Add	R196	To PCB_all.PcbDoc	
Add	R197	To PCB_all.PcbDoc	
Add	R198	To PCB_all.PcbDoc	
Add	R199	To PCB_all.PcbDoc	
Add	R200	To PCB_all.PcbDoc	
Add	R201	To PCB_all.PcbDoc	
Add	R202	To PCB_all.PcbDoc	
Add	R203	To PCB_all.PcbDoc	
Add	R204	To PCB_all.PcbDoc	
Add	R205	To PCB_all.PcbDoc	
Add	R206	To PCB_all.PcbDoc	
Add	R207	To PCB_all.PcbDoc	
Add	R208	To PCB_all.PcbDoc	
Add	R209	To PCB_all.PcbDoc	
Add	R210	To PCB_all.PcbDoc	
Add	R211	To PCB_all.PcbDoc	
Add	R212	To PCB_all.PcbDoc	
Add	R213	To PCB_all.PcbDoc	
Add	R214	To PCB_all.PcbDoc	
Add	R215	To PCB_all.PcbDoc	
Add	R216	To PCB_all.PcbDoc	
Add	R217	To PCB_all.PcbDoc	
Add	R218	To PCB_all.PcbDoc	
Add	R219	To PCB_all.PcbDoc	
Add	R220	To PCB_all.PcbDoc	
Add	R221	To PCB_all.PcbDoc	
Add	R222	To PCB_all.PcbDoc	
Add	R223	To PCB_all.PcbDoc	
Add	R224	To PCB_all.PcbDoc	
Add	R225	To PCB_all.PcbDoc	
Add	R226	To PCB_all.PcbDoc	
Add	R227	To PCB_all.PcbDoc	
Add	R228	To PCB_all.PcbDoc	
Add	R229	To PCB_all.PcbDoc	
Add	R230	To PCB_all.PcbDoc	
Add	R231	To PCB_all.PcbDoc	
Add	R232	To PCB_all.PcbDoc	
Add	R233	To PCB_all.PcbDoc	
Add	R234	To PCB_all.PcbDoc	
Add	R235	To PCB_all.PcbDoc	
Add	R236	To PCB_all.PcbDoc	
Add	R237	To PCB_all.PcbDoc	
Add	R238	To PCB_all.PcbDoc	
Add	R239	To PCB_all.PcbDoc	
Add	U4	To PCB_all.PcbDoc	
Add	ZD1	To PCB_all.PcbDoc	
Add	ZD2	To PCB_all.PcbDoc	
Add	ZD3	To PCB_all.PcbDoc	
Add	ZD4	To PCB_all.PcbDoc	
Add	ZD5	To PCB_all.PcbDoc	
Add	ZD6	To PCB_all.PcbDoc	
Add	ZD7	To PCB_all.PcbDoc	
Add	ZD8	To PCB_all.PcbDoc	
Add	ZD9	To PCB_all.PcbDoc	
Add	ZQ1	To PCB_all.PcbDoc	

Add Nets

Action	Object	Change Document	Status
Add	+3V3	To PCB_all.PcbDoc	
Add	3_3Va	To PCB_all.PcbDoc	
Add	3V3b	To PCB_all.PcbDoc	
Add	3V3LVDSA	To PCB_all.PcbDoc	
Add	3V3LVDSD	To PCB_all.PcbDoc	
Add	3V3LVDSP	To PCB_all.PcbDoc	
Add	3V3SD	To PCB_all.PcbDoc	
Add	3V3	To PCB_all.PcbDoc	
Add	5V_DDC	To PCB_all.PcbDoc	
Add	5V_STBY	To PCB_all.PcbDoc	
Add	5V_VGA	To PCB_all.PcbDoc	
Add	5Va	To PCB_all.PcbDoc	
Add	5Vb	To PCB_all.PcbDoc	
Add	12MHZ	To PCB_all.PcbDoc	
Add	9883_HS	To PCB_all.PcbDoc	
Add	9883_VS	To PCB_all.PcbDoc	
Add	A3_3V	To PCB_all.PcbDoc	
Add	A3V3	To PCB_all.PcbDoc	
Add	ADC1	To PCB_all.PcbDoc	
Add	ADC2	To PCB_all.PcbDoc	
Add	ASIC_H	To PCB_all.PcbDoc	
Add	ASIC_RESET	To PCB_all.PcbDoc	
Add	ASIC_SCL	To PCB_all.PcbDoc	
Add	ASIC_SDA	To PCB_all.PcbDoc	
Add	AUDIO_EN	To PCB_all.PcbDoc	
Add	AUDIO_MUTE	To PCB_all.PcbDoc	
Add	B_INA0	To PCB_all.PcbDoc	
Add	B_INA1	To PCB_all.PcbDoc	
Add	B_INA2	To PCB_all.PcbDoc	
Add	B_INA3	To PCB_all.PcbDoc	
Add	B_INA4	To PCB_all.PcbDoc	
Add	B_INA5	To PCB_all.PcbDoc	
Add	B_INA6	To PCB_all.PcbDoc	
Add	B_INA7	To PCB_all.PcbDoc	
Add	B_INB0	To PCB_all.PcbDoc	
Add	B_INB1	To PCB_all.PcbDoc	
Add	B_INB2	To PCB_all.PcbDoc	
Add	B_INB3	To PCB_all.PcbDoc	
Add	B_INB4	To PCB_all.PcbDoc	
Add	B_INB5	To PCB_all.PcbDoc	
Add	B_INB6	To PCB_all.PcbDoc	
Add	B_INB7	To PCB_all.PcbDoc	
Add	B_IN	To PCB_all.PcbDoc	
Add	BA0	To PCB_all.PcbDoc	
Add	BA1	To PCB_all.PcbDoc	
Add	BA2	To PCB_all.PcbDoc	
Add	BA3	To PCB_all.PcbDoc	
Add	BA4	To PCB_all.PcbDoc	
Add	BA5	To PCB_all.PcbDoc	
Add	BA6	To PCB_all.PcbDoc	
Add	BA7	To PCB_all.PcbDoc	
Add	BB0	To PCB_all.PcbDoc	
Add	BB1	To PCB_all.PcbDoc	
Add	BB2	To PCB_all.PcbDoc	
Add	BB3	To PCB_all.PcbDoc	
Add	BB4	To PCB_all.PcbDoc	
Add	BB5	To PCB_all.PcbDoc	
Add	BB6	To PCB_all.PcbDoc	
Add	BB7	To PCB_all.PcbDoc	
Add	BL_ON_OFF	To PCB_all.PcbDoc	
Add	COAST	To PCB_all.PcbDoc	
Add	D3_3V	To PCB_all.PcbDoc	
Add	D3_V3	To PCB_all.PcbDoc	
Add	DE_IN	To PCB_all.PcbDoc	
Add	FBLK	To PCB_all.PcbDoc	
Add	FCLK1	To PCB_all.PcbDoc	
Add	G_INA0	To PCB_all.PcbDoc	
Add	G_INA1	To PCB_all.PcbDoc	
Add	G_INA2	To PCB_all.PcbDoc	

Action	Object	Change Document	Status
Add Nets			
Add	G_INA3	To PCB_all.PcbDoc	
Add	G_INA4	To PCB_all.PcbDoc	
Add	G_INA5	To PCB_all.PcbDoc	
Add	G_INA6	To PCB_all.PcbDoc	
Add	G_INA7	To PCB_all.PcbDoc	
Add	G_INB0	To PCB_all.PcbDoc	
Add	G_INB1	To PCB_all.PcbDoc	
Add	G_INB2	To PCB_all.PcbDoc	
Add	G_INB3	To PCB_all.PcbDoc	
Add	G_INB4	To PCB_all.PcbDoc	
Add	G_INB5	To PCB_all.PcbDoc	
Add	G_INB6	To PCB_all.PcbDoc	
Add	G_INB7	To PCB_all.PcbDoc	
Add	G_IN	To PCB_all.PcbDoc	
Add	GA0	To PCB_all.PcbDoc	
Add	GA1	To PCB_all.PcbDoc	
Add	GA2	To PCB_all.PcbDoc	
Add	GA3	To PCB_all.PcbDoc	
Add	GA4	To PCB_all.PcbDoc	
Add	GA5	To PCB_all.PcbDoc	
Add	GA6	To PCB_all.PcbDoc	
Add	GA7	To PCB_all.PcbDoc	
Add	GB0	To PCB_all.PcbDoc	
Add	GB1	To PCB_all.PcbDoc	
Add	GB2	To PCB_all.PcbDoc	
Add	GB3	To PCB_all.PcbDoc	
Add	GB4	To PCB_all.PcbDoc	
Add	GB5	To PCB_all.PcbDoc	
Add	GB6	To PCB_all.PcbDoc	
Add	GB7	To PCB_all.PcbDoc	
Add	GND	To PCB_all.PcbDoc	
Add	HP_SENSE	To PCB_all.PcbDoc	
Add	HSYNC_D	To PCB_all.PcbDoc	
Add	HSYNC_IN	To PCB_all.PcbDoc	
Add	HSYNC_X	To PCB_all.PcbDoc	
Add	INPUT_SELECT	To PCB_all.PcbDoc	
Add	LCD_CLK	To PCB_all.PcbDoc	
Add	LCD_DE	To PCB_all.PcbDoc	
Add	LCD_VCC	To PCB_all.PcbDoc	
Add	LVDS_PD	To PCB_all.PcbDoc	
Add	MCU_H_IN	To PCB_all.PcbDoc	
Add	MCU_ISP_SCL	To PCB_all.PcbDoc	
Add	MCU_ISP_SDA	To PCB_all.PcbDoc	
Add	MCU_SCL1	To PCB_all.PcbDoc	
Add	MCU_SDA1	To PCB_all.PcbDoc	
Add	MCU_V_IN	To PCB_all.PcbDoc	
Add	NetC7_1	To PCB_all.PcbDoc	
Add	NetC8_1	To PCB_all.PcbDoc	
Add	NetC11_1	To PCB_all.PcbDoc	
Add	NetC15_1	To PCB_all.PcbDoc	
Add	NetC16_1	To PCB_all.PcbDoc	
Add	NetC17_1	To PCB_all.PcbDoc	
Add	NetC18_1	To PCB_all.PcbDoc	
Add	NetC19_1	To PCB_all.PcbDoc	
Add	NetC20_2	To PCB_all.PcbDoc	
Add	NetC21_1	To PCB_all.PcbDoc	
Add	NetC22_1	To PCB_all.PcbDoc	
Add	NetC23_1	To PCB_all.PcbDoc	
Add	NetC24_1	To PCB_all.PcbDoc	
Add	NetC27_2	To PCB_all.PcbDoc	
Add	NetC29_2	To PCB_all.PcbDoc	
Add	NetC49_2	To PCB_all.PcbDoc	
Add	NetC55_2	To PCB_all.PcbDoc	
Add	NetC56_2	To PCB_all.PcbDoc	
Add	NetC61_2	To PCB_all.PcbDoc	
Add	NetC63_2	To PCB_all.PcbDoc	
Add	NetC90_2	To PCB_all.PcbDoc	
Add	NetC129_1	To PCB_all.PcbDoc	
Add	NetC132_1	To PCB_all.PcbDoc	

Action	Object	Change Document	Status

Add Nets

Action	Object	Change Document	Status
Add	NetC159_2	To PCB_all.PcbDoc	
Add	NetC160_1	To PCB_all.PcbDoc	
Add	NetC161_1	To PCB_all.PcbDoc	
Add	NetC162_2	To PCB_all.PcbDoc	
Add	NetC163_1	To PCB_all.PcbDoc	
Add	NetC164_1	To PCB_all.PcbDoc	
Add	NetC166_1	To PCB_all.PcbDoc	
Add	NetC167_1	To PCB_all.PcbDoc	
Add	NetC168_1	To PCB_all.PcbDoc	
Add	NetC170_1	To PCB_all.PcbDoc	
Add	NetJ1_10	To PCB_all.PcbDoc	
Add	NetJ1_11	To PCB_all.PcbDoc	
Add	NetJ1_12	To PCB_all.PcbDoc	
Add	NetJ1_13	To PCB_all.PcbDoc	
Add	NetJ1_14	To PCB_all.PcbDoc	
Add	NetJ1_15	To PCB_all.PcbDoc	
Add	NetJ1_16	To PCB_all.PcbDoc	
Add	NetJ1_17	To PCB_all.PcbDoc	
Add	NetJ1_18	To PCB_all.PcbDoc	
Add	NetJ1_19	To PCB_all.PcbDoc	
Add	NetJ1_20	To PCB_all.PcbDoc	
Add	NetJ1_21	To PCB_all.PcbDoc	
Add	NetJ1_22	To PCB_all.PcbDoc	
Add	NetJ1_23	To PCB_all.PcbDoc	
Add	NetJ1_24	To PCB_all.PcbDoc	
Add	NetJ1_25	To PCB_all.PcbDoc	
Add	NetJ1_26	To PCB_all.PcbDoc	
Add	NetJ1_27	To PCB_all.PcbDoc	
Add	NetJ1_28	To PCB_all.PcbDoc	
Add	NetJ1_29	To PCB_all.PcbDoc	
Add	NetL2_2	To PCB_all.PcbDoc	
Add	NetL3_2	To PCB_all.PcbDoc	
Add	NetL4_2	To PCB_all.PcbDoc	
Add	NetL5_2	To PCB_all.PcbDoc	
Add	NetL6_2	To PCB_all.PcbDoc	
Add	NetL8_1	To PCB_all.PcbDoc	
Add	NetL9_1	To PCB_all.PcbDoc	
Add	NetL10_1	To PCB_all.PcbDoc	
Add	NetL11_1	To PCB_all.PcbDoc	
Add	NetL24_2	To PCB_all.PcbDoc	
Add	NetR11_1	To PCB_all.PcbDoc	
Add	NetR23_2	To PCB_all.PcbDoc	
Add	NetR24_2	To PCB_all.PcbDoc	
Add	NetR25_1	To PCB_all.PcbDoc	
Add	NetR26_1	To PCB_all.PcbDoc	
Add	NetR27_1	To PCB_all.PcbDoc	
Add	NetR28_1	To PCB_all.PcbDoc	
Add	NetR29_1	To PCB_all.PcbDoc	
Add	NetR30_1	To PCB_all.PcbDoc	
Add	NetR31_1	To PCB_all.PcbDoc	
Add	NetR32_1	To PCB_all.PcbDoc	
Add	NetR33_1	To PCB_all.PcbDoc	
Add	NetR34_1	To PCB_all.PcbDoc	
Add	NetR35_1	To PCB_all.PcbDoc	
Add	NetR36_1	To PCB_all.PcbDoc	
Add	NetR37_1	To PCB_all.PcbDoc	
Add	NetR38_1	To PCB_all.PcbDoc	
Add	NetR39_1	To PCB_all.PcbDoc	
Add	NetR40_1	To PCB_all.PcbDoc	
Add	NetR41_1	To PCB_all.PcbDoc	
Add	NetR42_1	To PCB_all.PcbDoc	
Add	NetR43_1	To PCB_all.PcbDoc	
Add	NetR44_1	To PCB_all.PcbDoc	
Add	NetR45_1	To PCB_all.PcbDoc	
Add	NetR46_1	To PCB_all.PcbDoc	
Add	NetR47_1	To PCB_all.PcbDoc	
Add	NetR48_1	To PCB_all.PcbDoc	
Add	NetR49_2	To PCB_all.PcbDoc	
Add	NetR50_1	To PCB_all.PcbDoc	

Action	Object	Change Document	Status
Add Nets			
Add	NetR51_1	To PCB_all.PcbDoc	
Add	NetR54_1	To PCB_all.PcbDoc	
Add	NetR55_1	To PCB_all.PcbDoc	
Add	NetR56_1	To PCB_all.PcbDoc	
Add	NetR57_1	To PCB_all.PcbDoc	
Add	NetR58_1	To PCB_all.PcbDoc	
Add	NetR59_2	To PCB_all.PcbDoc	
Add	NetR60_1	To PCB_all.PcbDoc	
Add	NetR61_1	To PCB_all.PcbDoc	
Add	NetR63_1	To PCB_all.PcbDoc	
Add	NetR64_1	To PCB_all.PcbDoc	
Add	NetR65_1	To PCB_all.PcbDoc	
Add	NetR66_1	To PCB_all.PcbDoc	
Add	NetR67_1	To PCB_all.PcbDoc	
Add	NetR68_1	To PCB_all.PcbDoc	
Add	NetR69_1	To PCB_all.PcbDoc	
Add	NetR70_1	To PCB_all.PcbDoc	
Add	NetR71_1	To PCB_all.PcbDoc	
Add	NetR72_1	To PCB_all.PcbDoc	
Add	NetR73_1	To PCB_all.PcbDoc	
Add	NetR74_1	To PCB_all.PcbDoc	
Add	NetR75_1	To PCB_all.PcbDoc	
Add	NetR76_1	To PCB_all.PcbDoc	
Add	NetR77_1	To PCB_all.PcbDoc	
Add	NetR78_1	To PCB_all.PcbDoc	
Add	NetR79_1	To PCB_all.PcbDoc	
Add	NetR80_1	To PCB_all.PcbDoc	
Add	NetR81_1	To PCB_all.PcbDoc	
Add	NetR82_1	To PCB_all.PcbDoc	
Add	NetR83_1	To PCB_all.PcbDoc	
Add	NetR84_1	To PCB_all.PcbDoc	
Add	NetR85_1	To PCB_all.PcbDoc	
Add	NetR86_1	To PCB_all.PcbDoc	
Add	NetR87_1	To PCB_all.PcbDoc	
Add	NetR88_1	To PCB_all.PcbDoc	
Add	NetR89_1	To PCB_all.PcbDoc	
Add	NetR90_1	To PCB_all.PcbDoc	
Add	NetR91_1	To PCB_all.PcbDoc	
Add	NetR92_1	To PCB_all.PcbDoc	
Add	NetR93_1	To PCB_all.PcbDoc	
Add	NetR94_1	To PCB_all.PcbDoc	
Add	NetR95_1	To PCB_all.PcbDoc	
Add	NetR96_1	To PCB_all.PcbDoc	
Add	NetR97_1	To PCB_all.PcbDoc	
Add	NetR100_1	To PCB_all.PcbDoc	
Add	NetR101_1	To PCB_all.PcbDoc	
Add	NetR102_1	To PCB_all.PcbDoc	
Add	NetR103_1	To PCB_all.PcbDoc	
Add	NetR104_1	To PCB_all.PcbDoc	
Add	NetR105_1	To PCB_all.PcbDoc	
Add	NetR106_1	To PCB_all.PcbDoc	
Add	NetR107_1	To PCB_all.PcbDoc	
Add	NetR111_2	To PCB_all.PcbDoc	
Add	NetR113_1	To PCB_all.PcbDoc	
Add	NetR114_1	To PCB_all.PcbDoc	
Add	NetR115_1	To PCB_all.PcbDoc	
Add	NetR118_1	To PCB_all.PcbDoc	
Add	NetR119_2	To PCB_all.PcbDoc	
Add	NetR120_2	To PCB_all.PcbDoc	
Add	NetR121_2	To PCB_all.PcbDoc	
Add	NetR122_2	To PCB_all.PcbDoc	
Add	NetR123_2	To PCB_all.PcbDoc	
Add	NetR124_2	To PCB_all.PcbDoc	
Add	NetR125_2	To PCB_all.PcbDoc	
Add	NetR126_2	To PCB_all.PcbDoc	
Add	NetR127_2	To PCB_all.PcbDoc	
Add	NetR128_2	To PCB_all.PcbDoc	
Add	NetR129_2	To PCB_all.PcbDoc	
Add	NetR130_2	To PCB_all.PcbDoc	

Add Nets

Action	Object	Change Document	Status
Add	NetR131_2	To PCB_all.PcbDoc	
Add	NetR132_2	To PCB_all.PcbDoc	
Add	NetR133_2	To PCB_all.PcbDoc	
Add	NetR134_2	To PCB_all.PcbDoc	
Add	NetR135_2	To PCB_all.PcbDoc	
Add	NetR136_2	To PCB_all.PcbDoc	
Add	NetR137_2	To PCB_all.PcbDoc	
Add	NetR138_2	To PCB_all.PcbDoc	
Add	NetR139_2	To PCB_all.PcbDoc	
Add	NetR140_2	To PCB_all.PcbDoc	
Add	NetR141_2	To PCB_all.PcbDoc	
Add	NetR142_2	To PCB_all.PcbDoc	
Add	NetR143_2	To PCB_all.PcbDoc	
Add	NetR144_2	To PCB_all.PcbDoc	
Add	NetR145_2	To PCB_all.PcbDoc	
Add	NetR146_2	To PCB_all.PcbDoc	
Add	NetR147_2	To PCB_all.PcbDoc	
Add	NetR148_2	To PCB_all.PcbDoc	
Add	NetR149_2	To PCB_all.PcbDoc	
Add	NetR150_2	To PCB_all.PcbDoc	
Add	NetR151_2	To PCB_all.PcbDoc	
Add	NetR152_2	To PCB_all.PcbDoc	
Add	NetR153_2	To PCB_all.PcbDoc	
Add	NetR154_2	To PCB_all.PcbDoc	
Add	NetR155_2	To PCB_all.PcbDoc	
Add	NetR156_2	To PCB_all.PcbDoc	
Add	NetR157_2	To PCB_all.PcbDoc	
Add	NetR158_2	To PCB_all.PcbDoc	
Add	NetR159_2	To PCB_all.PcbDoc	
Add	NetR160_2	To PCB_all.PcbDoc	
Add	NetR161_2	To PCB_all.PcbDoc	
Add	NetR162_2	To PCB_all.PcbDoc	
Add	NetR163_2	To PCB_all.PcbDoc	
Add	NetR164_2	To PCB_all.PcbDoc	
Add	NetR165_2	To PCB_all.PcbDoc	
Add	NetR166_2	To PCB_all.PcbDoc	
Add	NetR167_2	To PCB_all.PcbDoc	
Add	NetR168_2	To PCB_all.PcbDoc	
Add	NetR171_2	To PCB_all.PcbDoc	
Add	NetR172_2	To PCB_all.PcbDoc	
Add	NetR173_1	To PCB_all.PcbDoc	
Add	NetR174_1	To PCB_all.PcbDoc	
Add	NetR175_1	To PCB_all.PcbDoc	
Add	NetR176_1	To PCB_all.PcbDoc	
Add	NetR177_1	To PCB_all.PcbDoc	
Add	NetR179_1	To PCB_all.PcbDoc	
Add	NetR185_2	To PCB_all.PcbDoc	
Add	NetR186_2	To PCB_all.PcbDoc	
Add	NetR188_1	To PCB_all.PcbDoc	
Add	NetR189_1	To PCB_all.PcbDoc	
Add	NetR190_1	To PCB_all.PcbDoc	
Add	NetR191_1	To PCB_all.PcbDoc	
Add	NetR192_1	To PCB_all.PcbDoc	
Add	NetR196_1	To PCB_all.PcbDoc	
Add	NetR202_1	To PCB_all.PcbDoc	
Add	NetR207_2	To PCB_all.PcbDoc	
Add	NetR209_2	To PCB_all.PcbDoc	
Add	NetR214_2	To PCB_all.PcbDoc	
Add	NetR216_2	To PCB_all.PcbDoc	
Add	NetR218_2	To PCB_all.PcbDoc	
Add	NetR231_2	To PCB_all.PcbDoc	
Add	NetR232_2	To PCB_all.PcbDoc	
Add	NetR233_2	To PCB_all.PcbDoc	
Add	NetR234_2	To PCB_all.PcbDoc	
Add	NetR235_2	To PCB_all.PcbDoc	
Add	NetR236_1	To PCB_all.PcbDoc	
Add	NetR238_1	To PCB_all.PcbDoc	
Add	NetR239_1	To PCB_all.PcbDoc	
Add	NetRX_CLK+_4	To PCB_all.PcbDoc	

Action	Object	Change Document	Status

Add Nets

Action	Object	Change Document	Status
Add	NetRX_CLK_4	To PCB_all.PcbDoc	
Add	NetRX_D0+_4	To PCB_all.PcbDoc	
Add	NetRX_D0-_4	To PCB_all.PcbDoc	
Add	NetRX_D1+_4	To PCB_all.PcbDoc	
Add	NetRX_D1-_4	To PCB_all.PcbDoc	
Add	NetRX_D2+_4	To PCB_all.PcbDoc	
Add	NetRX_D2-_4	To PCB_all.PcbDoc	
Add	NetU1_2	To PCB_all.PcbDoc	
Add	NetU1_11	To PCB_all.PcbDoc	
Add	O3_3V	To PCB_all.PcbDoc	
Add	OSD_B	To PCB_all.PcbDoc	
Add	OSD_CLK	To PCB_all.PcbDoc	
Add	OSD_G	To PCB_all.PcbDoc	
Add	OSD_HS	To PCB_all.PcbDoc	
Add	OSD_R	To PCB_all.PcbDoc	
Add	OSD_VS	To PCB_all.PcbDoc	
Add	P3_3V	To PCB_all.PcbDoc	
Add	P3V3	To PCB_all.PcbDoc	
Add	PDO	To PCB_all.PcbDoc	
Add	PD	To PCB_all.PcbDoc	
Add	PKA_GND	To PCB_all.PcbDoc	
Add	POWER_ON_OFF	To PCB_all.PcbDoc	
Add	PSC0	To PCB_all.PcbDoc	
Add	PSC1	To PCB_all.PcbDoc	
Add	R_INA0	To PCB_all.PcbDoc	
Add	R_INA1	To PCB_all.PcbDoc	
Add	R_INA2	To PCB_all.PcbDoc	
Add	R_INA3	To PCB_all.PcbDoc	
Add	R_INA4	To PCB_all.PcbDoc	
Add	R_INA5	To PCB_all.PcbDoc	
Add	R_INA6	To PCB_all.PcbDoc	
Add	R_INA7	To PCB_all.PcbDoc	
Add	R_INB0	To PCB_all.PcbDoc	
Add	R_INB1	To PCB_all.PcbDoc	
Add	R_INB2	To PCB_all.PcbDoc	
Add	R_INB3	To PCB_all.PcbDoc	
Add	R_INB4	To PCB_all.PcbDoc	
Add	R_INB5	To PCB_all.PcbDoc	
Add	R_INB6	To PCB_all.PcbDoc	
Add	R_INB7	To PCB_all.PcbDoc	
Add	R_IN	To PCB_all.PcbDoc	
Add	RA0	To PCB_all.PcbDoc	
Add	RA1	To PCB_all.PcbDoc	
Add	RA2	To PCB_all.PcbDoc	
Add	RA3	To PCB_all.PcbDoc	
Add	RA4	To PCB_all.PcbDoc	
Add	RA5	To PCB_all.PcbDoc	
Add	RA6	To PCB_all.PcbDoc	
Add	RA7	To PCB_all.PcbDoc	
Add	RB0	To PCB_all.PcbDoc	
Add	RB1	To PCB_all.PcbDoc	
Add	RB2	To PCB_all.PcbDoc	
Add	RB3	To PCB_all.PcbDoc	
Add	RB4	To PCB_all.PcbDoc	
Add	RB5	To PCB_all.PcbDoc	
Add	RB6	To PCB_all.PcbDoc	
Add	RB7	To PCB_all.PcbDoc	
Add	ROM_SCL_ASIC	To PCB_all.PcbDoc	
Add	ROM_SCL_EEPROM	To PCB_all.PcbDoc	
Add	ROM_SCL	To PCB_all.PcbDoc	
Add	ROM_SDA	To PCB_all.PcbDoc	
Add	SCDT	To PCB_all.PcbDoc	
Add	VCLK00	To PCB_all.PcbDoc	
Add	VCLK01	To PCB_all.PcbDoc	
Add	VGA_CONN	To PCB_all.PcbDoc	
Add	VGA_CON	To PCB_all.PcbDoc	
Add	VGA_HS	To PCB_all.PcbDoc	
Add	VGA_SCL	To PCB_all.PcbDoc	
Add	VGA_SDA	To PCB_all.PcbDoc	

Add Nets

Add	VGA_VS	To PCB_all.PcbDoc	
Add	VLCK00	To PCB_all.PcbDoc	
Add	VSYNC_D	To PCB_all.PcbDoc	
Add	VSYNC_IN	To PCB_all.PcbDoc	
Add	VSYNC_MCU	To PCB_all.PcbDoc	

Add Component Classes

Add	31	To PCB_all.PcbDoc	
Add	32	To PCB_all.PcbDoc	
Add	33	To PCB_all.PcbDoc	
Add	34	To PCB_all.PcbDoc	
Add	35	To PCB_all.PcbDoc	
Add	36	To PCB_all.PcbDoc	
Add	VGA	To PCB_all.PcbDoc	

Add Net Classes

Add	B_INA[0..7]	To PCB_all.PcbDoc	
Add	B_INB[0..7]	To PCB_all.PcbDoc	
Add	G_INA[0..7]	To PCB_all.PcbDoc	
Add	R_INA[0..7]	To PCB_all.PcbDoc	

Add Rooms

Add	Room 31 (Scope=InComponentClass('31')) TopLayer	To PCB_all.PcbDoc	
Add	Room 32 (Scope=InComponentClass('32')) TopLayer	To PCB_all.PcbDoc	
Add	Room 33 (Scope=InComponentClass('33')) TopLayer	To PCB_all.PcbDoc	
Add	Room 34 (Scope=InComponentClass('34')) TopLayer	To PCB_all.PcbDoc	
Add	Room 35 (Scope=InComponentClass('35')) TopLayer	To PCB_all.PcbDoc	
Add	Room 36 (Scope=InComponentClass('36')) TopLayer	To PCB_all.PcbDoc	
Add	Room VGA (Scope=InComponentClass('VGA')) TopLayer	To PCB_all.PcbDoc	