

Changes -

- Moved tubes at the rear of the chassis to create space for the trailing arm suspension, roughly 6 inches of space available now for it
- Redid some of the triangulation for the roll hoop to reduce stress concentration