



Changes

- Lowered front of chassis down to 16in
- Overall height down to 46in
- Fixed error in rear chassis where it was angled inwards, which increased volume electrical has to their stuff
- o Triangulation on the bottom, front, and rear of the car has been changed
- Roll hoop has been tightened to better fit the driver, and the front roll hoop has been angled more backwards for easier egress

Potential Future Changes

o Fix seat, Victor doesn't believe its size

Notes

 Seat dimensions need to be re-evaluated to clarify proper sizing of occupant cell and calm Victor still