


# Verilog Debugging Tool - nWave

Speaker: 王景平




### **How to Debug**






#### **nWave**


- A waveform analysis tool for viewing \*.fsdb & \*.vcd waveform files
- For school workstation, source license first
  - source /usr/cad/cadence/cshrc
  - source /usr/spring\_soft/CIC/verdi.cshrc
- Invoke nWave
  - ❖ > nWave &
- Open waveform file
  - .fsdb or .vcd





### **Select Signals to View**









### **Drag Selected Signals**






#### **Shift windows** Viewing Tools







**Select Value Notation** 



## Reload New Waveform File (Shift+L)

❖ You don't need to re-open nWave to reload a new waveform file! → Shift+L

