ክፍል አንድ

1,00906

የምርታማነት ማሻሻያና የልህቀት ማዕከል ፣ የከተማ አስተዳደሩ ከያዘው ፌጣንና ዘላቂነት የልማት አባልግሎት በመነሳት ከሌሎች አጋር መስሪያ ቤቶች በጋራ በመሆን ተልዕኮውን እየተወጣ ያለ መሆኑ ይታወቃል በመሆኑም የአዲስ አበባ ቴክኒክ ሙያ ስልጠና እና ቴክኖሎጂ ልማት ቢሮ በጠየቀው የስራ እንቅስቀሴ ላይ ከማዕከላችንና ከልደታ ማፋክቸሪንን ኮሎጂ የተወጣጣ ወደ 8 አባላትያሉት አስልጣኞች የተዋቀረ ሲሆን ለከተማችን 11 ክፍለ ከተማ ለሆነችው ለሚኩራ ክፍለ ከተማ ወደ 9 ለሚሆኑ ወረዳዎች ማለትም ወረዳ 2፣3፣4፣5፣6፣8፣9፣10፣13፣14 ሙያዊ ድጋፍ ያደረገ ሲሆን የተሰራው ስራ አፈፃፀም ፣ያጋጠሙ ችግሮች እና መፍትሄዎች፣የቀጣይ የትኩረት አቅጣጫና ማጠቃለያን በማካተት እንደሚከተለው ቀርቧል።

ክፍል ሁለት

2. ዕቅዱ ዓላማ / Objective/

የዚህ እቅድ ዋነኛ ዓላማ በክፍለ ከተማ ምን ያህል ኮምፒዊተሮች ፕሪንተሮችና እና ፎቶ ኮፒ ማሽኖች እንዱሁም ስካነሮች እንደሚሰሩ ለመለየትና ተገና የሚያስፌል,ንቸውን በመለየት ወደስራ ለማስገባት ነው፡፡

የተሰሩ ስራዎች በዝርዝር

በለሚ ኩራ ክፍለ ከተማ ለሚገኙ 9 ወረዳዎች ማለትን ወረዳ 2,3,4,5,8,9,10,,13,14 ከቀን 16/03/2015 እስከ ቀን 19/03/2015 የተሰሩ ስራዎች

ማስታወሻ

ከተዘረዘሩት ውስጥ ፎቶ ኮፒ ማሸኖቹ ማለትም አስሩም (10) ብናያቸውም በኛ የሚጠገኑ ሳይሆኑ ሰርቪስ በሚሰጥ አካል የሚታዩ *መ*ሆናቸውን እንገልፃለን፡፡

ጠቅለል ባለ <i>መ</i> ልኩ የታዩ <i>እቃዎች</i>							
ወረዳ	ኮምፒውተር	ፕ <i>ሪ</i> ንተር	ፎቶኮፒ ማሽን	ስካነር			
02	4	3	0	0			
03	15	5	3	0			
04	7	6	-	1			
05	0	0	0	0			
06	5	8	0	0			
08	10	18	3	0			
09	6	5	0	0			
10	8	20	3	1			
13	11	14	0	0			
14	10	2	1	0			
ድምር	76	81	10	2			

የታዩ ኮምፒውተሮች ዝርዝርና የሚያስፈልጉ እቃዎች							
ተ/ቁ	ወሬዳ	ኮምፒዊተር	ብዛት	ሞዴል ቁትር	የሚያስፌልገው እቃ	ምርመራ	
	02	Hp-compact	1	Hp-compact	RAM		
	02	Dell optiplex	3	3050	Software		
		Dell	1	3050	Power supply		
		Dell	1	3050	Monitor screen		
		Dell	1	3060	Hard drive		
		Dell	1	7040	Software and fan		
	03	Dell	1	7010	Operating system		
		Dell	1	3060	Operating system		
		Dell	3	3050	Mother board/hard drive		
		Dell	3	3050	Hard disk		
		Dell	1	780	Software		
		Dell optiplex	1	3080	display port		
		Нр	1		software		
	04	Dell optiplex	2	3090	display port and Software(os)		
		Dell optiplex	2	5070	display port and Software(os)		
		Dell optiplex	1	745	software(os)		
		Dell optiplex	1	7010	RAM, software, CMOS battery		
	06	Dell optiplex	1	780	power supply		
		Dell optiplex	1	3040	Power supply, RAM, CMOS battery		
		Dell optiplex	1	3080	software		

	Dell optiplex	1	3020	Power supply	
	Dell optiplex	2	7010	RAM, Hard disk, power supply	
	Dell optiplex	2	3060	power supply, software(os)	
	Dell optiplex	1	3020	power supply, Hard disk	
08	Нр	1	pro	Hard disk	
	Dell optiplex	1	7020	Power supply	
	Dell optiplex	1	790	Hard disk, RAM, CPU, power supply	
	Dell optiplex	1	3050	Hard disk , power	
	Dell optiplex	1	780	Power supply , RAM	
	Dell optiplex	1	3060	Operating system	
	Dell optiplex	1	7010	Operating system	
09	Dell optiplex	1	7080	CPU hit Sinker	
	Dell optiplex	1	3050	Power supply and RAM	
	Dell optiplex	1	3050	RAM/System board	
	Dell optiplex	1	7010	Software	
	Dell	1	3070	Hard disk & software	
	Vostro	1	Vostro	Power supply	
10	Dell	1	3020	Power button	
	Dell	2	3070	Hard disk & software	
	Dell opteplex	3	3050	Software	
13	Dell optiplex	3	780	RAM, software(os), case, software(os)	
	Dell optiplex	1	710	Power supply, Hard disk	

	Dell optiplex	1	3050	Hard dsik, RAM	
	Dell optiplex	1	7020	power supply	
	Dell optiplex	1	5040	power supply	
	Dell optiplex	1	790	RAM	
	Dell	1	3050	Mother board	
	Dell	1	3050	Power supply	
	Dell	2	3050	Monitor screen	
	Dell	1	3060	Mother board/cpu	
14	4 Dell	1	5040	Mother board/cpu	
	Dell	1	5040	Power supply & Ram	
	Dell	2	3020	Power supply	
	Dell	1	3060	Power supply	
	Dell	1	5040	Power supply	

	የታዩ ፕሪንተሮች ዝርዝርና የሚያስፈልጉ						
ተ/ቁ	ወረዳ	ኮምፒዊተር	ብዛት	ሞዴል ቁትር	የሚያስፈልገው እቃ	ምርመ ራ	
	02	Hp-laser jet	1	Fs-2100	Toner miss		
	02	Lexmark	1	Ms-610dn	Pick up roller		
		Kyocera Ecosys	1	Fs-2100	Developer unit and toner		
		Kyocera Ecosys	1	p-2040dn	Developer unit and toner		
	03	Kyocera Ecosys	1	p-2040dn	Developer unit and toner		
		Hp Laser jet pro	1	p-2055d	toner		
		Hp laser jet	1	p-m402	Gs-052,chip /toner		
		Kyocera Ecosys	2	P2040-dn	Developer unit and toner		
		Kyocera Ecosys	1	3145-dn	Developer unit and toner		
	04	Kyocera Ecosys	1	3145-dn	Fixing Unit		
		Hp LaserJet pro	1	M404n	Fixing Unit		
		Kyocera Ecosys	1	Fs-1025mfp	Fixing Unit		
		Kyocera Ecosys	2	P2040-dn	Developer unit and toner		
		Kyocera Ecosys	1	Fs-1025mfp	Power bored E.C.U		
	06	Kyocera Ecosys	4	P2040-dn	Power bored E.C.U		
		Kyocera	1		-		
	00	Hp-laser jet pro	2	404dn	Easy maintain		
	08	Hp-laser jet pro	5	2055	Formatter board ,Control board		

	Hp laser jet pro	4	P400 - m401d	Formatter board
	Hp laser jet pro	2	P400 - m401d	Formatter board and Control board
	Hp laser jet	1	P402dn	Formatter board
	Hp laser jet pro	1	M404dn	Drum unit
09	Hp laser jet pro	1	M402n	Dust problem
	Hp laser jet pro	2	400 m401a	Formatter board
	Hp laser jet	1	P-2055	Formatter board
	Hp-laser jet pro	1	p-400	Service/ Developer unit and toner
10	Kyocera Ecosyst	1	M2440idw	Reset fuser roller system
	Kyocera Ecosys	1	Fs-2100	Developer unit and toner
	Kyocera Ecosys	2	Fs-3045	Developer unit toner
	Hp-laser jet pro	2	p-400	Control board and formatter board
	Hp-laser jet pro	3	p-2015	Formatter board and pickup roller
	Hp –laser jet	2	M402dn	Power board control board/dev unit
	Hp –laser jet	1	p-400	Formatter board
	Lexmark	1	Ms-810dn	Developer unit with toner
	Hp laser jet pro	1	P1102	Power board/E.C.U
	Lexmark	2	Ms-415dn	Developer unit and toner
	Hp laser jet	1	P4014	cartilage
13	Hp laser jet	1	M402d	Transfer roller
	Kyocera Ecosys	1	M2640idw	Developer unit
	Kyocera Ecosys	1	P3045dn	Developer unit and toner
	Lexmark	1	Ms 415dn	Power board/E.C.U
	Laser jet pro	3	400 m401a	Formatter board

	Kyocera	1	P2040dn	toner	
	Lexmark	2	Ms 415dn	Easy maintain	
	Hp-laser jet	1	p-m402dne	Power bored/ E.C.U	
14	Hp-laser jet	1	p-400	Formatter board	

በስራው ላይ ያጋጠሙ ተግዳሮቶች

- 1, በሄድንባቸው ወረዳዎች ሰለ ታሰበው ስራ እና ስለ እኛ *መምጣት ምንም አይነት ምርጃ* አለ*መ*ኖር
- 2. ይጠገናሉ ተብለው ከተሳክው ቀጥር በታች አንዳንድ ቦታ ደግሞ በሳይ ማግኘት
- 3. የሚጠንኑ ንብረቶች ለማየት አስቸጋሪ ቦታ ላይ ማስቀመጥ
- 4, ንብረቶቹ በየቢሮው መሆናቸው
- 5, እኛን ወደንብረቶቹ የሚወስድ አካል ያለምግንት
- 6. ለመለየት የሄደውን ሰው ንብረቶችን ይዞ ወደ መሞከሪያ ቦታ ለመውሰድ የጉልበት ስራ ማሰራት
- 7. የሰራተኞች ስብሰባ ላይ መሆን ፣ የ አንዳንድ ቢሮዎች ዝግ መሆን

የተወሰዱ መፍትሄዎች

- የሚለዩ ኮምፒተሮችንና ፐሪንተሮችን በመሸከም ወደ መሞከሪያ ቦታ መውሰድ
- ለማየትም ሆነ ለመሞከር አስቸጋሪ የሆኑትን በተቻለ መጠን ለማየት ሞክረናል
- በሁሉም ወረዳዎች በየቢሮው በመዞር የመለየት ስራ መስራት

*ማ*ጠቃለያ

እቃ ከተሟላሳቸው መልሰው አገልግሎት መስጠት የሚችሉትን በሚከተለው መልኩ በአጭሩ ለማስቀመጥ ተሞክሯል፡፡

- 1. ኮምፒውተር ብዛት----**›**70
- 2. ፕሪንተር ብዛት-----65