*Possibility of a branch with a zero magnetic flux.* In a magnetic circuit with several nodes and branches, nonlinear magnetization curves of the core materials, and more than one magnetomotive force (winding with current), it is possible to have a branch with a zero magnetic flux.

- (A) True.
- (B) False.

Solution: (A)
Answer: (A)