Cranberry logger : RootLogger, Logger, NoneType receive log()

Cranberry addr close: bool logger : RootLogger, NoneType, Logger port server socket: socket communicate by thread(client socket, addr) initialize server() run server() set logger()

ProfileMonitor REQUEST : pvproperty STATUS: pvproperty connected: bool gpio last status: int, NoneType number request queue status queue check connection()

handle screen()

update status(request)