designation	qte	observation	nordre
Bergadeur75	4.000	null	1
fumier de vaches	2.000	null	16
Bergadeur75	4.000	null	1
Berga 50	2.000	null	2

designation	qte	observation	nordre
gg20-300m	1.000	null	3
gg10mm/2000	1.000	null	4
manchant75	3.000	null	5
Bouchon75	1.000	null	6

designation	qte	observation	nordre
Collier de prise 75/50 tn	3.000	null	7
memlon50/50	3.000	null	8
vanne 50+racc turk	3.000	null	9
teNoir75 male	1.000	null	10

designation	qte	observation	nordre
memlon 75/75	2.000	null	11
vanne75+raccord alfa	2.000	null	12
Raccort75	1.000	null	13
vanne 50+racc turk	1.000	1	1

designation	qte	observation	nordre
vanne 50+racc turk	1.000	null	1