

Customer Repair Report

_				•	•				
Model	Serial Number	Manufacture Da	ate	RMA Number	IRIDEX Service Contact	Completio	n Date		
OTHER	GH16675I			02386	Mark W				
Customer Name		Customer Number	Repa	ir Type			_		
Topcon Europe Medical B.V.		14251	14251 Warranty non-warranty			Upgrade Other			
Customer Description									
is not detected by a GLx	(check and ve	erify its PCB operat	tions)						
Technician Product	Evaluate:								
Repalced fiber, Test, clear	n and inspec.								
Service Performed o	n Unit:								
Waiting for customer a									
		ITEMIZED	RE	PAIR CHARG	SES				
Part Number	Price/Unit	Quantity		D	escription		Total Price		
31158-01		1		ASSY GL/G	GLX JUMPER 9' 50/125u		\$	500.00	
TECHNICIAN HQ		2.5		T	echnician Labor		\$	712.50	
			_		TOTAL CIL	ADCEC	φ	1 212 50	
					TOTAL CH	AKGES	\$	1,212.50	
Repaired products may conta and are warranted as such. T in the IRIDEX Standard War Freight and sales tax will be	he labor and part ranty Statement.	s are guaranteed for 90 Your signature below	0 days a	fter the ship date of th	ne product. Items not cove	red in the w			
D. W									
Print Name:									