

				•	•		
Model Serial Num		mber Manufacture Date		RMA Number	IRIDEX S	ervice Contact	Completion Date
OTHER	1355855			01959	Mai	rk W	
Customer Name		Customer Number R		Repair Type			
Retina Consultants of Fargo Ltd.		10778		☐ Warranty ☐ Upgrade ☐ Other			
Customer Description of I KNOB LOOSE IN BACK		provides a r	epair completi	on and need estimate			
Technician Product Evaluat Cannot test due to twisto Service Performed on Uni	ed and bur	nt assembly	fiber optic, bu	rnt Heine halogen bu	ılb, loose rear knob	of headbnad a	and will need alignment.
Waiting for customer appr							
ITEMIZED REPAIR CHARGES							
Part Number	I	Price/Unit	Quantity		Description		Total Price
65867			1		SY JUMPER LIC	\$984.00	
10784			1	LIO	Halogen Bulb-10	\$105.00	
11481			1	DUS	ST CAP W/LANYAR	D DART	3.00
		*			TAX		4000 50
LABOR HOURS SHIPPING & HANDLING		\$285.00	4.5		Service Labor Ho	1282.50	
				F	edEx 2- Day Se	\$191.60 RGES \$2,566.10	
						TOTAL CHA	RGE3
Repaired products may cont materials and are warranted are stated in the IRIDEX Sta Freight and sales tax will be	as such. Th andard Wari	e labor and pranty Statem	parts are guaran ent. Your signa	teed for 90 days after t	he ship date of the p	roduct. Items n	ot covered in the warranty
Print Name: Melissa	Krame						
Signature:	lissi	a Ki	rame	r	Date:	10/22/2024	<u> </u>

1212 Terra Bella Ave. Mountain View, CA 94043 • Ph: 650.962.8100 • FAX 650.967.4093

ECO4507 FRM990304B