## いかよ 71

- O classification of measuring instrument.
- 1) type of error
- 3 Explain essential requirement of indicating
- D what three force required for sentifactory operating or an analog most rument
  - (5) what do you mean by static characteristics of measuring instrument.

## unit-2

De write difference b/w Amneter and valencer

- D'Explain Rechifier type vallmeter.
- & Explain crand pr
  - 1 Explain clamp on meter (tong testor) a unit -3

## Dexpedin PMMc instrument.

- @ Experis me instrument.
- 3 Explain syrameter type walt meter
- \* Explain two weethneter method.
- 3) merz price maximum demand indictor.
- D expeain single prage induction type energy neter D Explain groor and their compensation.
- & Experin calibration of cenergy meter
  - 1 Explain alectronic Energy meter

## Unit 4,5

- D'experin kelvin's double bridge.
- @ Expenin measurement et Resistance by vallmetre
- 1 Explois about megger.
- € Experin schering bridge and Anderson bridge.
- @ Expain cro and CRT
- O Ex kain forguency meter.
- 1 Expain, Synchr Scope.
  - @ Explain P.F meter.
  - 1 Expenis earth tester.

· L. C. R meter