

Objective Questions For 3-D Printing & Design

- 1. Which of the following is typically cheapest type of 3-d Printer?
 - a) FDM
 - b) SLA
 - c) Power-Based
 - d) SLM
- 2. SLA printing uses a plastic strand that's pushed through a heated nozzle.
 - a) True
 - b) False
- 3. 3D printing Technology is expending and is now able to print metal parts.
 - a) True
 - b) False
- 4. Which of the following is typically the most expensive type of 3d printer?
 - a) SLA
 - b) SLM
 - c) FDM
 - d) None of these
- 5. FDM is stand for Fused Deposition Modelling
 - a) True
 - b) False

| 6 | Whic | h type of printer uses an enclosed build area? |
|---|-------|--|
| 0. | a) | SLA |
| | ~ | SLM |
| | | MDS |
| | | FDM |
| 7. | | t printer melts metal? |
| | a) | SLS |
| | | SLM |
| | | SLA |
| | , | FDM |
| 8. | SLA | printer package material is in a |
| | a) | Chain |
| | b) | Spool |
| | c) | Catridge |
| | d) | None of the above |
| 9. Which type of 3D printer uses a pool of resin to create the so | | |
| | parts | |
| | a) | FDM |
| | b) | SLA |
| | c) < | SNL |
| | d) | None of the Above |
| | 11 | |
| 10. What material is not used in 3d printing | | t material is not used in 3d printing |
| | a) | Nylon |
| | b) | ABS |
| | c) | PLA |
| | d) | PVC |
| | | |

- 11. Which of the following does NOT influence how refined the 3D printer part will be ?
 - a) Layer Thickness
 - b) Using support material
 - c) Part Orientation
 - d) All of the above
- 12. Which file type is most commonly exported from CAD software.
 - a) SLDRT
 - b) JPG
 - c) STL
 - d) X3G
- 13. FDM build plates are prepared by
 - a) Putting hair spray on it
 - b) Putting layer of painters tape on it
 - c) Putting glue stick layer on it
 - d) All of the above
- 14. What does SLS stand for?
 - a) Selective laser sintering
 - b) Selective lithography solution
 - c) Separated light sintering
 - d) None of these
- 15. The first step in each product design process is to and conceptualize the function and appearance of the product....
 - a) Summarize
 - b) Imagine
 - c) Visualize
 - d) None of these

- 16. The STL format of the 3D CAD model captures all surfaces of the 3d model by stitching of different sizes on its surface.....
 - a) Angles
 - b) Triangles
 - c) Planes
 - d) All of the above
- 17. The outside of the triangle is better established by the....
 - a) Left hand rule approach
 - b) Right hand rule approach
 - c) Thumb rule approach
 - d) None of the above
- 18. The appropriate value of the required offset would be largely dependent on the of the AM process to be used....
 - a) Resolution of accuracy
 - b) Precision of accuracy
 - c) Threshold
 - d) All of the above
- 19. The identification of the to be assisted can be made by evaluating the angle of the standard triangle.....
 - a) Surface
 - b) Plane
 - c) Face
 - d) Region
- 20. Which technology requires a filling pattern to be produced within the enclosed boundary?
 - a) Binder jetting
 - b) Material extrusion
 - c) Vat polymerization
 - d) None of the above

- 21. Stainless Steel is printed by fusion of.....
 - a) Sterolithography
 - b) Laser sintering
 - c) Material jetting
 - d) None of the above
- 22. SLA has been developed on the basis of
 - a) Photopolymerization
 - b) Material jetting
 - c) Drop on demand
 - d) None of the above
- 23. The sintering temperature of the printed ceramic component can affect the fraction of the metal phase.....
 - a) Viscosity & gravity
 - b) Thickness & length
 - c) Density & Volume
 - d) All of the above
- 24. The 3d printing of ceramics was first documented by MARCUS et al. and Sachs in
 - a) 1990s
 - b) 1980s
 - c) 1970s
 - d) 1960s
- 25. Parts produced using a 3d printer must be designed using some kind of
 - a) CATIA
 - b) ProE
 - c) CAD
 - d) Manual Design