# MARITIME INCIDENT REPORT - SAMPLE FOR TESTING

### **INCIDENT REPORT NO: MIR-2025-0820**

DATE OF INCIDENT: August 15, 2025

TIME: 14:30 UTC

LOCATION: 35°42'N, 139°46'E (Tokyo Bay, Japan)

#### **VESSEL INFORMATION:**

Vessel Name: MV Ocean PioneerIMO Number: 9876543210

• Flag State: Panama

Vessel Type: Container Ship
Gross Tonnage: 45,000 GT
Captain: John Anderson

Classification Society: Lloyd's Register

#### **INCIDENT DETAILS:**

At approximately 14:30 UTC on August 15, 2025, the MV Ocean Pioneer experienced a minor collision with a fishing vessel while entering Tokyo Bay. The incident occurred during foggy conditions with visibility reduced to less than 500 meters.

### **WEATHER CONDITIONS:**

Wind: Southwest 15 knotsSea State: 2-3 meters

Visibility: Less than 500m due to fog

• Temperature: 28°C

• Barometric Pressure: 1013.2 hPa

### **SEQUENCE OF EVENTS:**

- 13:45 UTC Vessel reduced speed to 8 knots due to fog
- 14:15 UTC Radar contact with multiple fishing vessels detected
- 14:25 UTC Sound signals initiated as per COLREGS
- 14:30 UTC Minor collision with fishing vessel 'Sakura Maru'
- 14:35 UTC Both vessels checked for damage
- 14:40 UTC Coast Guard notified via VHF Channel 16

### **DAMAGE ASSESSMENT:**

- MV Ocean Pioneer: Minor paint scrapes on starboard bow
- Sakura Maru: Damage to port gunwale and fishing nets

# **REGULATORY COMPLIANCE:**

- IMO STCW Convention requirements followed
- ISM Code procedures implemented
- MARPOL regulations observed
- · Local port authority regulations complied with

# **CONCLUSION:**

The incident was minor with no injuries reported. Both vessels were able to continue their operations after damage assessment. Weather conditions were the primary contributing factor.

Report Prepared By: Chief Officer Sarah Mitchell

Date: August 16, 2025

Port State Control Inspection scheduled for August 20, 2025

Insurance claim reference: INS-2025-08-001