

COMMISSION OF METRO RAILWAY SAFETY (CMRS) SOUTHERN CIRCLE, BANGALORE /
KOCHI SAFETY DIRECTIVE & TRACK INSPECTION NOTICE

Directive Ref No: CMRS/SC/KMRL/LINE1/2025/SAF-09 Date of Issue: 17th August 2026 Subject:
URGENT - Mandatory Track Geometry Compliance & Ultrasonic Flaw Detection (USFD) at
Vadakkekkotta Crossover

To: 1. The Managing Director, Kochi Metro Rail Limited (KMRL), JLN Stadium Metro Station, Kochi.
2. The Chief Safety Officer, KMRL Muttom Depot.

1. DIRECTIVE MANDATE: During the statutory inspection of Line 1 between Maharaja's College and Tripunithura Terminal, excessive dynamic track gauge widening (+4.2mm) was detected on Crossover Switch 12B at Pier 412 (Vadakkekkotta).
2. STATUTORY ACTIONS ORDERED:
 - Immediate imposition of Temporary Speed Restriction (TSR) of 20 km/h across Crossover 12B effective immediately.
 - Comprehensive Ultrasonic Flaw Detection (USFD) testing of all rail welds between Ch: 18+200 and Ch: 18+650.
 - Replacement of worn tongue rail and elastic rail clip fasteners before resumption of normal 60 km/h line speed.
 - Compliance report with non-destructive test certificates to be submitted within 48 hours.

Failure to comply with this safety directive will attract immediate suspension of commercial operations under Section 14 of the Metro Railways (Operation and Maintenance) Act, 2002.

By Order of Commissioner of Metro Railway Safety (CMRS) Southern Circle