

Maintenance Log: MLOG-006

Machine: Boiler B201

Date: 2026-06-03

Engineer: Karthik Raj

Issue: Conveyor jam

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 1 hours

Remarks: Resolved. References SOP-005 and Machine Manual.