

Maintenance Log: MLOG-009

Machine: Compressor CP01

Date: 2026-05-30

Engineer: Suresh Babu

Issue: Pump vibration

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 4 hours

Remarks: Resolved. References SOP-005 and Machine Manual.