

Maintenance Log: MLOG-011

Machine: Compressor CP01

Date: 2026-06-03

Engineer: Ravi Kumar

Issue: Generator shutdown

Symptoms: Operator reported abnormal behavior during shift.

Root Cause: Wear and tear on internal components.

Corrective Action: Replaced affected parts and recalibrated.

Downtime: 2 hours

Remarks: Resolved. References SOP-005 and Machine Manual.